Installing RealSense camera + Touchdesigner + NDI on Windows PC

Download Touchdesigner

On the windows computer download and install touchdesigner. Then open the Touchdesigner RealsensetoMax.1.toe patch.

Touchdesigner: https://derivative.ca/download

Download NDI Tools and SDK

Install NDI Tools and NDI SDK on Both the Windows and The MacOS computers. This is required on both computers in order for the objects to work properly.

NDI Tools: https://ndi.video/tools/
NDI SDK: https://ndi.video/for-developers/ndi-sdk/

Add Jit.NDI to Max Package folder

On the MacOS computer download the Jit.NDI external and place the unzipped folder in the Max Packages Folder (https://github.com/pixsper/jit.ndi/releases/tag/v0.3.1)

Touchdesigner Camera Setup

When in touchdesigner click an object and press p to open up it's properties window.

You can also click the small blue ball on the bottom right corner of an object to have it display as the background (this should already be enabled on the camera).

On the windows laptop In Touchdesigner check that patch is using the "real sense" Tops object. Check that this object's Model property is set to D455 and that image is set to IR. If working you should be able to see the Camera Feed in the object box window.

Check that the final object in the chain is the "NDI Out" Tops object. Make sure the source name is set in the object's properties, the default name should be touchdesigner. If working you should be able to see the Camera Feed in the object box window.

When the Camera is in the correct position you can press "1" on the keyboard to do the background subtraction.

If the Camera is not fully seeing the people in the environment you may need to adjust the levels, thresh, and/or blur properties. At home I was able to create a clear image by turning the gamma property in the levels object up to the maximum value.

Max Camera Setup

In Max open the patch and set the source in the umenu to match the source from touchdesigner. If you open touchdesigner first then Max it should automatically be populated and enabled, if you do not see it then click the getsource messages.

Enable the Render button, the camera feed should now be showing up in the jit.world window.