## • 06-FormProof.pdf

 Refined Dimensional Sketches - Using graph paper, create an accurately scaled drawing from multiple perspectives of your design

## None done.

- o Foam Model Created a model of your design using green foam
  - Model should be 1:1 scale
  - Surface should be sanded and sealed

## None done.

- o Virtual 3D Model Create a 3D model of your device in Fusion 360
  - Model should be to dimensions detailed in sketches and foam model (with reasonable deviations as necessary)

Renderings should include surface treatments and show device from the top, isometric, side, bottom, and exploded views.







