## 2.1.2 ADDRESS AND FUNCTION CHARACTERS (CONT'D)

Table 2.3 Function Characters

EIA Code	ISO Code	Meanings	Remarks
Blank	Nul	Error in significant data area in EIA Disregarded in ISO	
BS	BS	Disregarded	
Tab	нт	Disregarded	
CR	LF/NL	End of Block (EOB)	
	. CR	Disregarded	
SP	SP	Space	
ER	90	Rewind stop	
UC		Upper shift	
LC		Lower shift	
2-4-5 bits	(	Control out (Comment start)	EIA: Special code
2-4-7 bits	)	Control in (Comment end)	
+	+	Disregarded, User macro operator	
_	-	Minus sign, User macro operator	
0 to 9 ·	0 to 9	Numerals	
a to z	A to Z	Address characters, User macro operator	
1	1	Optional block skip	
Del	DEL	Disregarded (Including All Mark)	
		Decimal point	
Parameter setting	#	Sharp (Variable)	EIA: Special code
*	*	Astrisk (Multiplication operator)	
=	=	Equal mark	
[	[	Left bracket	
J	J	Right bracket	
:	:	User macro comment	
\$	\$.	User macro comment	
0	@	User macro comment	
?	?	User macro comment	

## Notes:

- 1. Characters other than the above cause error in significant data area.
- 2. Information between Control Out and Control In is ignored as insignificant data.
- 3. Tape code (EIA or ISO) can be switched by setting.