INDEX

	Subject	Chapter	Section Page
М	Multi-Active Registers $^{-}$		2.8.4 ···· 16
N	NC OPERATOR'S STATION WITH CRT CHARACTER DISPLAY NC TAPE	. 3	3. 4 ······ 113 3. 3. 3 ····· 113 3. 4. 2 ····· 113
	NC TAPE PUNCHING	. 3	3.3 ······ 113 4.1.6 ···· 116
o	On-Line Diagnostics	. 2	2.11.5 ···· 99 6.2 ···· 163
	Operation Time Display Optional Block Skip (/1-/9)† OPTIONAL BLOCK SKIP Switch OPTIONAL STOP Switch ORG (Origin) Key	. 6	2.2.3 ···· 6 6.1.19 ··· 159
	OTHERS	8	2. 9. 28 ···· 67 8. 4. 2 ···· 184 2. 11. 3 ···· 87
P	PAGE Keys Paper Tape Select PARAMETER NUMBERS, LIST OF Parameters, Displaying and Writing Part Program, Adding	PENDIX 2 · ·	3.3.1 113
	Part Program Block, Deleting Part Program Block, Modifying Part Program by MDI, Loading Part Program Display Part Program Form, General	· · 4 · · · · · · · · · · · · · · · · ·	4.6.3139
	PART PROGRAM TAPE CODING	· · 4 · · · · · · · · · · · · · · · · ·	· 4. 5. 1 ····· 135 · 4. 8. 3 ···· 145 · 4. 4. 5 ···· 133
	PART PROGRAMS INTO MEMORY, LOADING Plane Designation (G17, G18, G19) Playback Function Positioning (G00, G06) POWER CIRCUIT BREAKER AND FUSES	2	· 2. 9. 10 ···· 31 · 6. 2. 5 ···· 170 · 2. 9. 2 ···· 23
	POWER ON/OFF OPERATION Power On/Off Pushbuttons PREPARATION FOR TURNING OFF POWER PREPARATORY FUNCTION (G-FUNCTION) Process Sheet	4	· 4.1.1 ····· 115 · 7.10 ····· 176 · 2.9 ···· 21
	Program Interruption On/Off (M91/M90)†	2	· 2. 2. 1 · · · · · 6 · 3. 2 · · · · · · 110