Table 2.25 Canned Cycle (continued)

	With G99 (return to R)	With G98 (return to initial point)
G87	G87 X Y Z R Q L (X, Y) SPINDLE START R MANUAL RETRACTIO	SPINDLE START (X, Y) INITIAL POINT R MANUAL
G88	G88 X Y Z R P I	F; SPINDLE
Boring	SPINDLE START R MANUAL RETRACTIO Z SPINDLE STOP AFTER DWELL (P)	START INITIAL POINT R MANUAL RETRACTION Z SPINDLE STOP AFTER DWELL (P)
G89	G89 X Y Z R P 1	
Boring	DWELL (P)	DWELL (P)