6.2.5 PLAYBACK FUNCTION (CONT'D)

O0010N0000 PROG(PLAYBACK) O0010; G91 G28 X0 Y0 Z0; G92 X9 Y0 Z0; G90 G00 X0.4 Y0.2 Z0.3; N0001 G00 X0.700; N0002 G01 Z0.600 F20; N0003 G00 Y1.000; N0004 G01 X0.700 Y1.000 Z0.600 F100; .700 Y1.000 POS .600 (UNIV) RDY N0005 G01X0.5

Fig. 6.32



BY DEPRESSING WR KEY, POSITION X IS ADDED TO THE KEYED-IN VALUE.

PROG(PLAYBACK) O0010N0000 O0010; G91 G28 X0 Y0 Z0; G92 X0 Y0 Z0; G90 G00 X0.4 Y0.2 Z0.3; N0001 G00 X0.700; N0002 G01 Z0.600 F20; N0003 G00 Y1.000; N0004 G01 X0.700 Y1.000 Z0.600 F100; Х ,700 Y1.000 POS (UNIV) .600 N0005 G01 X1.200 RDY

Fig. 6.33

- (1) Key-in N, 0, 0, 0, 5.
- (2) Key-in G, 0, 1.
- (3) Depress the WR key after keying-in X0.5.
- (4) Depress the WR key after keying-in Y-0.2
- (5) Depress the WR key after keying-in Z.
- (6) Key-in F, 1, 0, 0.
- (7) Depress the EOB key.
- (8) Depress the INSRT key.

Then, block of N0005 G01 X1.200 Y0.800 Z0.600 F0.600 F100; will be stored in the part program.