Table 6.4 Tape Format

No.	Address		Metric output		Inch input		
			Metric input	<del></del>	Metric input		B: Basic O: Optional
1	Program No.		04		04		В
2	Sequence No.		N4		N4		В
3	G function		G3		G3		В
4	Cordinate Word	Linear axis	a + 43	a + 34	a + 53	a + 34	В
		Rotary axis	b + 43	b + 43	b + 43	b + 43	0
5	Feed/min		F40	F31	F50	F31	В
6	Feed/min 1/10		F41	F32	F51	F32	В
7	Feed/rev		F22	F13	F22	F13	0
8	Feed/rev 1/10		F23	F14	F23	F14	0
9	S-function		S2		S2		В
			S5		S5		0
10	T-function		Т2		T2		В
			Т4		Т4		0
11	M-function		М3		М3		В
12	Tool Offset No.		H2 or D2		H2 or D2		В
13	B-function		В3		В3		0
14	Dwell		P53		P53		В
15	Program No. designation		P1		P4		В
16	Sequence No. designation		P4		P4		В
17	No. of repititions		L8		L8		В