
2.9.23 TOOL POSITION OFFSET (G45 TO G48) (CONT'D)

EXAMPLE A



```
1)
     G91 G01 Z-2500 F150 ;
23456789
          G46 X4000 Y4000 D10 F300;
          G45 Y7000 ;
     G45 G02 X3000 Y3000 I3000 ;
     G45 G01 X3000;
               Y - 5000;
          G48 X5000 ;
               Y5000 ;
          G47 X7000 ;
<u>(10)</u>
          G47 Y-6000;
(i)
          G46 X0;
(12)
     G46 G03 X-4000 Y-4000 J-4000 ;
13
      G46 G01 Y0 ;
(i4)
          G47 X-14000 ;
(15)
          G46 X-4000 Y-4000 ;
(16)
               Z2500 ;
```

Fig. 2.68