In the above figure,

Compensation interval: 6000 pulses Absolute/incremental: Incremental Compensation multiplication: x 1

Compensation point on X axis: 100 points

Each parameter is set as follows:




Fig. 3.2