
2.8.5 MIRROR IMAGE.ON/OFF (M95, M94) (CONT'D)

EXAMPLE



```
N01 G92 X0 Y0;
N02
                            Mirror image on.
         M 95 ;
N03 G90 G01 X4000 Y4000 F300 ;
N04
         X12000 ;
         Y10000 ;
N05
N06
         X4000; .
N07
         Y4000 ;
                            If "M94;" is programmed here,
                             the tool moves on the dotted line.
N08
         X0 Y0 ;
N09
         M94;
                            Correct mirror image off.
         X2000 Y-4000;
N10
N11
         X6000;
```

Fig. 2.9