Location		Plug or slot	Arc seam or arc spot	Butt welds				
significance	e Fillet			Square	V	Bevel	U	J
Arrow Side	4	2	—				~	<u> </u>
Other Side	74				<i></i> ∠ <i>T</i>	Zĸ	~~	<u>ح</u> د
Both Sides	→	Not Used	Not Used	Z#_	₹	- ₹ <u>></u>	₩	- #
Supplementary symbols								
Weld a	II around	F	ield weld	d Contour				
					Flush		Conve	x
		_					\triangle	
Backing strip					Backing run			
<u> </u>					\			