## **Height & Width Roads Inspection Report**

Murray Valley Hwy Section 7 · Swan Hill



Road: Murray Valley Hwy Section 7

**Chainage:** KP 10.200 – 12.000 (1,800 m)

**Envelope Class:** Local/Other · **Required Height:** 5.0 m

**Inspection Date:** 13 Aug 2025 · **Inspector:** Greg Woodburn

Desktop example generated for scoping. Totals reflect forward and reverse drives; images are placeholders hosted on Vercel.

### **Key Findings & Treatment Summary**

- Canopy non-compliance observed in shaded gullies (approx. 220 m cumulative).
- Isolated low branches at driveways; recommend selective prune rather than full raise.
- Drainage vegetation encroachment near KP 11.400 affecting shoulder visibility.

Direction	Segment Count	Total Treatment (m)
Forward	2	800
Reverse	1	180
Combined	3	980

# Segments

#### FWD - KP 10.200



Before – View eastbound; low eucalypt limbs over lane at KP 10.550.

KP Start	KP End	Len (m)	GPS Start	GPS End
10.200	10.900	700	-35.1234, 143.5678	-35.1240, 143.5685

#### FWD - KP 11.420



Before – Dense canopy over crest; measured clear height ~4.6–4.8 m.

KP Start	KP End	Len (m)	GPS Start	GPS End
11.420	11.520	100	-35.1290, 143.5730	-35.1300, 143.5740

#### **REV - KP 11.600**



Before – Shoulders clear; intermittent saplings obstructing line of sight to Boort Rd intersection.

KP Start	KP End	Len (m)	GPS Start	GPS End
11.600	11.780	180	-35.1310, 143.5750	-35.1320, 143.5760

Generated by **Systems @ TMC enviro** · <u>www.tmcenviro.com.au</u> Email: <u>systems@tmcenviro.com.au</u> · Phone: <u>+61 458 922 033</u>