

ULINK2 User's Guide



Home P

Product

Download

Events

Support

Search Keil.com for:

Go

Technical Support

Overview

Search

Contact

Assistance Request

Feedback

On-Line Manuals

Product Manuals

Document Conventions

ULINK2 User's Guide

Introduction

Hardware Description

Setup ULINK2

Setup Flash Programming

Using ULINK2

Configure Cortex-M Devices for Tracing

μ Vision Windows

Real-Time Agent

Evaluation Boards

Analog Devices

Analog Devices ADuC702x

Analog Devices ADuC712x

Ashling

Ashling LPC2100

Atmel

Atmel EB40A

Freescale

Freescale MAC7100

Infineon

Infineon XC16x Starter Kits

Infineon Easy UTAH

Keil

Keil MCBXC167

Keil MCB2100

Keil MCB2103

Keil MCB2130 Keil MCB2140

Keil MCB2300

Keil MCBSTM32 Keil MCBSTR7

Keil MCBSTR730

Keil MCBSTR750

Keil MCBSTR9

Luminary

Luminary Stellaris Boards

Nohau

Nohau LPC3000

OKI

OKI ML674000

OKI ML67Q4003

OKI ML67Q4051 OKI ML67Q4061

OKI ML67Q5003

OKI ML69Q6203 Phytec

Phytec AT91M55800A

Phytec LPC229x

Phytec LPC3180

Phytec XC16x Boards

Revely

Revely RMS100

Samsung

Samsung S3C44001

Sharp

Sharp LH75401

STMicroelectronics

STMicroelectronics DK3300

ΤI

TI TMS470R1A256

TI TMS470R1B1M

TQ Systems

TQ Systems TQMX16xU

Appendix

Keil MCB2140

Home » Evaluation Boards » Keil » Keil MCB2140

The Keil MCB2140 Evaluation Board works with the ULINK2 USB - JTAG Adapter. The following instructions show you how to connect and run an example program on this board.



ULINK2 Adapter Connected to MCB2140

To download and run an example project using ULINK2 with the Keil MCB2140 Board:

- 1. Connect the 20 pin ribbon connector from the ULINK2 Adapter to the JTAG port of the MCB2140 evaluation board.
- 2. Make sure that Jumper **J9** JTAG is ON.
- 3. Connect power to the board using a standard USB cable. Connect the other end of the USB cable to an unused USB connector on your PC.
- 4. Start μ Vision.
- 5. Select the BLINKY.UV2 example project from C:\KEIL\ARM\BOARDS\KEIL\MCB2130\BLINKY\
- 6. Click the **Download** button to download the program to the target board.
- 7. Click the **Debug** button to start the debugger.
- 8. Click the Run button to start the program running on the target board.



