

Illustrations for TRENTOS Handbook

Page Content

- [Tasks](#)
- [Description](#)
- [Timeline/ Deadline:](#)
- [Used Data](#)
- [New Illustrations Overview](#)
- [Color Scheme](#)
- [Handbook Overview](#)

Requested by: [Julius Rüdiger](#) resulting from

- SEOS-2095 - Getting issue details...

STATUS
- SEOS-2121 - Getting issue details...

STATUS

Tasks

- ☒

create overview of all pictures with respective page number of the handbook
- ☒

clarify license conditions for fritzing we are allowed to publish the created images if we attribute to fritzing by saying "this image was created with Fritzing." see <https://fritzing.org/faq/>
- ☒

create illustrations with fritzing tool ongoing (only saber board is missing and will be done in CW21)
- ☒

provide png and raw fritzing files and save to wiki ongoing (only saber board is missing and will be done in CW21)
- ☒

check illustrations for technical correctness

SEOS-2867 - Getting issue details...STATUS
- ☒

check this wiki page for completeness and decide which illustrations should be added/ replaced [Unknown User \(thowit01\)](#)  done on 17 Jun 2021
- ☒

replace/ extend illustrations in handbook [Julius Rüdiger](#)
- ☒

update pin mapping in handbook documentation [Julius Rüdiger](#) with new color scheme as defined by [Axel Heider](#)
- ☐

give Fritzing credit in the handbook according to their license terms [Julius Rüdiger](#)


Description





In order to make the wiring and HW setup more feasible for our customers we require a few more illustrations.

Timeline/ Deadline:

The improved illustrations are required for the TRENTOS v1.3 release, which is currently scheduled for end of Q2 2021.








Used Data


	Cropped PNG	SVG (vector graphic)	Fritzing custom part
Nitrogen Board with JTAG			

Sabre Board with JTAG			
JTAG Adapter			
Windbond Flash			
SD Card Switcher			on demand
MiG-V			on demand

New Illustrations Overview

	Fritzing Raw File	PNG1	PNG2
--	-------------------	------	------



RasPi 3b+ Setup Option 1	 Raspi_Setup.fzz	 fritzing	
RasPi 3b+ Setup Option 2	 Raspi_Setup_Option2.fzz	 fritzing	
RasPi 3B+ JTAG	 Raspi_JTAG.fzz	 fritzing	
Nitrogen JTAG	 Nitrogen_w_JTAG.fzz	 fritzing	
Sabre	 Sabre_w_JTAG.fzz	 fritzing	




JTAG Adafruit			
------------------	---	--	--





Color Scheme





- for colors please adjust them to the following
 - black: ground
 - orange: +3V or +3.3V
 - red: +5V
 - yellow: +12V (not possible because of QSG that uses yellow cable color)
- I (Axel) recommend we always use these colors for JTAG
 - TDI: blue
 - TDO: green
 - TCK: brown
 - TMS: violet
 - TRST: white



Handbook Overview

#	Page	Current Graphic	Fritzing
1	53		


2	53		
3	64		
4	65		

5	65		
6	148		
7	148		

8	266		
9	269 RasPi JTAG		

10	272 SoloX		
11	273 SoloX		


12 283
JTAG
SoloX




Option 1





Option 2



13	284 Segger Toolcha in SoloX		
14	287 Sabre		


15


297
JTAG
Sabre



16

298
Segger
Sabre



17	336		
18	336		