L4 () - For a cyber-physical system, the software and hardware manifests (i.e., inventories) should be separated into an SBOM and a HBOM (Hardware Bill of Materials).

