Instructions	Opcode	Instructions	Opcode	
MOV reg, reg	1000101			
MOV reg, mem	100010dw oorrrmmm	RCL reg, 1	1101000w oo010mmm	
MOV mem, reg	disp	RCL mem,1	disp	
MOV reg, imm	1011wrrr data	RCR reg, 1	1101000w oo011mmm	
	Torrwitt data	RCR mem,1	disp	
MOV mem, imm	1100011w oo000mmm	ROL reg, 1	1101000w oo000mmm	
	disp data	ROL mem,1	disp	
MOVSX reg, reg	00001111 1011111w	ROR reg, 1	1101000w oo001mmm	
MOVSX reg, mem	oorrrmmm disp	ROR mem,1	disp	
MOVZX reg, reg	00001111 1011011w	RCL reg, CL	1101001w oo010mmm	
MOVZX reg, mem	oorrrmmm disp	RCL mem, CL	disp	
MUL reg	1111011w oo100mmm	RCR reg, CL	1101001w oo011mmm	
MUL mem	disp	RCR mem, CL	disp	
NEG reg	1111011w oo011mmm	ROL reg, CL	1101001w oo000mmm	
NEG mem	disp	ROL mem, CL	disp	
NOT reg	1111011w oo010mmm	ROR reg, CL	1101001w oo001mmm	
NOT mem	disp	ROR mem, CL	disp	
OR reg, reg	0000101	RCL reg, imm	1100000w oo010mmm	
OR reg, mem	000010dw oorrrmmm		disp data	
OR mem, reg	disp	RCL mem, imm	uisp uata	
OR reg, imm	1000000w oo001mmm	RCR reg, imm	1100000w oo011mmm	
OR mem, imm	disp	RCR mem, imm	disp data	
POP reg		ROL reg, imm	1100000w oo000mmm	
	01011rrr	ROL mem, imm	disp data	
POP mem	10001111 oo000mmm	ROR reg, imm	1100000w oo001mmm	
	disp	ROR mem, imm	disp data	
PUSH reg		ADD reg, reg	000000dw oorrrmmm	
	01010rrr	ADD reg, mem	disp	
		ADD mem, reg		
PUSH mem	11111111 oo110mmm	SUB reg, reg	001010dw oorrrmmm disp	
	disp	SUB reg, mem		
PUSH imm	01101000 data	SUB mem, reg		
	1111111w oo000mmm	DEC reg	1111111w oo001mmm	
INC reg	disp	DEC mem	disp	
INC mem	ctive Address			

MOD-11			Direct Effective Address				
MOD=11		W=1	R/M	MOD = 00	MOD = 01	MOD = 10	
R/M	W=0		000	[BX]+[SI]	[BX]+[SI]+D <sub>8</sub>	[BX]+[SI]+D <sub>16</sub>	
000	AL	AX	000	[BX]+[DI]	[BX]+[DI] +D <sub>8</sub>	[BX]+[DI] +D <sub>16</sub>	
001	CL	CX		[BP]+[SI]	[BP]+[SI] +D <sub>8</sub>	[BP]+[SI] +D <sub>16</sub>	
010	DL	DX	010	[BP]+[DI]	[BP]+[DI] +D <sub>8</sub>	[BP]+[DI] +D <sub>16</sub>	
011	BL	BX	011	[SI]	[SI] +D <sub>8</sub>	[SI] +D <sub>16</sub>	
100	AH	SP	100		[DI] +D <sub>8</sub>	[DI] +D <sub>16</sub>	
101	CH	BP	101	[DI]	[BP] +D <sub>8</sub>	[BP] +D <sub>16</sub>	
110	DH	SI	110	Direct Address			
111	ВН	DI	111	[BX]	[BX] +D <sub>8</sub>	[BX] +D <sub>16</sub>	