The gait engine alone does not walk: untrained networks and zero actions make no useful progress



Untrained networks: the standard 63→256→256→16 architecture with seeded random weights, real observations and the unchanged gait/IK/reset machinery. Uniform random: independent actions within the expert range. Low fall counts for the inactive controls reflect little movement, not stable walking.