```
% Taha Akhlaq MATLAB Assignment 6: Foray and Zee
clc; % clear command window
% 1: dB to magnitude conversion
dB to Amplitude = @(dB) 10^(dB/20);
% 2: signal generation and DFT plot
Fs = 44100; % sampling frequency in Hz
N = 88200; % total number of samples
timeVec = (0:N-1) / Fs; % time vector
% frequencies and dB levels
freqList = [14.96e3, 5.52e3, 3.15e3, -3.76e3, 11.01e3];
dBvals = [20, 19, 7, -7, -4];
% construct composite signal
compositeSig = zeros(1, N);
for n = 1:length(freqList)
    compositeSig = compositeSig + ...
        dB to Amplitude(dBvals(n)) * exp(1j*2*pi*freqList(n)*timeVec);
end
% white noise at -10 dB
compositeSig = compositeSig + dB to Amplitude(-10) * randn(1, N);
% plot the real part of the signal
figure(1);
subplot(2,1,1)
plot(timeVec, real(compositeSig), 'LineWidth', 1)
grid on
xlabel('Time [s]')
ylabel('Amplitude')
title('Real Part of Composite Signal')
% compute and shift FFT
signalFFT = fft(compositeSig);
signalFFTshifted = fftshift(signalFFT);
freqRange = linspace(-Fs/2, Fs/2, N);
subplot(2,1,2)
plot(freqRange, abs(signalFFTshifted), 'LineWidth', 1)
grid on
xlabel('Frequency [Hz]')
ylabel('Magnitude')
title('Magnitude of DFT [Shifted]')
% 3: pole-zero plot and frequency response
```

1


```
myZeros = [0.55+1i*0.08;
           0.55-1i*0.08;
           0.39+1i*0.96;
           0.39-1i*0.96;
           0.07+1i*0.68;
           0.07-1i*0.68;
           0.081;
myPoles = [-0.06+1i*0.83;
           -0.06-1i*0.83;
            0.30+1i*0.69;
            0.30-1i*0.69;
            0.77+1i*0.61;
            0.77-1i*0.61;
           -0.68;
           -0.341;
overallGain = -0.43;
numCoeffs = overallGain * poly(myZeros);
denCoeffs = poly(myPoles);
% pole-zero diagram
figure(2);
plot(real(myZeros), imag(myZeros), 'o', 'MarkerSize', 8, 'LineWidth', 1)
plot(real(myPoles), imag(myPoles), 'x', 'MarkerSize', 8, 'LineWidth', 1)
angleCircle = linspace(0, 2*pi, 800);
plot(cos(angleCircle), sin(angleCircle), '--', 'LineWidth', 1)
grid on
axis equal
xlabel('Real Axis')
ylabel('Imag Axis')
title('Pole-Zero Plot')
legend('Zeros','Poles','Unit Circle','Location','Best')
% frequency response calculation
fftSize = 1024;
omegaVec = linspace(0, 2*pi, fftSize);
        = zeros(1, fftSize);
for idx = 1:fftSize
        = exp(1j * omegaVec(idx));
    H(idx) = polyval(numCoeffs, z) / polyval(denCoeffs, z);
end
% convert frequencies to kHz
freqInHz = (omegaVec / (2*pi)) * Fs;
freqInkHz = freqInHz / 1000;
% plot magnitude and phase responses
figure(3);
subplot(2,1,1)
plot(freqInkHz, 20*log10(abs(H)), 'LineWidth', 1)
grid on
```


```
xlabel('Frequency [kHz]')
ylabel('Magnitude [dB]')
title('Magnitude Response')

phaseUW = unwrap(angle(H));
phaseDeg = phaseUW * (180/pi);

subplot(2,1,2)
plot(freqInkHz, phaseDeg, 'LineWidth', 1)
grid on
xlabel('Frequency [kHz]')
ylabel('Phase [degrees]')
title('Phase Response')
```

% Output:





Published with MATLAB® R2024b