




SD CARD




BATTERY VOLTAGE SENSE




BOARD FLASH AND DEBUGGER




POWER INPUT BATTERY



PASSIVE BUZZER




USB TYPE C




H1 MountingHole H2 MountingHole H3 MountingHole H4 MountingHole


IMU ICM-42688-P 6-AXIS



BMI 280




RECIVER




STM32


NRST The MCU must stay in reset briefly until the power supply is stable.




3.3V LDO + IMU FILTER



MOTOR DRIVE SETUP



5V BUCK CONVERTER



motor sheet



File: untitled.kicad_sch

OLLE


Sheet: /
File: OLLE.fpv_pcb.kicad_sch

Title: olle.fpv pcb


Size: A3
KiCad E.D.A. 9.0.8

Date: 5
Rev: 1/2


MOTOR 2



MOTOR 3



MOTOR 4



OLL.E

Sheet: /motor sheet/
File: untitled.kicad_sch

Title: motor sheet

Size: A4
KiCad E.D.A. 9.0.8

Date:

Rev:

Id: 2/2