Dept.: CSE (16" Batch, Section: A) CT-04 Total Marks: 15 Time: 20 minutes

a.Write down the necessity of parallel condition and its conditions.
b.Draw the circuit diagram of a 3 phase synchronous generator.
c.Determine the prime mover speed to generate 50Hz frequency in output when number of pole is 2