

1



S Finzel Mechanical
Clinton Township MI
License 7119809
586-366-4328

Furnace Inspection Record

Property Address: 37900 Mound Rd Sterling Heights MI 48312

Date work Performed: 9/8/2026

Model: YSC072E4EHA0000 Serial Number: 10401023L

All of the following have been inspected and tested to ensure safe operation of the gas and/or oil fired heating equipment at the above address.

1. Heat exchanger(s) were visually inspected (if applicable).

Result: PASS

2. Carbon monoxide tests were performed:

C/O Test Results: 0 Flue: 0 PPM Air Stream: 0 PPM

3. All system controls and safety devices were inspected for proper operation.

Result: PASS

4. 110v electrical system was inspected. On/off switch checked for proper operation.

Result: PASS

5. All filters were inspected

Result: GOOD

6. Existing chimney liner was inspected.

Result: NA

☒ No deficiencies were found. All tests and equipment were within normal operating limits and equipment is deemed safe for use.

☐ Deficiencies were found and proper actions need to be taken before equipment can be deemed safe for use.

Repairs to be completed:

Other notes or work performed:
BELT AX32, (4) 16X25X2 FILTERS

Technician: Nels Olsen



S Finzel Mechanical
Clinton Township MI
License 7119809

586-366-4328

Furnace Inspection Record

Property Address: 37900 Mound Rd Sterling Heights MI 48312

Date work Performed: 9/8/2026

Model: YSC060E4EHA0000

Serial Number: 106310123L

All of the following have been inspected and tested to ensure safe operation of the gas and/or oil fired heating equipment at the above address.

1. Heat exchanger(s) were visually inspected (if applicable).

Result: PASS

2. Carbon monoxide tests were performed:

C/O Test Results: 0 Flue: 0 PPM Air Stream: 0 PPM

3. All system controls and safety devices were inspected for proper operation.

Result: PASS

4. 110v electrical system was inspected. On/off switch checked for proper operation.

Result: PASS

5. All filters were inspected


Result: GOOD

6. Existing chimney liner was inspected.

Result: NA



No deficiencies were found. All tests and equipment were within normal operating limits and equipment is deemed safe for use.



Deficiencies were found and proper actions need to be taken before equipment can be deemed safe for use.

Repairs to be completed:

replace belt

Other notes or work performed:

BELT AX26, (2) 20X30X2 FILTERS

Technician:

Nels Olsen



S Finzel Mechanical
Clinton Township MI
License 7119809

586-366-4328

Furnace Inspection Record

Property Address: 37900 Mound Rd Sterling Heights MI 48312

Date work Performed: 9/8/2026

Model: YSC092E4EHA0000

Serial Number: 100711112L

All of the following have been inspected and tested to ensure safe operation of the gas and/or oil fired heating equipment at the above address.

1. Heat exchanger(s) were visually inspected (if applicable).

Result: PASS

2. Carbon monoxide tests were performed:

C/O Test Results: 0 Flue: 0 PPM Air Stream: 0 PPM

3. All system controls and safety devices were inspected for proper operation.

Result: PASS

4. 110v electrical system was inspected. On/off switch checked for proper operation.

Result: PASS

5. All filters were inspected

Result: GOOD

6. Existing chimney liner was inspected.

Result: NA

☒ No deficiencies were found. All tests and equipment were within normal operating limits and equipment is deemed safe for use.

☐ Deficiencies were found and proper actions need to be taken before equipment can be deemed safe for use.

Repairs to be completed:

replace belt

Other notes or work performed:

BELT AX35, (4) 20X25X2 FILTERS

Technician:

Nels Olsen



S Finzel Mechanical
Clinton Township MI
License 7119809
586-366-4328

Furnace Inspection Record

Property Address: 37900 Mound Rd Sterling Heights MI 48312

Date work Performed: 9/8/2026

Model: 48FCFA062A2A6A0A0A0

Serial Number: 3621C62041

All of the following have been inspected and tested to ensure safe operation of the gas and/or oil fired heating equipment at the above address.

1. Heat exchanger(s) were visually inspected (if applicable).

Result: PASS

2. Carbon monoxide tests were performed:

C/O Test Results: 0

Flue: 0 PPM

Air Stream: 0 PPM

3. All system controls and safety devices were inspected for proper operation.

Result: PASS

4. 110v electrical system was inspected. On/off switch checked for proper operation.

Result: PASS

5. All filters were inspected

Result: GOOD

6. Existing chimney liner was inspected.

Result: NA

☒ No deficiencies were found. All tests and equipment were within normal operating limits and equipment is deemed safe for use.

☐ Deficiencies were found and proper actions need to be taken before equipment can be deemed safe for use.

Repairs to be completed:

Other notes or work performed:

(2) 16X25X2 FILTERS

Technician:

Nels Olsen



S Finzel Mechanical
Clinton Township MI
License 7119809

586-366-4328

Furnace Inspection Record

Property Address: 37900 Mound Rd Sterling Heights MI 48312

Date work Performed: 9/8/2026

Model: YSC072E4EHA0000

Serial Number: 103811696L

All of the following have been inspected and tested to ensure safe operation of the gas and/or oil fired heating equipment at the above address.

1. Heat exchanger(s) were visually inspected (if applicable).

Result: PASS

2. Carbon monoxide tests were performed:

C/O Test Results: 0

Flue: 0 PPM

Air Stream: 0 PPM

3. All system controls and safety devices were inspected for proper operation.

Result: PASS

4. 110v electrical system was inspected. On/off switch checked for proper operation.

Result: PASS

5. All filters were inspected


Result: GOOD

6. Existing chimney liner was inspected.

Result: NA



No deficiencies were found. All tests and equipment were within normal operating limits and equipment is deemed safe for use.



Deficiencies were found and proper actions need to be taken before equipment can be deemed safe for use.

Repairs to be completed:

replace belt

Other notes or work performed:

BELT AX32, (4) 16X25X2 FILTERS

Technician:

Nels Olsen

67



S Finzel Mechanical
Clinton Township MI
License 7119809

586-366-4328

Furnace Inspection Record

Property Address: 37900 Mound Rd Sterling Heights MI 48312

Date work Performed: 9/8/2026

Model: YSC092E4EHA0000

Serial Number: 103911954L

All of the following have been inspected and tested to ensure safe operation of the gas and/or oil fired heating equipment at the above address.

1. Heat exchanger(s) were visually inspected (if applicable).

Result: PASS

2. Carbon monoxide tests were performed:

C/O Test Results: 0

Flue: 0 PPM

Air Stream: 0 PPM

3. All system controls and safety devices were inspected for proper operation.

Result: PASS

4. 110v electrical system was inspected. On/off switch checked for proper operation.

Result: PASS

5. All filters were inspected


Result: GOOD

6. Existing chimney liner was inspected.

Result: NA



No deficiencies were found. All tests and equipment were within normal operating limits and equipment is deemed safe for use.



Deficiencies were found and proper actions need to be taken before equipment can be deemed safe for use.

Repairs to be completed:

Other notes or work performed:

BELT AX32, (4) 20X25X2 FILTERS

Technician:

Nels Olsen



S Finzel Mechanical
Clinton Township MI
License 7119809
586-366-4328

Furnace Inspection Record

Property Address: 37900 Mound Rd Sterling Heights MI 48312

Date work Performed: 9/8/2026

Model: YSC060E4EHA000014

Serial Number: 103312173L

All of the following have been inspected and tested to ensure safe operation of the gas and/or oil fired heating equipment at the above address.

1. Heat exchanger(s) were visually inspected (if applicable).

Result: PASS

2. Carbon monoxide tests were performed:

C/O Test Results: 0

Flue: 0 PPM

Air Stream: 0 PPM

3. All system controls and safety devices were inspected for proper operation.

Result: PASS

4. 110v electrical system was inspected. On/off switch checked for proper operation.


Result: PASS

5. All filters were inspected


Result: GOOD

6. Existing chimney liner was inspected.

Result: NA



No deficiencies were found. All tests and equipment were within normal operating limits and equipment is deemed safe for use.



Deficiencies were found and proper actions need to be taken before equipment can be deemed safe for use.

Repairs to be completed:

replace belt

Other notes or work performed:

BELT AX26, (2) 20X30X2 FILTERS

Technician:

Nels Olsen