8 Features of Manufacturing Industries

8.3 – Characteristics, processes, application, advantages and disadvantages and the importance of considering accuracy of production and efficiency of modern manufacturing methods and systems when designing for manufacture for small, medium, and large-scale production:

Test Yourself:

1. *Name and briefly explain **four** key features of **a just-in-time (JIT)** manufacturing system and explain the key area for improvement that is targeted by a **'lean' manufacturing** approach to JIT.*

2. *Quality control* and *efficiency* are key issues in modern manufacturing. ***Value*** and ***value stream*** are the first ***two*** *stages* of ***lean manufacturing***. Explain the ***three*** further stages of ***lean manufacturing***.