Paper Id:

140323

Roll No:						

#### B TECH (SEM III) THEORY EXAMINATION 2019-20 MATERIALS ENGINEERING

Time: 3 Hours Total Marks: 100

Note: 1. Attempt all Sections. If require any missing data; then choose suitably.

#### **SECTION A**

#### 1. Attempt all questions in brief.

 $2 \times 10 = 20$ 

Sub Code: KME303

Q. No.	Questions	Marks	CO
a.	What is unit cell?	2	1
b.	Draw the planes for given miller indices (111) and (101)?	2	1
c.	What is the difference between Ductile and Brittle fractures?	2	2
d.	Differentiate between NDT and destructive testing.	2	2
e.	What is Gibb's phase rule?	2	3
f.	What is Invariant reaction? Write eutectic reaction.	2	3
g.	What is the difference between annealing and normalizing?	2	4
h.	Enlist the quenching medium in descending order of their cooling rate.	2	4
i.	What are the different constituents present in HSS and why?	2	5
j.	What are the uses of copper and aluminum? Enlist them.	2	5

#### SECTION B

#### 2. Attempt any three of the following:

 $3 \times 10 = 30$ 

Q. No.	Questions	Marks	CO
a.	What are the different types of imperfections present in the crystal?	10	1
	Explain them.		
b.	What is factor of safety and what is its importance? Also explain the	10	2
	Tresca and Von-mises failure theory.		
c.	What is solid solution? What is the difference between interstitial and	10	3
	substitutional solid solutions?		
d.	Why we prefer tempering after hardening? Explain in details.	10	4
e.	What is cast iron? What are the different types of cast iron? Explain	10	5
	them with proper applications.		

#### SECTION C

#### 3. Attempt any one part of the following:

 $1 \times 10 = 10$ 

Q. No.	Questions	Marks	CO
a.	Define Atomic packing factor and determine the Atomic packing	10	1
	factor for FCC and BCC.		
b.	What is hardness? Explain Brinell and Vickers hardness testing	10	1
	techniques.		

### 4. Attempt any *one* part of the following:

 $1 \times 10 = 10$ 

Q. No.	Questions	Marks	CO
a.	Explain the Griffith criteria of brittle fracture.	10	2
b.	What is Fatigue limit? Draw S-N curve and explain its importance.	10	2

Sub Code: KME303
Roll No:

Paper Id: 140323

5.	Attempt any one part	t of the following:
<b>.</b>	Attention and one bar	or the following.

1	X	10	=	10
---	---	----	---	----

Q. No.	Questions	Marks	CO
a.	Draw Fe-C equilibrium diagram? What are the different informations	10	3
	we get from this diagram? Explain.		
b.	What is the difference between Eutectic and Eutectoid phase	10	3
	diagrams? Explain with suitable example.		

# 6. Attempt any *one* part of the following:

#### $1 \times 10 = 10$

Q. No.	Questions	Marks	CO
a.	Draw TTT diagram? What are the applications of this diagram?	10	4
	Explain.		
b.	Write short note on: Austempering and Mertempering.		4

## 7. Attempt any one part of the following:

### $1 \times 10 = 10$

Q. No.	Questions	Marks	CO
a.	What is the purpose behind alloying the steels? What are the different	10	4
	types of steels are available and what are their applications? Explain.		100
b.	Write the composition and application of brass and bronze.	10	4
		- 5	1
		A STATE OF THE STA	
		A STATE OF THE STA	
		8	
	the second secon		
	· · · · · · · · · · · · · · · · · · ·		
	and the second s		
	Christian Contraction of the Con		
	$\sim$		