

SOP-04 Heat Exchanger Tube Plugging Criteria

1. Criteria

Tubes with eddy-current wall loss above 40% shall be plugged. Tubes with 20-40% wall loss are placed on monitor.

2. Limit

If more than 10% of tubes in a bundle require plugging, the bundle shall be retubed or replaced; raise a Management of Change request (SOP-05).

SYNTHETIC DEMO DOCUMENT - fictional company, invented data. Not for operational use.