

[Add sectional-view]

[Add detailed view]





[Dimensions of the holes are missing]



E(1:2)
(2x)

A(1:1)



NOTES:-
-ALL BURRS AND SHARP EDGES TO BE REMOVED.
-BENDING RADIUS; R = 4

[Add Name of the part]

[Add part-list]

[Add material]

[Add welding details]

[Add comment for modification]