




SPLICE PLATE DETAIL (/A-AP500PS0061) TYPE 1




SPLICE PLATE DETAIL (/A-AP500PS0061) TYPE 2

ANALYSIS RESULTS







	e pipe support men /A-AP500P50071	nbers (Common Su	pport)	Display from M	lin. U.C.	
meter 1 Parame	eter 2 Parameter 3	Warnings/Note			1	
Member	Property	Critical Cond.	U.C.	Des. Loading	Result	
8150	SHS200X08.0	EC-6.2.9.1	0.46	1103	PASS	
8149	SHS200X08.0	EC-6.2.5	0.46	1103	PASS	
8162	SHS200X08.0	EC-6.3.3-662	0.38	1104	PASS	
8153	SHS200X08.0	EC-6.3.3-662	0.33	1103	PASS	
8151	SHS200X08.0	EC-6.2.9.1	0.32	1108	PASS	
8152	SHS200X08.0	EC-6.2.9.1	0.32	1108	PASS	
8160	SHS200X08.0	EC-6.3.3-662	0.32	1101	PASS	
8154	SHS200X08.0	EC-6.2.5	0.28	1103	PASS	
8147	SHS150X06.0	EC-6.3.3-662	0.23	1104	PASS	
8163	SHS200X08.0	EC-6.2.6-(Z)	0.22	1104	PASS	
8156	SHS200X08.0	EC-6.3.3-662	0.22	1101	PASS	
8168	SHS150X06.0	EC-6.3.3-662	0.19	1104	PASS	
8157	SHS200X08.0	EC-6.2.5	0.19	1101	PASS	
8161	SHS200X08.0	EC-6.3.3-662	0.19	1101	PASS	
8164	SHS060X04.0	EC-6.3.3-662	0.18	1103	PASS	
8216	SHS150X06.0	EC-6.3.3-662	0.18	1104	PASS	
se Summary	U.C. results table	e for Parameter	1 (Ultim	ate Limit State)		

sign Results								
	1 /A-AP500P500	71		upport)	Display fro	m Min. U.	c. 0	_
Parameter 1 Para	,	er 3 Warnin Act. Def.			Des. Load	DFF	Result	
8155	Property SHS200X08.0	2.83	3	U.C. 0.94	2104	571	PASS	- 1
8217	SHS200X08.0	2.83	3	0.94	2104	571	PASS	
8158	SHS200X08.0	2.74	3	0.91	2102	571	PASS	
8159	SHS200X08.0	2.74	3	0.91	2102	571	PASS	-
8149	SHS200X08.0	1	3	0.33	2101	367	PASS	-
8150	SHS200X08.0	1	3	0.33	2101	367	PASS	
8151	SHS200X08.0	0.7	3	0.23	2106	367	PASS	
8152	SHS200X08.0	0.7	3	0.23	2106	367	PASS	
8153	SHS200X08.0	0.66	3	0.22	2103	410	PASS	
8154	SHS200X08.0	0.66	3	0.22	2103	410	PASS	
8218	SHS150X06.0	0.53	3	0.18	2106	575	PASS	
8216	SHS150X06.0	0.52	3	0.17	2106	575	PASS	
8157	SHS200X08.0	0.45	3	0.15	2101	410	PASS	
8156	SHS200X08.0	0.45	3	0.15	2101	410	PASS	-
8164	SHS060X04.0	0.44	3	0.15	2101	367	PASS	
8165	SHS060X04.0	0.44	3	0.15	2101	367	PASS	
Close Summary	U.C. results t	table for P	aramete	r 2 (Sen	viceability Lim	it State)		
	i	•	•	-	meter: 2 Critic meter: 2 Critic			

AP500PS0061 /	e pipe support men 'A-AP500P50071 ter 2 Parameter 3	nbers (Common Su Warnings/Note)	oport)	Display from N	lin. U.C.
Member	Property	Critical Cond.	U.C.	Des. Loading	Result
8162	SHS200X08.0	EC-6.3.3-662	0.47	3023	PASS
8150	SHS200X08.0	EC-6.2.9.1	0.45	3013	PASS
8149	SHS200X08.0	EC-6.2.5	0.45	3013	PASS
8160	SHS200X08.0	EC-6.3.3-662	0.42	3021	PASS
8153	SHS200X08.0	EC-6.3.3-662	0.38	3023	PASS
8156	SHS200X08.0	EC-6.3.3-662	0.3	3021	PASS
8163	SHS200X08.0	EC-6.3.3-662	0.28	3023	PASS
8161	SHS200X08.0	EC-6.3.3-662	0.26	3021	PASS
8154	SHS200X08.0	EC-6.2.5	0.24	3013	PASS
8151	SHS200X08.0	EC-6.2.9.1	0.22	3208	PASS
8152	SHS200X08.0	EC-6.2.9.1	0.22	3208	PASS
8164	SHS060X04.0	EC-6.3.3-662	0.18	3003	PASS
8218	SHS150X06.0	EC-6.3.3-662	0.18	3018	PASS
8157	SHS200X08.0	EC-6.2.5	0.17	3011	PASS
8168	SHS150X06.0	EC-6.3.3-662	0.17	3012	PASS
8147	SHS150X06.0	EC-6.3.3-662	0.17	3012	PASS