

NOTES

- FOR GENERAL NOTES AND SYMBOLS SEE DRAWING 4A, 4B.
- LOW PRESSURE STEAM CONDENSATE CONNECTION FOR CLEAN OUT.

