

Technical Datasheet

ZIEGLER TW SERIES

CURRENT TRANSFORMER

CURRENT TRANSFORMER

ZIEGLER ZIR Series

Round type CTs come with two types ZIR & ZIR-E, Clamp Screw Termination and extended wires type. These are designed to measure currents from 50A to 3200A (ZIR Series) to 5000A (ZIR-E Series). Ziegler Round CTs come with bus bar mounting kit and wall mounting frame is an optional accessory.

Product Features

- Wide range of system current ratings
- Primary Current ratings 50A to 3200A
- VA ratings available from 1VA to 45VA
- Mounting options : Wall mounting (option), Bus bar mounting .
- Available in 12 different sizes: Class 0.2, 0.5s, 0.5, 1
- Secondary Current ratings 5A & 1A
- ISF value : 5, 10.
- Transparent terminal cover for ZIR Series provides IP 20 Protection to
- terminals.


General Specification

Applicable standard :-	IEC 61869-1 & 2
Case :-	10% Glass Field polycarbonate, flame retardant grades classified UL 94V-0
Insulation class :-	E (120°C max)
Test voltage :-	For Ring (Window) type CT : 4KV 50 Hz for 1 min
Operating frequency :-	50Hz/60Hz
Rated Primary current :-	50A to 3200A
Rated secondary current :-	5A,1A
Burden :-	1VA to 45VA
Continuous current :-	1.2X Rated current
Rated system voltage :-	0.72/3KV
Operating temperature range:-	-20 to +45°C
Storage temperature range:-	-50 to +80°C
Accuracy Class	0.2,0.5s,0.5,1
Thermal short circuit current (Ith):-	60xI _n for Wound type CT and 60xI _n for Bus Bar type CT
Dynamic short circuit current (I _{dyn}):-	2.5xI _{th}
Instrument security factor (FS): -	2.5, 5, 10




CURRENT TRANSFORMER

ZIR 7.30B




	ZIR 7.30B (73/30(40)					
Primary Current	Accuracy					
	0.5	1.0				
50A	-	1.5VA				
60A	-	1.5VA				
75A	-	1.5VA				
100A	1.5VA	2.5VA				
120A	1.5VA	2.5VA				
125A	2.5VA	3.75VA				
150A	2.5VA	5VA				
200A	5VA	10VA				

ZIR 7.30D



	ZIR 7.30 (73/30(50))							
Primary Current	Accuracy							
, , , , , , , , , , , , , , , , , , , ,	0.2	0.5S	0.5	1.0				
50A	-	-	-	1.5VA				
60A	-	-	-	1.5VA				
75A	-	-	1.5VA	2.5VA				
100A	-	-	2.5VA	5VA				
120A	-	-	2.5VA	5VA				
125A	-	-	2.5VA	5VA				
150A	-	2.5VA	5VA	10VA				
200A	2.5VA	5VA	10VA	15VA				


ZIR 9.43B



	ZIR 9.43B (92/43(41))							
Primary Current	Accuracy							
	0.2	0.58	0.5	1.0				
75A	-	-	-	1VA				
80A	-	-	-	1.5VA				
100A	-	-	1VA	2.5VA				
120A	-	-	1VA	2.5VA				
125A	-	-	1VA	2.5VA				
150A	-	-	1.5VA	3.75VA				
200A	1.5VA	5VA	5VA	10VA				
250A	50A 2.5VA		7.5VA	15VA				
300A	3.75VA	10VA	10VA	20VA				


CURRENT TRANSFORMER

ZIR 10.58B




	ZIR 10.58B (100/58(41)							
Primary Current	Accuracy							
Trimury current	0.2	0.58	0.5	1.0				
120A	-	-	-	1VA				
125A	-			1.5VA				
150A	-	-	1VA	2.5VA				
200A	-	1.5VA	2.5VA	5VA				
250A	-	- 2.5VA		7.5VA				
300A	-	3.75VA	5VA	10VA				
400A	5VA	7.5VA	10VA	20VA				
500A	7.5VA	10VA	15VA	25VA				
600A	10VA	15VA	15VA	25VA				

ZIR 11.72B




	ZIR 11.72B (110/73(41)							
Primary Current								
	0.2	0.58	0.5	1.0				
200A	-	-	-	1.5VA				
250A	-	-	1.5VA	2.5VA				
300A	-	-	2.5VA	5VA				
400A	2.5VA	5VA	7.5VA	12.5VA				
500A	3.75VA	7.5VA	10VA	15VA				
600A	5VA	7.5VA	10VA	15VA				
800A	10VA	15VA	15VA	30VA				
1000A	10VA	15VA	15VA	30VA				

ZIR 15.11B



	ZIR 15.11B(159/113(40)							
Primary Curren	Accuracy							
Timuly current	0.2	0.58	0.5	1.0				
600A	1.5VA	3.75VA	5VA	10VA				
800A	2.5VA	7.5VA	10VA	15VA				
1000A	3.75VA	7.5VA	10VA	15VA				
1200A	15VA	15VA	20VA	30VA				
1250A	15VA	15VA	20VA	30VA				
1500A	15VA	15VA	20VA	30VA				
1600A	15VA	15VA	20VA	30VA				
2000A	15VA	20VA	25VA	45VA				
2500A	15VA	20VA	25VA	45VA				
3000A	15VA	25VA	30VA	45VA				
3200A	15VA	25VA	30VA	45VA				

CURRENT TRANSFORMER



Primary Current	ZIEGLER C	T TW-1	ZI	EGLER CT TV	V-2		ZIEGLER CT TW-3				
	Accuracy		Accuracy					Accu	racy		
	0.5 1.0		0.2 0.55 0.5			1.0	0.2	0.2 0.5S		1.0	
50A	-	1·5VA	-	-	-	1·5VA	-	-	-	-	
60A	-	1.5VA	-	-	-	1.5VA	-	-	-	-	
75A	-	1.5VA	-	-	1.5VA	2.5VA	-	-	-	1VA	
80A	-	-	-	-	-	-	-	-	-	1.5VA	
100A	1.5VA	2.5VA	-	-	2.5VA	5VA	-	-	1VA	2.5VA	
120A	1.5VA	2.5VA	-	-	2.5VA	5VA	-	-	1VA	2.5VA	
125A	2.5VA	3.75VA	-	-	2.5VA	5VA	-	-	1VA	2.5VA	
150A	2.5VA	5VA	-	2.5VA	5VA	10VA	-	-	1.5VA	3.75VA	
200A	5VA	10VA	2.5VA	5VA	10VA	15VA	1.5VA	5VA	5VA	10VA	
250A	-	-	-	-	-	-	2.5VA	7.5VA	7.5VA	15VA	
300A	-	-	-	-	-	-	3.75VA	10VA	10VA	20VA	

CURRENT TRANSFORMER

		ZIEGLER	CT TW-4			ZIEGLER	CT TW-5			ZIEGLE	R CT TW-6		
Primary Current		Accur	асу			Accuracy				Accuracy			
Current	0.2	0.58	0.5	1.0	0.2	0.58	0.5	1.0	0.2	0.58	0.5	1.0	
100A	-	-	-	-	-	-	-	-	-	1	1	-	
120A	-	-	-	1VA	-	-	-	-	-	1	1	-	
125A	1	-	-	1.5VA	-	1	-	-	1	1	1	1	
150A	-	-	1VA	2.5VA	-	-	-	-	-	-	1	-	
200A	-	1.5VA	2.5VA	5VA	-	-	-	1.5VA	-	-	-	-	
250A	-	2.5VA	3.75VA	7.5VA	-	-	1.5VA	2.5VA	-	-	-	-	
300A	-	3.75VA	5VA	10VA	-	-	2.5VA	5VA	-	-	-	-	
400A	5VA	7.5VA	10VA	20VA	2.5VA	5VA	7.5VA	12.5VA	-	-	-	-	
500A	7.5VA	10VA	15VA	25VA	3.75VA	7.5VA	10VA	15VA	-	-	-	-	
600A	10VA	15VA	15VA	25VA	5VA	7.5VA	10VA	15VA	1.5VA	3.75VA	5VA	10VA	
800A	-	-	-	-	10VA	15VA	15VA	30VA	2.5VA	7.5VA	10VA	15VA	
1000A	-	-	-	-	10VA	15VA	15VA	30VA	3.75VA	7.5VA	10VA	15VA	
1200A	-	-	-	-	-	-	-	-	15VA	15VA	20VA	30VA	
1250A	-	-	-	-	-	-	-	-	15VA	15VA	20VA	30VA	
1500A	-	-	-	-	-	-	-	-	15VA	15VA	20VA	30VA	
1600A	-	-	-	-	-	-	-	-	15VA	15VA	20VA	30VA	
2000A	-	-	-	-	-	-	-	-	15VA	20VA	25VA	45VA	
2500A	-	-	-	-	-	-	-	-	15VA	20VA	25VA	45VA	
3000A	-	-	-	-	-	-	-	-	15VA	25VA	30VA	45VA	
3200A	-	-	-	-	-	-	-	-	15VA	25VA	30VA	45VA	

Mounting Types







Ziegler Instrumentation UK Ltd.