

AC/DC Clamp Meter







3800 CL

3801 CL

3810 CL TRUE RMS

FEATURES

- \bullet Full auto range for V.A and Ω functions.
- Data hold function freezes the reading in dimly lit or hard to reach places.
- Low battery indication.
- Built-in buzzer for continuity test.

- Safety design throughout with no exposed metal parts. Shielded banana plugs and recessed input terminals.
- Ohm function ideal for checking continuity of relays transformers and motor coils.

SPECIFICATIONS	3800 CL	3801 CL	3810 CL
AC A	400A / 1000A ±(1.5%rdg+3dgt) : 40-500Hz	400A / 1000A ±(1.5%rdg+3dgt) : 40-500Hz	400A / 1000A ±(1.5%rdg+3dgt) : 40-500Hz
AC V	400V / 600V	400V / 600V	400V / 600V ±(1.0%rdg+3dgt) : 40-500Hz
DC A	400A / 1000A ±(1.5%rdg+3dgt)	400A / 1000A ±(1.5%rdg+3dgt)	400A / 1000A ±(1.5%rdg+3dgt)
DC V	400V / 600V ±(0.75%rdg+3dgt)	400V / 600V ±(0.75%rdg+3dgt)	400V / 600V ±(0.75%rdg+3dgt)
Ω	400Ω / 2000Ω ±(1.0%rdg+3dgt)	$400\Omega / 2000\Omega$ ±(1.0%rdg+3dgt)	400Ω / 2000Ω ±(1.0%rdg+3dgt)
Flashlight		, J	
LCD backlight display		\checkmark	
Buzzer sounds	< 38Ω	< 38Ω	< 38Ω
Conductor size	40mm Max.	40mm Max.	40mm Max.
Low battery Indication	-+	-+	-+
Dimensions	255(L) × 80(W) × 35(D)mm	255(L) × 80(W) × 35(D)mm	255(L) × 80(W) × 35(D)mm
Weight (battery included)	Approx. 420g	Approx. 430g	Approx. 420g
Power source	9V(6F22) × 1	9V(6F22) × 1	9V(6F22) × 1
Safety standard	EN 61010-1 CAT III 600V EN 61010-2-32 EN 61010-2-33	EN 61010-1 CAT III 600V EN 61010-2-32 EN 61010-2-33	EN 61010-1 CAT III 600V EN 61010-2-32 EN 61010-2-33
Accessories	Instruction manual Test leads Soft pouch Battery	Instruction manual Test leads Soft pouch Battery	Instruction manual Test leads Soft pouch Battery