## ♣ AC / DC Digital Clamp Meters

Versatile Clamp Meter, Compactly Designed





SK-7718 MERMS / SK-7719

## FEATURES

- AC / DC 1000A Measurements
- "Power-On Initialize" (auto zero adjustment) for DCA.
- MAX / MIN, Difference, Peak Hold (SK-7718), and Range Hold (SK-7719)
- Dust-proof case is used to protect the tester from dust damage.

## **SPECIFICATIONS**

Display : 4000 count LCD, Maximum reading 9999

Weight : 300g

Accessories : 100-57 Test Leads (x 1 set)

1012 Carrying Case (x 1) 9V 6F22 Battery (x 1)

## **OPTIONAL ACCESSORIES**

880 Line Separator 940 Alligator Clips 100-41 Test Lead Kit 948 Alligator Clips 100-62 Test Lead Set 793 Coil-Type Contact Pin

∼ / <del>=</del> A / A Hz	AC Current	400A	±1.5%rdg±5dgt	
		1000A	400 to 600A ± 1.5%rdg ± 5dgt	
			601 to 1000A ±3.0%rdg±5dgt	
	DC Current	400A	±1.5%rdg±3dgt	
		1000A	400 to 600A ± 1.5%rdg ± 3dgt	
			601 to 1000A ±3.0%rdg±3dgt	
	Frequency	1Hz to 1kHz	±0.2%rdg±2dgt	
γ⁄\ <del>\</del> Hz∙%	AC Voltage	4V	±1.0%rdg±5dgt (40Hz to 400Hz)	
		40V		
		400V		
		600V		
	DC Voltage	400mV	±1.0%rdg±3dgt	
		4V		
		40V		
		400V		
		600V		
	Frequency	1Hz to	±0.2%rdg±2dgt	
	, ,	49.99kHz	±0.2761ug±2ugt	
	Duty Cycle	10% to 90%	±2.0%rdg±2dgt	
Resistance		400Ω	±1.5%rdg±5dgt	
		4kΩ	±1.0%rdg±3dgt	
		40kΩ		
		400kΩ		
		4MΩ	±4.0%rdg±5dgt	
		40ΜΩ	±6.0%rdg±5dgt	
Other Measurements		Continuity Test, Diode Test, Capacitance		
Functions		Peak Hold (SK-7718), MAX / MIN, Difference, Power-on Initialize (for DC Current measurement), Range Hold (SK-7719), Display Hold, Auto Power OFF		

Range Accuracy

