ADR	CODE	Label	Instruc	tion	C	Comment	Page(1)
00 00 00 00				ブモードのテスト ジスタの値を確認	忍す	· る)	
00	10 OD		LD	G0,AA	;	G0[AA]	
02	17 01		LD	G1,#1	;	G1[01]	
04	1B 02		LD	G2,#2	;	G2[02]	
06	1C 0E		LD	SP,GG	;	SP[55]	
80	31 OF		ADD	G0, ARRAY, G1	;	G0[BB]	
0A	16 OF		LD	G1,ARRAY,G2	;	G1[CC]	
0C	FF		HALT				
0D							
0D	AA	AA	DC	0AAH			
ΟE	55	GG	DC	055H			
OF	FF	ARRAY	DC	OFFH			
10	11		DC	011H			
11	CC		DC	0CCH			