NFPA Rating Health 2 Flamr	mability 3 Reacti	vity 0	HMIS Rating	Health 2 Flami	nability 3 Reactivit	ıy u	
SECTION I			507	101			
Material Safety Data		DOT Hazard Classification *					
OSHA's Hazard Comm. Standard 29 C	HA Form 174						
Distributed By:		Identity (Tra					
Hillyard Indu		stries, Inc.	#1046 Spring Breeze Air Freshener				
Address:			MSDS Num	ıber *			
	P.O. Box 909		1046-99-1				
			Date Prepai	red:			
	St. Joseph, MO 64502		J		January 1, 19	January 1, 1999	
Telephone (Information)	(816) 233-1321 (Ext.2303)		Prepared By:		•	Regulatory Dept.	
	http://www.hillyard.com				Regulatory D		
Telephone (Emergency)	CHEMTREC		NOTE: Blank spaces are not permitted. If any item is not applicable or no information is available, the space must be marked to indicate that.		not applicable or no		
Total (Emergency)))	indicate triat.					
SECTION II - Hazardous Ing	redients/Identity	/ Information					
Hazardous Components (Specific					Other Limits		
Chemical Identity, Commor			OSHA PEL	ACGIH-TLV	Recommended	%(Opt.)	
Isobutane			800 ppm	800 ppm			
Propane			1000 ppm	Asphyxiant			
Acetone		67-64-1	1000 ppm	750 ppm	STEL 1000 ppm		
Perfume		Mixture	None	None			
Section 313.							
Section 313. Any substance listed as hazard Texas is described above if kn	dous by the State	s of California, Flori gulated concentrati	da, Illinois, Mid			ania or	
Section 313. Any substance listed as hazard Texas is described above if kn	dous by the State	s of California, Flori gulated concentrati	da, Illinois, Micons.	chigan, New Jers		ania or	
Section 313. Any substance listed as hazard Texas is described above if kn SECTION III Physical/Chen Boiling Point	dous by the State	s of California, Flori gulated concentrati	da, Illinois, Micons.				
Section 313. Any substance listed as hazard Texas is described above if kn	dous by the State	s of California, Flori gulated concentrati	da, Illinois, Micons.	chigan, New Jers		ania or 0.794	
Section 313. Any substance listed as hazard Texas is described above if kn SECTION III Physical/Chen Boiling Point Concentrate - Initial	dous by the State	s of California, Flori gulated concentrati tics	da, Illinois, Micons. Specific Gi Concentrate	chigan, New Jers ravity (H ₂ O = 1) e @70° F			
Section 313. Any substance listed as hazard Texas is described above if kn SECTION III Physical/Chen Boiling Point Concentrate - Initial	dous by the State	s of California, Flori gulated concentrati tics	da, Illinois, Micons.	chigan, New Jers ravity (H ₂ O = 1) e @70° F			
Section 313. Any substance listed as hazard Texas is described above if kn SECTION III Physical/Chen Boiling Point Concentrate - Initial Pressure (psig. @ 70° F)	dous by the State	s of California, Flori gulated concentrati tics 133° F 40 ± 5	da, Illinois, Micons. Specific Gi Concentrate Melting Po	chigan, New Jers ravity (H ₂ O = 1) e @70° F int	sey, Ohio, Pennsylva	0.794	
Section 313. Any substance listed as hazard Texas is described above if kn SECTION III Physical/Chen Boiling Point Concentrate - Initial Pressure (psig. @ 70° F)	dous by the State	s of California, Flori gulated concentrati tics 133° F 40 ± 5 Greater than	da, Illinois, Micons. Specific Gi Concentrate Melting Po	chigan, New Jers ravity (H ₂ O = 1) e @70° F	sey, Ohio, Pennsylva	0.794 No Data	
Section 313. Any substance listed as hazard Texas is described above if kn SECTION III Physical/Chen Boiling Point Concentrate - Initial Pressure (psig. @ 70° F) Vapor Density (AIR = 1)	dous by the State	s of California, Flori gulated concentrati tics 133° F 40 ± 5	da, Illinois, Micons. Specific Gi Concentrate Melting Po Evaporatio	chigan, New Jers ravity (H ₂ O = 1) e @70° F int	sey, Ohio, Pennsylva	0.794 No Data	
Section 313. Any substance listed as hazard Texas is described above if kn SECTION III Physical/Chen Boiling Point Concentrate - Initial Pressure (psig. @ 70° F) Vapor Density (AIR = 1)	dous by the State	s of California, Flori gulated concentrati tics 133° F 40 ± 5 Greater than one (1)	da, Illinois, Micons. Specific Gi Concentrate Melting Po	chigan, New Jers ravity (H ₂ O = 1) e @70° F int	sey, Ohio, Pennsylva	0.794 No Data No Data Not	
Section 313. Any substance listed as hazard Texas is described above if kn SECTION III Physical/Chen Boiling Point Concentrate - Initial Pressure (psig. @ 70° F) Vapor Density (AIR = 1) Solubility in Water	dous by the State own present in re nical Characteris	s of California, Flori gulated concentrati tics 133° F 40 ± 5 Greater than one (1) Soluble	da, Illinois, Micons. Specific Gi Concentrate Melting Po Evaporatio	chigan, New Jers ravity (H ₂ O = 1) e @70° F int on Rate (Butyl Ac	sey, Ohio, Pennsylva	0.794 No Data No Data Not	
Section 313. Any substance listed as hazard Texas is described above if kn SECTION III Physical/Chen Boiling Point Concentrate - Initial Pressure (psig. @ 70° F) Vapor Density (AIR = 1) Solubility in Water Appearance and Odor - Clea	dous by the State own present in re nical Characteris	s of California, Florigulated concentratistics 133° F 40 ± 5 Greater than one (1) Soluble with a fresh scent in	da, Illinois, Micons. Specific Gi Concentrate Melting Po Evaporatio	chigan, New Jers ravity (H ₂ O = 1) e @70° F int on Rate (Butyl Ac	sey, Ohio, Pennsylva	0.794 No Data	
Section 313. Any substance listed as hazard Texas is described above if kn SECTION III Physical/Chem Boiling Point Concentrate - Initial Pressure (psig. @ 70° F) Vapor Density (AIR = 1) Solubility in Water Appearance and Odor - Cleat SECTION IV - Fire and Expl	dous by the State own present in re nical Characteris	s of California, Florigulated concentratictics 133° F 40 ± 5 Greater than one (1) Soluble with a fresh scent in tata	da, Illinois, Micons. Specific Grant Concentrate Melting Po Evaporatio pH an aerosol ca	chigan, New Jers ravity (H ₂ O = 1) e @70° F int on Rate (Butyl Ac	sey, Ohio, Pennsylva	0.794 No Data No Data Not applicable	
Any substance listed as hazard Texas is described above if kn SECTION III Physical/Chem Boiling Point Concentrate - Initial Pressure (psig. @ 70° F) Vapor Density (AIR = 1) Solubility in Water Appearance and Odor - Clean SECTION IV - Fire and Expl USA Flame Projection Test (AIR = 1)	dous by the State own present in re nical Characteris r colorless liquid volosion Hazard Data ASTM D-3065)	s of California, Florigulated concentratistics 133° F 40 ± 5 Greater than one (1) Soluble with a fresh scent in	da, Illinois, Micons. Specific Gi Concentrate Melting Po Evaporatio pH an aerosol ca	chigan, New Jers ravity (H ₂ O = 1) e @70° F int on Rate (Butyl Ac	cetate = 1)	0.794 No Data No Data Not applicable	
Any substance listed as hazard Texas is described above if kn SECTION III Physical/Chem Boiling Point Concentrate - Initial Pressure (psig. @ 70° F) Vapor Density (AIR = 1) Solubility in Water Appearance and Odor - Clean SECTION IV - Fire and Expl USA Flame Projection Test (10", no flashback, not flammal	dous by the State own present in re nical Characteris r colorless liquid volosion Hazard Data ASTM D-3065) ble	s of California, Florigulated concentrations: 133° F 40 ± 5 Greater than one (1) Soluble with a fresh scent in tata Flammable Lie	da, Illinois, Micons. Specific Gramma Concentrate Melting Po Evaporatio pH an aerosol ca mits No Data	chigan, New Jers ravity (H ₂ O = 1) e @70° F int on Rate (Butyl Ad	cetate = 1) LEL No Data	0.794 No Data No Data Not applicable UEL No Dat	
Any substance listed as hazard Texas is described above if kn SECTION III Physical/Chen Boiling Point Concentrate - Initial Pressure (psig. @ 70° F) Vapor Density (AIR = 1) Solubility in Water Appearance and Odor - Clean SECTION IV - Fire and Expl USA Flame Projection Test (10", no flashback, not flamma Extinguishing Media - Water	dous by the State own present in renical Characteristrical Charact	s of California, Florigulated concentrations: 133° F 40 ± 5 Greater than one (1) Soluble with a fresh scent in tata Flammable Lieue. Use carbon diox	da, Illinois, Micons. Specific Gramma Concentrate Melting Po Evaporatio pH an aerosol ca mits No Data	chigan, New Jers ravity (H ₂ O = 1) e @70° F int on Rate (Butyl Ad	cetate = 1) LEL No Data	0.794 No Data No Data Not applicable UEL No Dat	
Any substance listed as hazard Texas is described above if kn SECTION III Physical/Chen Boiling Point Concentrate - Initial Pressure (psig. @ 70° F) Vapor Density (AIR = 1) Solubility in Water Appearance and Odor - Clean SECTION IV - Fire and Expl USA Flame Projection Test (10", no flashback, not flammal Extinguishing Media - Water flammable. Vapors may travel	dous by the State own present in renical Characteristrical Charact	s of California, Florigulated concentrations: 133° F 40 ± 5 Greater than one (1) Soluble with a fresh scent in ta Flammable Lieue. Use carbon diox gnition sources.	da, Illinois, Micons. Specific Gi Concentrate Melting Po Evaporatio pH an aerosol ca mits No Data ide, dry chemi	chigan, New Jers ravity (H ₂ O = 1) e @70° F int on Rate (Butyl Additional)	cetate = 1) LEL No Data Concentrate is high	0.794 No Data No Data Not applicable UEL No Data	
SECTION III Physical/Chen Boiling Point Concentrate - Initial Pressure (psig. @ 70° F) Vapor Density (AIR = 1) Solubility in Water Appearance and Odor - Clea SECTION IV - Fire and Expl USA Flame Projection Test (A	dous by the State own present in renical Characteristrical Charact	s of California, Florigulated concentration intics 133° F 40 ± 5 Greater than one (1) Soluble with a fresh scent in the second diox gnition sources. spray to keep containing the soluble state of the second containing	da, Illinois, Micons. Specific Gi Concentrate Melting Po Evaporatio pH an aerosol ca mits No Data ide, dry chemi	chigan, New Jers ravity (H ₂ O = 1) e @70° F int on Rate (Butyl Additional) in. ical, foam or fog. d vapors down. [cetate = 1) LEL No Data Concentrate is high	0.794 No Data No Data Not applicable UEL No Data	
Any substance listed as hazard Texas is described above if kn SECTION III Physical/Chen Boiling Point Concentrate - Initial Pressure (psig. @ 70° F) Vapor Density (AIR = 1) Solubility in Water Appearance and Odor - Clean SECTION IV - Fire and Expl USA Flame Projection Test (10", no flashback, not flamma Extinguishing Media - Water flammable. Vapors may travel Special Fire Fighting Proced	r colorless liquid voices has be ineffectively along ground to lures - Use water self-contained brown present in resource of the self-contained brown present in resource of t	s of California, Florigulated concentration intics 133° F 40 ± 5 Greater than one (1) Soluble with a fresh scent in the content in the co	da, Illinois, Micons. Specific Gi Concentrate Melting Po Evaporatio pH an aerosol ca mits No Data ide, dry chemical chemical fire	chigan, New Jers ravity (H ₂ O = 1) e @70° F int on Rate (Butyl Addition) ical, foam or fog. d vapors down. [cetate = 1) LEL No Data Concentrate is high	0.794 No Data No Data Not applicable UEL No Data No Data	

1046-99-1 January 1, 1999 SECTION V - Reactivity Data Stability Unstable Conditions to Avoid - Extreme heat, direct sunlight Stable Incompatibility (Materials to Avoid) - Strong oxidizers and mineral acids, permanganates, chromates and chlorine. Hazardous Decomposition or Byproducts - Carbon dioxide, carbon monoxide, smoke, soot and various organic oxidation byproducts May Occur **Hazardous** Conditions to Avoid - None known **Polymerization** Will Not Occur Χ **SECTION VI - Health Hazard Data** Route(s) of Entry Eves? Yes Inhalation? Skin? Ingestion? Yes Yes Yes Health Hazards (Acute and Chronic) - Warning. Flammable contents. Causes eye irritation. May cause skin irritation. May be harmful if swallowed, but this is unlikely as the product is a mist when sprayed. Intentional overexposure to mist or vapors may result in anesthetic or central nervous system effects. IARC Monographs? Carcinogenicity: None known **OSHA Regulated?** Signs and Symptoms of Exposure - Irritation of nose, throat, skin or eyes. Dryness of skin. Drowsiness, dizziness, fatigue or loss Medical Conditions Generally Aggravated by Exposure - Pre-existing skin, liver or kidney disorders may be adversely affected. Follow good chemical hygiene practices to avoid these hazards. Emergency and First Aid Procedures: Eyes - Flush with plenty of water for at least 15 minutes lifting eyelids to insure complete removal. Get immediate medical attention. Ingestion - Unlikely as this product is a mist when used. Inhalation - Get to fresh air. If breathing has stopped, qualified personnel should administer artificial respiration. Skin - Wash thoroughly with soap and water. If irritation arises and persists, call a physician. SECTION VII - Precautions for Safe Handling and Use Steps to be Taken in Case Material is Released or Spilled -Caution, slip hazard. Wipe up small spills promptly. For large releases, isolate traffic and ventilate area. Eliminate all ignition sources. Wear protective gear as necessary. Dike to prevent spread. Pick up with an absorbant material and put in a suitable container for proper disposal. Clean any residues from large spills with a suitable soap or detergent. Waste Disposal Method - Consult local, state and federal regulations. Do not puncture or incinerate container. Replace cap on empty can, wrap, then discard container if allowed by applicable statutes. Offer for recycling if resources are available. Precautions to be Taken in Handling and Storing - Do not use around ignition sources such as heat, sparks, open flame, static electricity, welding arcs, etc. Do not get in eyes. Avoid contact with skin and clothing. Wash thoroughly after handling. Avoid directly inhaling mists. Store in a cool (under 120°F) dry location away from heat, sparks, open flame and direct sunlight. Other Precautions - Follow label directions carefully. Keep out of reach of children. Spray can in upright position only. Do not deliberately concentrate and inhale vapors. Direct spray away from face. Do not use around any ignition sources such as heat, sparks, open flame, static electricity, welding arcs, etc. Do not puncture or incinerate container. Do not smoke while using. **SECTION VIII - Control Measures** Respiratory Protection (Specify Type) - Not usually necessary. Use with adequate ventilation. If PELs or TLVs are exceeded (see Section II), use an approved NIOSH\MSHA respirator. Ventilation **Local Exhaust** Not usually needed **Special** None **Mechanical (General)** Acceptable Other None Protective Gloves - Not usually needed. Wear gloves if direct Eye Protection - Not usually needed. Wear approved safety

Work/Hygienic Practices -Normal. Wash thoroughly before eating, drinking, smoking, using restrooms, etc. DISCLAIMER OF WARRANTIES

glasses or goggles if direct contact is possible

NO REPRESENTATIONS OR WARRANTIES, EITHER EXPRESS OR IMPLIED, OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, OR OF ANY NATURE ARE MADE WITH RESPECT TO THE PRODUCT(S) OR INFORMATION CONTAINED IN THIS MATERIAL SAFETY DATA SHEET.

The information and recommendations contained in this Material Safety Data Sheet are supplied pursuant to 29 CFR 1910.1200 of the Occupational Safety and Health Standards Hazard Communication Rule. All information contained herein is presented in good faith and is believed to be appropriate and accurate.

THE BUYER OR USER ASSUMES ALL RISKS ASSOCIATED WITH THE USE, MISUSE OR DISPOSAL OF THIS PRODUCT. THE BUYER OR USER IS RESPONSIBLE TO COMPLY WITH ALL FEDERAL, STATE OR LOCAL REGULATIONS CONCERNING THE USE, MISUSE OR DISPOSAL OF THESE PRODUCTS.

Other Protective Clothing or Equipment - Not usually needed. If direct contact is possible, wear apron, boots, face shield, etc. as