MATERIAL SAFETY DATA SHEET

This Made Complies with our reason Communication Orange 25 Or N 1500, 1200 and Oct N 1500, 12						
		UTOR'S INFORMATION				
		HMIS Rating: Health-2; Flammability-2; Reactivity-0; Personal Protection-B				
		DOT Hazard Classification: ORM-D				
Address: 302 N. 4th Street		Identity (trade name æ used on label):				
Address: St. Joseph, MO 64501		I-Force Gear, Chain & Cable Lubricant				
		(# HIL0110254)				
Phone: (816)-233-1321 ext. 8285 or http://www.hillyard.com		MSDS Number: 352 Revision- 1				
		Date Prepared: 10/07/93 Prepared By: DL/KD				
		Information Calls: (770)422-2071				
SECTION 1 - MATERIAL IDENTIFICATION AND INFORMATION						
COMPONENTS-CHEMICAL NAMES AND COMMON NAMES	CAS Number	SARA	OSHA PEL	ACGIH	Carcinogen	
(Hazardous Components 1% or greater; Carcinogens 0.1% or greater)		CAS Number	III LIST	(ppm)	TLV (ppm)	Ref. Source **
PETROLEUM DISTILLATE		64742-47-8	No	100	100	d d
		·····				
ISOBUTANE / PROPANE BLEND		75-28-5	No	800	800	d
		74-98-6	No	1000	1000	q
PETROLEUM OIL MIXTURE		8002-05-9	Νο	5mg/M3	5mg/M3	d
				TWA for oil	TWA for oil	
				mist	mist	
OFOTION C. DUVINO	AL IOLICI	HOAL OUADAOTEOIG	7100	<u> </u>		
		MICAL CHARACTERIS				
Boiling Point: N/A	Specific Gravity (H2O=1): Concentrate Only = 0.90					
		Vapor Pressure (Non-Aerosols)(mm Hg and Temperature): N/A				
		Evaporation Rate (= 1): N/E				
Solubility in Water: Insoluble	Water Reactive: No					
Appearance and Odor: Silver cofor with aliphatic solvent odor.						
SECTION 3 - FIRE AND EXPLOSION HAZARD DATA						
LAMMABILITY as per USA FLAME PROJECTION TEST Auto Ignition Temperature Flammability Limits in Air by % in Volume:						
(aerosols) FLAMMABLE	N/E % LEL: N/E % UEL: N/E					
FLASH POINT AND METHOD USED (non-aerosols): N/A EXTINGUISHER MEDIA: Foam, dry chemical, carbon dioxide.						
SPECIAL FIRE FIGHTING PROCEDURES: Self-contained breathing apparatus.						
Unusual Fire & Explosion Hazards: Do not expose aerosols to temperatures above 130°F or the container may rupture.						
SECTION 4 - REACTIVITY HAZARD DATA						
STABILITY [X] STABLE [] UNSTABLE HA		HAZARDOUS POLYMERIZATION [] WILL [X] WILL NOT OCCUR				
		Conditions to Avoid: Open flame, welding arcs, heat, sparks.				
Hazardous Decomposition Products: CO, CO2, and various hydrocarbons.						
SECTION 5 - HEALTH HAZARD DATA						
PRIMARY ROUTES OF ENTRY: [X] INHALATION [] INGESTION [] SKIN ABSORPTION [] EYE [] NOT HAZARDOUS						
ACUTE EFFECTS						
Inhalation: Excessive inhalation of vapors can be harmful and may cause headache, dizziness, asphyxia, anesthetic effects and possible unconsciousness.						
Eye Contact: Mild irritation. Skin Contact: Mild irritation due to defatting of skin.						
ingestion: Possible chemical pneumonitis if aspirated into lungs. Nausea.						
CHRONIC EFFECTS: (Effects due to excessive exposure to the raw materials of this mixture) May cause elevated carboxyhemoglobin levels, eye damage, lung						
damage.						
Medical Conditions Generally Aggravated by Exposure: ·May aggravate existing eye, skin, or upper respiratory conditions.						
EMERGENCY FIRST AID PROCEDURES						
Eye Contact: Flush with water for 15 minutes. If irritated, seek medical attention.						
Skin Contact: Wash with soap and water. If irritated, seek medical attention.						
Inhalation: Remove to fresh air. Resuscitate if necessary. Get medical attention.						
Ingestion: DO NOT INDUCE VOMITING. Drink two large glasses of water. Get immediate medical attention.						
SECTION 6 - CONTROL AND PROTECTIVE MEASURES						
Respiratory Protection (specify type): If vapor concentration exceeds TLV, use respirator approved by U.S. Bureau of Mines for organic vapor.						
Protective Gloves: Neoprene, if skin easily irritated. Eye Protection: Safety glasses recommended.						
Ventilation Requirements: Adequate ventilation to keep vapor concentration below TLV.						
Other Protective Clothing & Equipment: None						
Hygienic Work Practices: Wash with soap and water before handling food. Remove contaminated clothing.						
SECTION 7 - PRECAUTIONS FOR SAFE HANDLING AND USE						
Steps To Be Taken If Material is Spilled Or Released: Absorb with suitable medium. Incinerate or landfill according to local, state or federal regulations. DO NOT						
FLUSH TO SEWER.						
Waste Disposal Methods: Aerosol cans when vented to atmospheric pressure through normal use, pose no disposal hazard.						
Precautions To Be Taken in Handling & Storage: Do not puncture or incinerate containers. Do not store at temperatures above 130°F.						
Other Precautions &/or Special Hazards: KEEP OUT OF REACH OF CHILDREN. Avoid food contamination. Remove ignition sources.						
Other Fredautions aron special nazards: NEEF OUT OF REACH OF CHILDREN, AVOID 1000 CONTAMINATION, Remove ignition sources,						

We believe the statements, technical information and recommendations contained herein are reliable, but they are given without warranty or guarantee of any kind.

** Chemical Listed as Carcinogen or Potential Carcinogen. [a] NTP [b] IARC Monograph [c] OSHA [d] Not Listed [e] Animal Data Only