Product: 77610055	MATERI AL	SAFETY DATA	SHEET]	MSDS:	541160
Ŋ	ATERIAL SA	FETY DATA SI	HEET			
Product Name or Number(as it appears on the label) GLISTEN 64 to 1 Concentrated Glass Cleaner						
Section I - Product Identification						
Manufacturer's Name Spectrum I Inc. Address(No, Street, City, State & Zip Code) 618 West Flores Tucson, AZ 85705 Material Safety Data Sheet ID # 541160			Date 6-28-99 Emergency Telephone No. (800) 424-9300 Chemtrec Telephone No. for Information (520) 791-7094			
Section II - Hazardous Ingredients						
hazardous components (specific chemical identity, common name) Isopropanol		acgih tlv 400ppm		mits	% opt	ti onal
Section III - Physical Data						
Boiling Point 212 F Vapor Pressure - like water Vapor Density (Air=1) like water Solubility in Water complete Specific Gravity (H20=1) 0.980 Melting Point n/a Evaporation Rate (but. ace. =1)<0.4 Appearance and Odor-clear blue liquid, alcohol odor						
Section IV - Fire & Explosion Hazard Data						
Flash Point (Method Used)	Fla	mmable Limit n/a	ts	LEL n/a		
Extinguishing Media-Water, CO2, Dry foam Special Fire Fighting Procedures - none Unusual Fire And Explosion Hazards - none						
Section V - Reactivity Data						
Stability Conditions to Avoid Stable Avoid open flame Incompatability (Materials to Avoid) none Hazardous Decomposition of Byproduct						
none Hazardous Polymerization Conditions to Avoid Will not Occur none						
Secti	on VI - He	alth Hazard	Data			
Route(s) of Entry Inhala Health Hazards (Acute and Carcinogenicity Nt n/a n/ Signs and Symptoms of Expo Inhalation: Vapors may ventilation. Medical conditions Aggrava none	ation_X_ S Chronic) - p a osure be irrita	kin Ing Eyes: bur IARC Mono n/a ting to brea	estion_X_ ning, irri graphs	Other(Sitation, OSHA Reg n/a	Specit redno gul ato	fy) ess ed

Product: 77610055 MSDS 541160 Page 2 of 2

Emergency and First Aid Procedures
Eyes: flush with large amounts of running water (15 minutes) occasionally holding yeylids open. Ingestion: drink 2 glasses of water. Induce vomiting. CALL A PHYSICIAN. Section VII - Precautions for Safety Handling and Use Steps to be Taken in Case Material is Released or Spilled Collect and reuse if possible. Wash area with water. Waste Disposal Method Wash down drain, if permitted by federal, state and local regulations. Precautions to be taken in handling and storing Avoid open flame. Other Precautions None, except normal good housekeeping practices. -Sections VIII - Control Measures Respiratory Protection (Specify Type) none required Ventilation Local Exhaust satisfactory Special n/a Other n/a Mechanical (General) n/a Eye Protection Protective Gloves Avoid prolonged exposure to skin. Avoid splashing into eyes. Other Protective Clothing or Equipment As required to prevent wetting of clothing. Work/Hygienic Practices Normal good housekeeping practices. Wash hands after use.