


FPV Frame Assembly Guide for XL10 V4



Accessories list for XL10 V4

M3x8mm Screw 12

M3x12mm Screw 4

M3x14mm Screw 4

M3x16mm Screw 4

M3 Press Nut 8

M3 Nylon Nut 8

M3x5+6 Nylon Nut 12

M3x25mm Standoff 4

M3x35mm Standoff 4