AOS 5 O3

机架组装示意图 Frame Assembly Guide

1.	顶板 Top plate	x1 ,
2.	底板 Bottom plate	x1
	机臂 Arm	x4
4.	中板A Counter plate A	x1
5.	中板B Counter plate B	x2 :
	摄像头侧板 Camera side plate	x1
7.	脚垫打印件 Arm guard TPU	x4
	图传天线座打印件 Antenna TPU	x1
9.	可调节狗座底座打印件 GoPro bottom stand TPU	x1
	接收机座打印件 Receiver mount TPU	x1
11.	天线固定座 Antenna mount plastic	x1
12.	摄像头硅胶侧板 Silicone camera side plate	x1
13.	M2*23 圆形网纹铝柱 M2*23 Al. standoff	x2
14.	M3*20 圆形网纹铝柱 M3*20 Al. standoff	x8 ¦
15.	M3*6 沉头内六角螺丝 M3*6 countersunk hex screw	x8 !
16.	M3*14 沉头内六角螺丝 M3*14 countersunk hex screw	x10
17.	M3*6 内六角螺丝 M3*6 hex screw	x4
18.	M2*5 内六角螺丝 M2*5 hex screw	x10
19.	M2*7 内六角螺丝 M2*7 hex screw	x4
20.	M3*10 内六角螺丝 M3*10 hex screw	x14
21.	M1.6*10 杯头内六角螺丝 M1.6*10 socket head cap	x4
	M2*6 内六角螺丝 M2*6 hex screw	x4
	M3*8 内六角带垫螺丝 M3*8 hex washer head screw	x2
24.	M2 尼龙螺母 M2 nvlon nut	x2

,, (附赠)/(Additional parts)			
1. M3 尼龙螺母 1. M3 nylon nut	x8 ¦		
2. M3*20 沉头内六角螺丝 2. M3*20 countersunk hex screw	x4 !		
3. M2*20 内六角螺丝 M2*20 hex screw	x4 ¦		
4. M3六角斜花齿压铆螺母 M3 hexagon nut	x2		
5. M2 防松自紧螺母 M2 lock nut	x4 ¦		
6. M3 lock nut	x4 :		
7. Allen wrench	x1 ¦		
8. M5法兰螺母 8. M5 nut	x1 ¦		
9. M5*20 内六角螺丝 9. M5*20 hex screw	x1 !		
·	x4 :		
10. Motor wire protector	x1 :		
11. 15 * 250 Battery strap 15 * 250 超纤皮电池扎带	x1		
12. 15*200 Battery strap	x1 :		
13. Sticker 模拟图传天线座打印件			
14. Analog VTX antenna mount	x1 :		
15. M3 硅胶减震垫片 15. M3 silicone washer	х8		
16. M3减震橡胶柱 16. M3 rubber damper balls	х8 ¦		
17. 光面硅胶防滑垫 17. Silicone spacer for 19mm cam	x2		
电池硅胶防滑垫 18. Battery pad	x2		
19. 自锁尼龙扎带 Self-locking nylon zip ties	x5 ¦		
`\/			

