AMERICA'S # SOLVENT BRAND



ACETONE CLEANS PROJECT RESIDUE



Fiberglass Resins, **Epoxy & Adhesives**



with No Residue



Learn More!

DANGER! EXTREMELY FLAMMABLE. VAPORS MAY CAUSE FLASH FIRES OR IGNITE EXPLOSIVELY, VAPOR HARMFUL, EYE IRRITANT.

Read entire label prior to use or storage.

ONE GALLON (3.785 L)

Lea toda la etiqueta antes de usar o almacenar este

J10226

Klean-Strip® Acetone is a strong, fast-acting solvent that is a thinner and remover for specified coatings, including uncured polyester and epoxy resins, ink, adhesives and contact cement. Acetone is an effective cleanup solvent after the completion of a fiberglass project, for removal of excess fiberglass resin or foreign material from solvent-tolerant surfaces.

DIRECTIONS FOR USE: Use only as specified by the coating, adhesive, or hobby product manufacturer. Test in an inconspicuous spot first.

IMPORTANT: Do not spread this product over surface areas greate than 1 sq. foot because fire and health safety risks will increase dramatically. Acetone may soften or damage plastics, synthetics, and many other finishes. Do not use to clean or flush spray equipment.

DANGER! EXTREMELY FLAMMABLE, VAPORS MAY CAUSE FLASH FIRE OR IGNITE EXPLOSIVELY, KEEP AWAY FROM HEAT SPARKS, FLAME, AND ALL OTHER SOURCES OF IGNITION Extinguish all flames and pilot lights, and turn off all stoves, heaters, electric motors and all other sources of ignition during use and until all vapors are gone. Do not smoke. Keep away from electrical outlets and switches. Beware of static electricity generated by synthetic clothing and other sources. **USE ONLY WITH ADEQUATE VENTILATION TO PREVENT BUILDUP OF VAPORS.** Do not use in areas where vapors can accumulate and concentrate such as basements, bathrooms and small, enclosed areas. If using indoors, open all windows and doors and maintain a cross ventilation of moving fresh air across the work area. If strong odor is noticed or you experience dizziness – STOP – ventilation is inadequate. Leave area immediately. IF THE WORK AREA IS NOT WELL VENTILATED, **DO NOT USE THIS PRODUCT.** A dust mask does not provide protection against vapors

DANGER! VAPOR HARMFUL, EYE IRRITANT, Contains Acetone. Keep container tightly closed when not in use. Reports have associated repeated and prolonged overexposure to solvents with neurological and other physiological damage. Intentional misuse of this product by deliberately concentrating and inhaling vapors can be harmful or fatal. Do not take internally. Avoid breathing of vapors or mist and contact with skin, eyes or clothing.

FIRST AID: INHALATION: First move person to fresh air. If not breathing, give artificial respiration. Call 911, or Poison Control Center at 1-800-222-1222, or emergency room, as soon as possible. EYE EXPOSURE: Immediately flush affected eye(s) with water for 15 minutes, Call 911, or Poison Control Center, or emergency room, as soon as possible. SKIN EXPOSURE: la niebla y el contacto con la piel, los ojos o la ropa. Immediately wash skin with soap and water. Avoid spreading material on unaffected skin. Remove contaminated clothing and shoes, and thoroughly clean before reuse. Contact medical professional for advice. IF SWALLOWED: IMMEDIATELY call 911. or Poison Control Center, or emergency room, as soon as possible. **DO NOT INDUCE VOMITING** unless directed to do so by medical personnel. Never give anything by mouth to an unconscious person.

KEEP OUT OF REACH OF CHILDREN.

Product Category: Multi-Purpose Solvent • Max VOC: 3%

For assistance: Call the Barr Help Line 1-800-398-3892 Monday through Friday 8:00am to 4:30pm CT

GAC18 / J10227



©2025, W.M. Barr & Co., Inc. Memphis, TN 38113 www.kleanstrip.com

INSTRUCIONES DE USO: Úselo únicamente conforme lo especifique el fabricante del recubrimiento, adhesivo o producto para aficionados. Primero pruebe en un punto poco visible.

IMPORTANTE: No rocíe este producto en áreas mayores a 1 pie cuadrado (0.093 m2) ya que el riesgo de incendio y los riesgos a la salud se incrementarán dramáticamente. La acetona puede ablandar o dañar plásticos, superficies sintéticas y muchos otros acabados. No lo utilice para limpiar ni enjuagar el equipo rociador

¡PELIGRO! EXTREMADAMENTE INFLAMABLE. LOS VAPORES PUEDEN PROVOCAR COMBUSTIONES SUBITAS O INFLAMARSE DE MANERA EXPLOSIVA. MANTÉNGASE LEJOS DEL CALOR CHISPAS, LLAMAS Y OTRAS FUENTES DE IGNICIÓN, Extinga todas las llamas y pilotos, y apague las estufas, calentadores, motores eléctricos y cualquier otra fuente de ignición durante su uso y hasta que se hayan disipado los vapores. No fumar. Mantenerlo lejos de tomacorrientes e interruptores eléctricos. Tenga cuidado con la electricidad estática generada por la ropa sintetica y otras fuentes. USE ÚNICAMENTE CON UNA VENTILACIÓN ADECUADA PARA EVITAR LA ACUMULACIÓN **DE VAPORES.** No use en áreas donde los vapores se puedan acumular y concentrarse tales como sótanos, cuartos de baño y áreas pequeñas y encerradas. Si se utiliza bajo techo, abra todas las ventanas y las puertas y mantenga una ventilación cruzada de aire fresco en movimiento a través, del área de trabajo. Si nota un olor fuerte o se marea – DETÉNGASE –, la ventilación es inadecuada. Abandone el área de inmediato. SI EL ÁREA DE TRABAJO NO ESTÁ BIEN VENTILADA, NO USE ESTE PRODUCTO. Una máscara para el polvo no otorga protección contra los vapores.

iPELIGRO! VAPOR DAÑINO. IRRITA LOS OJOS. Contiene acetona. Mantener el recipiente bien cerrado cuando no esté en uso Ciertos informes asocian la sobreexposición repetida y prolongada a los solventes con dolencias neurológicas y otras afecciones fisiológicas. El uso indebido intencional de este producto para concentrar e inhalar de manera deliberada sus vapores puede resultar dañino o mortal. No ingerir. Evite respirar los vapores o

PRIMEROS AUXILIOS: INHALACIÓN: Primero mueva a la persona a un lugar con aire fresco. Si no respira, administre respiración artificial. Llame al 911, al centro de control toxicológico al 1-800-222-1222, o a la sala de emergencias, tan pronto como sea posible. EXPOSICIÓN DE LOS OJOS: Enjuague de inmediato con agua los ojos afectados durante 15 minutos. Llame al 911, al centro de control toxicológico, o a la sala de emergencias, tan pronto como sea posible. **EXPOSICIÓN DE LA PIEL:** Lave la piel inmediatamente con agua y jabón. Evite extender el material sobre la piel no afectada. Quite la ropa y los zapatos contaminados y lávelos minuciosamente antes de volver a usarlos. Póngase en contacto con un profesional médico para obtener consejos. SI SE TRAGA: INMEDIATAMENTE llame al 911, al centro de control toxicológico, o a la sala de emergencias, tan pronto como sea posible. NO INDUCIR EL VÓMITO a menos que así lo indique el personal médico. Nunca le dé nada por la boca a una persona inconsciente.

MANTENGASE FUERA DEL ALCANCE DE LOS NIÑOS.

Categoría de producto: Solvente multiuso • COV máx.: 3%