Los aditivos para queroseno Klean-Strip[®] son la forma segura de alargar la vida de la mecha en su calentador de queroseno. Esto ayudará a reducir el olor del queroseno y a reducir el humo y la acumulación de alquitrán y carbón.

INSTRUCCIONES PARA SU USO: Vierta el aditivo para queroseno Klean-Strip directamente en su contenedor de queroseno o en su calentador de queroseno. No use más de 1 oraza para cinico galories de gueroseno. Muntar rellene el calentador de queroseno cuando alon este operando o aún esté caliente. Siempre lea y siga las instrucciones del fabricante del calentador.

PELERON SE VEIENICS, INFLAMABLE LOS VENDERS PLECIBLE CAUSANI, INCLAMO DI INCENDIO EPICENTO, MANTENIASE FIERA DEL CALO, CHISNA NALIMANO Y TIODAS LOS DEMAS PERIFERIO E DIGITORIO. CONTINE PRESENTA DEL CALO, CHISNA CHISNA Y TIODAS LOS DEMAS PLEMENTO E DIGITORIO. CONTINE PRESENTA DEL CALO CHISNA CHISNA SE SELILAS CALENDATORIO DEL PROSENTA DEL PR

ADVERTENCIA: Este producto puede exponerlo a productos quimicos como el metanol y el monovido de carborio que, según el estado de California causan defectos de nacimiento u otros parios reproductivos. Los subproductos del combustible contienen hollin, que el estado de California sade que causa cancer. Para obtener más información, vaya a www.P651Namingos.ca.gov.

PRIMEROS AUXILLOS. EN CASÓ DE CONTACTO OCIULAD, láves e immediatamente con apua, effer padaquier lente de contrado, continue epispaindose con aqua port amenos 15 minotos que porte para atención medica immediate. EN CASO DE CONTACTO CON LA PEC, lan eminocionamente con aqua, a Syessiste la initiación, obtenza atención médica. SI ES INCERIDO, contacte de immediato al centro de contro de verenco, sala de eleptracia de un hispital o a un medico para obtener restructores sobre como motor el Virnito.

MANTÉNGASE FUERA DEL ALCANCE DE LOS NIÑOS





Reduces smoke and kerosene odors • Keeps wick cleaner and longer lasting
Reduces tar and carbon build-up

DANGER! ** POISON.
FLAMMABLE. VAPORS MAY CAUSE
FLASH FIRE OR IGNITE EXPLOSIVELY.
MAY BE FATAL OR CAUSE
BLINDNESS IF SWALLOWED.
VAPOR HARMFUL. EYE, SKIN AND
RESPIRATORY IRRITANT.
Read other cautions on back panel.

8 FL OZ (236 mL)

iPELIGRO! ★ VENENO.
INFLAMABLE. LOS VAPORES
PUEDEN CAUSAR UN INCENDIO
ESPONTANEO O INCENDIARSE
EXPLOSIVAMENTE. LETAL O CAUSAR
CEGUERA SI SE INGIERE. VAPOR
DANINO. IRRITANTE DE LOS OJOS.
I A PIEL Y I AS VIAS RESPIRATORIAS

Lea las precauciones en el panel posterior.

Klean-Strip® Kerosene Additives are a safe way to add life to the wick in your kerosene heater. It will help reduce kerosene odors as well as reduce smoke, tar and carbon build-up.

DIRECTIONS FOR USE: Pour Klean Strip Kerosene Additive directly into your container of Kerosene or into your kerosene heater. Do not use more than 1 ounce to five gallons of Kerosene, NEVER REFLIL KEROSENE HEATER WHEN IT IS SILL OPERATING OR HOT. Awars read and follow heater manufacturer's instructions.

DANGERI 'S POISON, FLAMMABLE, VAPORS MAY CAUSE FLASH FIRE OR IGNTE EXPLOSIVELY KEEP AWAY FROM HEAT, SPARKS, FLAME, AND ALL OTHER SOURCES OF IGNITION. Cortains Neithand. Cannot be made run-robisomous. Evinquish all flames and pibli flights, and turn off all disces heaters, electric motions and all other sources of ignition during use and until all vapors are gone. Do not smoke. Keep away from electrical outliets and switches. Beware of static electricity generated by synthetic coloring and other sources. USE ONLY WITH ADEQUATE VERTILATION TO PREVENT BUILDUP OF VAPORS. Do not use in areas where vapors can accumulate and concentrate such as basements, behrmoms and small, enclosed areas. If using indoors, open all windows and doors and maintain a rows welfilation of moving fresh ar aroses the work area. If strong odor is noticed or you experience dizziness. — STOP — vertilation is inadequate. Leave area immediately. IF THE WORK AREA IS NOT WELL VERTILATED, DO NOT USE THIS PRODUCT. A dust mask does not provide profection acabinst vacors.

WARNING: This product can expose you to chemicals including Methanol, and Carbon Monoxide which are known to the State of California to cause birth defects or other reproductive harm. By-products of fuel contain soot, which is known to the State of California to cause cancer. For more information go to www.P56Warnings.ca.gov.

FIRST AID: IN CASE OF EYE CONTACT, immediately flush with water, remove any contact lens, continue flushing with water for at least 15 minutes, then get immediate medical attention. IN CASE OF SXIN CONTACT, flush thoroughly with water. If irritation persists, get medical FSWALLOWED, immediately contact Poison Control Center (1-800-222-1229), hospital emergency room or physician for instructions on inducing womiting.

KEEP OUT OF REACH OF CHILDREN

For assistance call: The Barr Help Line 1-800-398-3892 Monday - Friday 8am - 4:30 pm Central Time

Product # WKAU55000 ©2019 W.M. Barr & Co., Inc. www.kleanstrip.com All rights reserved.



Label design is a trademark of W.M. Barr & Co., Inc