Los aditivos para queroseno Klean-Strip® son la forma segura de alargar la vida de la mecha en su calentador de queroseno. Esto apudará a rediucir el olor del queroseno y a reducir el humo y la acumulación de aloutitan y carbón.

INSTRUCCIONES PARA SU USO: Vierta el atório para quencisero (kean Sirro directamente en su contenedor de quenciseno o en su calentador de quenciseno. No use más de 1 oraza para cincio galories de quenciseno. Nunca rellans el calentador de quenciseno cuando da más de porte de calentador cuando da más de predictador se de calenta. Sempre lea y siga las instrucciones del táncisante el el calentador

PELGROL SE VELENISO, INFLAMABLE LOS VAPORES PLEDEN CAUSAR UN INCENDIO DI OCCUDIO EPPLOSIVO, MANTEDIASE FIRER DEL CALOR, CHISPA. LLAMAS Y TOORS LAS DEMAS FILIPITES DE IGNICIÓN. Contiene netaron. No pude haceres no veneriosa. Apaque todas las almas y luces piloto, y apaque todas las estudas cultariadores motores electricos y todas las otras buentos de conción durante el uso y hasta que todas las electricos y todas las otras buentos electricos y todas las otras buentos de conción durante el uso y hasta que todas las reportes es legan do. No forma cuntado con la electricodad estática cemerada por la repos similariz o vitras fuentes. SISEN DIVIGAMENTE CON VINTITACIÓN ADECUADA PARA EVITAR LA EXISTENDA DE VAPORES. No lo use en áreas donde los regores se pueden acomulad y concentra como sistemas, bains y areas pequenas y certadas. Si que ale refere como monimento en el area de balago. Si se nota un hierte doro os experimenta manero. DE ENIOSES la ventilación en radicuadas. Salos alel area mediatamente. SI EL ARRAD ETRABAJO NO ESTA BEREVIENTILAÇÃO, NO USE ESTE PRODUCTO. Una massara anticolo no brinda professión contra las vapores.

ADVERTENCIA: Este producto puede exponerio a productos quimios como el metanol y el monoxido de carbono que, según el estado de California, causan defectos de nacimiento u otros fiarios reproductivos. Los subproductos que causa cáncor. Para obtener más información, vaya a www.P60/Haminos.ca.cov.

PRIMEROS AUXILIOS. ÉN CASÓ DE CONTACTO OCULAR, laves inmediatamente con qua, effer palquier lente de contracto, continue enjuacandose con aqua con entre 15 firmulos. Leuro ditença atención medica immetale. EN CASO DE CONTACTO CON LA PEEL, lave milhuoloscamente con aqua. Si perseste la milación, obtença atención médica. SI ES MICERIOD, contacte de immediato al centro de contro de envenos, sala de envierpeicas de un lasgital o a un medio para obtener restrucciónes sobre como rindor el firmito.

MANTÉNGASE FUERA DEL ALCANCE DE LOS NIÑOS





Reduces smoke and kerosene odors • Keeps wick cleaner and longer lasting
Reduces tar and carbon build-up

DANGER! > POISON.
FLAMMABLE. VAPORS MAY CAUSE
FLASH FIRE OR IGNITE EXPLOSIVELY.
MAY BE FATAL OR CAUSE
BLINDNESS IF SWALLOWED.
VAPOR HARMFUL EYE, SKIN AND
RESPIRATORY IRRITANT.
Red ofter caufors on back panel.

8 FL OZ (236 mL)

iPELIGRO! № VENENO.
INFLAMABLE. LOS VAPORES
PUEDEN CAUSAR UN INCENDIO
ESPONTANEO O INCENDIARSE
EXPLOSIVAMENTE. LETAL O CAUSAR
CEGUERA SI SE INGIERE. VAPOR
DANINO. IRRITANTE DE LOS OJOS,
LA PIEL Y LAS VIAS RESPIRATORIAS.

Lea las precauciones en el panel posterior.

Klean-Strip® Kerosene Additives are a safe way to add life to the wick in your kerosene heater. It will help reduce kerosene odors as well as reduce smoke, tar and carbon build-up.

DIRECTIONS FOR USE; Pour Klean Strip Kerosene Additive directly into your container of Kerosene or into your kerosene heater. Do not use more than 1 ounce to five gallons of Keroséne. NEVER REFILL KEROSENE HEATER WHEN IT IS STILL OPERATING OR HOT. Always read and follow heater manufacturer's instructions DANGERI POISON EI AMMARI E VAPORS MAY CAUSE EI ASH EIRE OR IGNITE EXPLOSIVELY, KEEP AWAY FROM HEAT, SPARKS, FLAME, AND ALL OTHER SOURCES OF IGNITION. Contains Methanol. Cannot be made non-poisonous Extinguish all flames and pilot lights, and turn off all stoves, heaters, electric motors and all other sources of ignition during use and until all vapors are gone Do not smoke. Keep away from electrical outlets and switches. Beware of statio electricity generated by synthetic clothing and other sources, USE ONLY WITH ADEQUATE VENTILATION TO PREVENT BUILDUP OF VAPORS. Do not use in areas where vapors can accumulate and concentrate such as basements bathrooms and small, enclosed areas, If using indoors, open all windows and doors and maintain a cross ventilation of moving fresh air across the work area If strong odor is noticed or you experience dizziness – STOP – ventilation is inadequate. Leave area immediately, IF THE WORK AREA IS NOT WELL VENTILATED, DO NOT USE THIS PRODUCT. A dust mask does not provide protection against vapors

WARNING: This product can expose you to chemicals including Methanol, and Carbon Monoxide which are known to the State of California to cause birth defects or other reproductive harm. By-products of fuel contain soot, which is known to the State of California to cause cancer. For more information go to www.P65Wamings.ca.gov.

FIRST AID: IN CASE OF EVE CONTACT, immediately flush with water, remove any contact lens, continue flushing with water for at least 15 minutes, then get immediate medical attention. IN CASE OF SKIN CONTACT, flush thoroughly with work that the property of the contact Poison Control Center (1-800-222-1222), Insopital emergency room or physician for instructions on inducing vorniting.

KEEP OUT OF REACH OF CHILDREN

For assistance call: The Barr Help Line 1-800-398-3892 Monday - Friday 8am - 4:30 pm Central Time

Product # WKAP55001 ©2019 W.M. Barr & Co., Inc www.kleanstrip.com All rights reserved.

W.M. Barr & Co., Inc. Memphis, TN 38113

Label design is a trademark of W.M. Barr & Co., Inc