US Patent & Trademark Office Patent Public Search | Text View

United States Patent Application Publication

Kind Code

A1

Publication Date

Inventor(s)

August 21, 2025

DUNCAN; BRANDON

METHOD AND APPARATUS FOR GREATER PRECISION IN TRACKING

Abstract

An apparatus and method including a means for adjusting the angle of a pointing input device. The pointing input device relies on an input surface for the purpose of calculating cursor position. The means for adjusting the angle of the pointing input device may include computer software stored in a computer memory, and implemented by a computer processor. The computer software may provide suggested angle changes on the computer screen to improve input precision of the pointing input device. The computer software may be configured to implement the suggested angle changes, with the pointing device; and wherein after the suggested angle changes are implemented with the pointing input device, the computer software enables a user, through a user interactive device, to determine what affect the suggested angle changes had on accuracy of the pointing input device, through data displayed on the computer screen.

Inventors: DUNCAN; BRANDON (LEE, NH)

Applicant: DUNCAN; BRANDON (LEE, NH)

Family ID: 1000007950847

Appl. No.: 18/747613

Filed: June 19, 2024

Related U.S. Application Data

parent US division 18581639 20240220 parent-grant-document US 12056298 child US 18747613

Publication Classification

Int. Cl.: G06F3/038 (20130101); G06F3/0354 (20130101); G06F3/039 (20130101)

U.S. Cl.:

Background/Summary

CROSS REFERENCE TO RELATED APPLICATION(S) [0001] The present application is a divisional of and claims the priority of U.S. patent application Ser. No. 18/581,639, filed on Feb. 20, 2024, inventor and applicant Brandon Duncan.

FIELD OF THE INVENTION

[0002] This invention relates devices for attempting to have greater precision in tracking operations on a computer screen as a result of interaction between a pointing input device, such as a computer mouse, and an input surface, such as a computer mousepad.

BACKGROUND OF THE INVENTION

[0003] In the present application, "input surface" is a surface that an input device makes contact with; and is used by the input device to calculate the position of a reference indicator (i.e. a mouse cursor or a game crosshair, hereby known as "cursor") on a computer screen as the input device is moved. A computer mousepad is a common example of an input surface. (Please note that almost any flat horizontal surface could functionally be used as an input surface, such as the surface of a desk.)

[0004] In the present application, "input device" refers to a physical device that a user uses to interact with computer software. There are many types of input devices, but the present application only references input devices that are "pointing input devices", other than a few references to keyboards, which are not pointing input devices. A computer mouse is a common example of a pointing input device. Though the concepts described in the present application would relate to any pointing input device that relies on the use of an input surface for calculation of cursor location and movement, for the sake of brevity, any further mention of a "pointing input device" will be referred to as a "mouse".

[0005] "Tracking" is the process of a user attempting to keep the cursor aligned with (or overlapping) a specific target in a software application, as that target moves and changes direction. Tracking accuracy can be expressed as a percentage, which is calculated by measuring how frequently the cursor stays in alignment with a target that is moving and changing direction. For any specified length of time divided into many intervals, a check is made at each interval to determine whether the cursor is aligned or not with the target. For example, if 25 seconds is divided into 100 intervals, and the cursor overlaps the target at **86** of those intervals, the tracking accuracy result would be 86%.

[0006] In a 3D (three dimensional) software application, the representation of the user (hereby known as the "avatar") could either be referred to as "the camera" in a first-person perspective software environment, or the user's "character" in a third-person perspective software environment. Objects that exist in the environment are often represented to be at different distances away from the avatar. Many applications will include reference markers (often as stripes on the ground labelled in 10-meter increments) to clarify how distances in the application are represented. These reference markers are often found in training sections of the application. For applications that don't include reference markers for distance, the size of the user's avatar can be used as the unit of measure. In most applications, an avatar is described to be approximately 2.0 meters tall, and the distance of objects would be expressed proportionally by how far away they appear from the avatar. One particular object may be 5.0 meters (2.5 character lengths) away from the avatar, while another object may appear to be 30.0 meters (fifteen character lengths) away, and a third object may be approximately 70.0 meters (thirty-five character lengths) away. In this example, the object at 5.0 meters would be described as being at "close range", the object at 30.0 meters would be at

"medium range", and the object at 70.0 meters would be "far range".

[0007] Prior to the creation of the present invention, it was possible to adjust mouse settings in such a way that the user would be able to maintain accurate tracking at a certain range, but would almost always find difficulty in producing a similar level of accuracy when tracking at any ranges that were significantly closer or farther away. For example, the user may have adjusted the mouse settings to optimize the ability to track targets at medium range, but would then find that his/her accuracy suffered at both close and far ranges. The user may have then adjusted the mouse settings to improve close range accuracy, but would find that the medium range accuracy had decreased, and that the far range accuracy had been even further worsened. (This difficulty maintaining tracking accuracy also applies in both 2D (two dimensional) environments and 3D environments when a target changes position along the Y axis (moves higher or lower), or when the user begins tracking a new target that is on a different Y axis position (higher or lower) than the original target.) [0008] Extreme input precision (hereby known as "precise aim") in 3D software space requires having a high percentage of tracking accuracy consistent across many ranges of targets, regardless of those targets' positions on the Y axis. Having precise aim in 2D software space requires having a consistent high percentage of accuracy for tracking targets, regardless of those targets' positions on the Y axis. In situations that require continuous accuracy in regard to cursor placement (such as when controlling expensive electronic equipment remotely or when playing competitive video games), the ability to consistently have precise aim across multiple ranges (or hypothetically, all ranges) would be a major advantage to a user.

[0009] Regarding mice and input surfaces, there are at least six factors that currently limit the possibility of precise aim in 2D and 3D computer software. At the time of the filing of the present application, two of these factors are widely known and understood by the mouse and input surface industry, and a third factor is known and at least somewhat understood. There are at least three factors that currently appear to not be understood to be a limitation to precise aim.

[0010] This is a list of those factors and how some affect the others. [0011] (a) First factor: Materials, and the friction between surfaces. (This is an industry-known factor).

[0012] A mouse has points where it physically makes contact with the input surface. Depending on the material composition of that surface (cloth, glass, plastic, leather) and those of the mouse contact points (e.g. mouse feet or mouse skates, often made of plastic) and their current conditions (hot/cold, humidity/wetness), along with any external contaminants present (dust, sweat, skin particles), there will be differing levels of friction when the mouse is moved.

[0013] If an input surface does not provide very much friction, a mouse will not require much force to start moving or change direction. In this instance, the input surface is described to be "fast". If an input surface provides significant friction, a mouse will require significant force to start moving or change direction. In this instance, the input surface is described to be "slow".

[0014] To ensure that input precision is consistent, the input surface must be clean of contaminants, and must have at least all of the following properties: [0015] (i) Durability—won't fray or degrade while being used; and [0016] (ii) Uniformity—the surface must have the same approximate friction at all points [0017] (iii) Humidity/Moisture resistance—if the material absorbs moisture, it will change the amount of resistance that the input surface provides.

[0018] In addition, in 3D space, when aiming at the longest ranges, having a textured input surface allows for fine adjustments that would be extremely difficult without tactile feedback from the input surface. The user can feel this input texture either as vibrations through the mouse as it moves, or by fingertips that directly touch the input surface.

[0019] If all other limiting factors have been accounted for and resolved/worked around, the most optimal input surface for most situations would be durable, uniform, and moisture resistant, and would be described as both textured and slow. This input surface would allow for fine grained adjustment in 3D aim when a target quickly and constantly changes directions. [0020] (b) Second Factor—Multiplicative product of the mouse DPI setting ("DPI", which stands for "dots per linear

inch" and is a measure of how many pixels the cursor moves per inch the actual mouse moves) and the sensitivity in the application ("sensitivity"), is often expressed as eDPI, which stands for "Effective Dots Per-inch". DPI values are generally set and/or modified in mouse software, or in a mouse driver interface. Most applications that rely on some level of input precision will have their own sensitivity setting (hereby known as "application sensitivity") that can be adjusted, either as a slider or a numerical value that can be typed in. DPI value multiplied by application sensitivity value equals eDPI value. (This is an industry known factor) For example, a DPI value of 800 with an application value of 4.21 would result in an eDPI of 3368. (Please note that eDPI only exists as a logical calculation, and thus, is not displayed anywhere and cannot be directly set anywhere. To raise eDPI, you would need to raise the mouse DPI value and/or the application sensitivity value. To lower eDPI, you would need to lower the mouse DPI value and/or the application sensitivity value.)

[0021] When eDPI values are changed, it affects the distance the mouse must be moved to have the cursor travel a set distance in a 2D or 3D space of a software application. If a mouse is physically moved a set distance, a higher eDPI value will cause the cursor to move farther than if a lower eDPI was used.

[0022] There is not a specific standard eDPI value or range that is universally considered to be the best in all situations. Different eDPI ranges are considered to be the most optimal in certain application types. In the example of computer games, tactical first-person perspective games often have slower movement and require a very slow, deliberate aiming style. The optimal eDPI range for many tactical first-person perspective games is often considered to be between 200 and 1000. In contrast, arena first-person perspective games often have much faster movement and require being able to react to opponents that suddenly appear behind the user. The optimal eDPI range for many arena first-person perspective games is often considered to be between 2500 and 7000. [0023] (c) Third Factor—Weight of the mouse. (This seems to be somewhat understood by industry) [0024] The weight of the mouse is an indirect factor whose largest impact is felt by how much force is required to initiate an abrupt change in direction of the mouse. The heavier a mouse, the more force it takes to start moving or change direction.

[0025] When used on an input surface that is "slow", the heavier a mouse is, the quicker it will come to a stop when movement force is reduced. When used on an input surface that is "fast", the heavier a mouse is, the more likely that momentum will keep the device moving when movement force is reduced, until eventually the friction of the input surface causes the mouse to come to a stop.

[0026] Generally speaking, a heavier mouse is considered less responsive than a lighter mouse because it takes additional force to initiate movement or direction changes in most situations, and it may situationally require additional force to make the device cease movement.

[0027] Conversely, a mouse that is too light may be considered to not have enough tactile feedback that the user would be able to intuitively estimate ("to feel") where the cursor should be at any given moment. This would lead to difficulty in maintaining tracking accuracy in situations where the target changes direction frequently.

[0028] For the most optimal aiming, a user should use the lightest mouse available that has enough weight to still provide tactile feedback.

[0029] There are three other factors that relate to precise aim, which do not appear to be currently understood, which is addressed in at least the summary and/or detailed description below related to the present invention.

SUMMARY OF THE INVENTION

[0030] (d) A Fourth Factor related to precision of mouse on input surface, is: Height angle of the mouse as it relates to the user. This fourth factor could be expressed as "forward to backward tilt and/or left to right tilt" of a mouse (e.g. leaning a mouse forward or backward, and/or to the left or right side). (At the time of this filing, this factor does not appear to be understood by the industry

and general public as a potential obstacle to mouse precision.)

[0031] This fourth factor is the primary limiting factor to aim precision that this present invention resolves in one or more embodiments.

[0032] In at least one embodiment of the present invention, an apparatus and/or a method is provided which comprises a means for adjusting the angle of a pointing input device with respect to a horizontal surface; and wherein the pointing input device relies on an input surface for the purpose of calculating cursor position.

[0033] The means for adjusting the angle of the pointing input device with respect to the horizontal surface may include computer software stored in a computer memory, and implemented by a computer processor.

[0034] The computer software stored in the computer memory, and implemented by the computer processor may provide suggested angle changes on the computer screen to improve input precision of the pointing input device.

[0035] The computer software may be configured to implement the suggested angle changes from the computer software, with the pointing device; and wherein after the suggested angle changes are implemented with the pointing input device, the computer software stored in the computer memory, and implemented by the computer processor enables a user, through a user interactive device, to determine what affect the suggested angle changes had on accuracy of the pointing input device, through data displayed on the computer screen.

[0036] In at least one embodiment, the computer software stored in the computer memory, and implemented by the computer processor generates targets at different positions on the computer screen.

[0037] In at least one embodiment, the computer software stored in the computer memory, and implemented by the computer processor produces additional sensitivity settings for improving accuracy of the pointing input device by creating an additional modifier to act along with manufacturer pointing input device DPI settings and manufacturer in-application sensitivities. [0038] The computer software stored in the computer memory, and implemented by the computer processor may use a range of dots per inch (DPI) settings and provides suggested angle changes on the computer screen to improve input precision of the pointing input device.

[0039] The computer software stored in the computer memory, and implemented by the computer processor may use a range of computer software sensitivities and may provide suggested angle changes on the computer screen to improve input precision of the pointing input device.

[0040] In at least one embodiment, an apparatus is provided comprising a means for adjusting the angle of an input surface with respect to a horizontal surface; and wherein a pointing input device relies on the input surface for the purpose of calculating cursor position.

[0041] The means for adjusting the angle of the input surface with respect to the horizontal surface may include computer software stored in a computer memory, and implemented by a computer processor.

[0042] In at least one embodiment, the computer software stored in the computer memory, and implemented by the computer processor provides suggested angle changes on the computer screen to improve input precision of the pointing input device.

[0043] In at least one embodiment, the computer software stored in the computer memory is configured to implement the suggested angle changes with the input surface; and wherein after the suggested angle changes are implemented with the input surface, the computer processor enables a user, through a user interactive device, to determine what affect the angle suggested changes had on accuracy of the pointing input device, through data displayed on the computer screen.

[0044] The computer software stored in the computer memory, and implemented by the computer processor may generate targets at different positions on the computer screen.

[0045] The computer software stored in the computer memory, and implemented by the computer processor may produce additional sensitivity settings for improving accuracy of the pointing input

device by creating an additional modifier to act along with manufacturer pointing input device DPI settings and manufacturer in-application sensitivities.

[0046] In at least one embodiment, the computer software stored in the computer memory, and implemented by the computer processor uses a range of dots per inch (DPI) settings and provides suggested angle changes on the computer screen to improve input precision of the pointing input device.

[0047] The computer software stored in the computer memory, and implemented by the computer processor may use a range of computer software sensitivities and provides suggested angle changes on the computer screen to improve input precision of the pointing input device.

[0048] In at least one embodiment, an apparatus is provided comprising a means for adjusting the angle of a horizontal surface with respect to a second horizontal surface; and wherein a pointing input device relies on an input surface for the purpose of calculating cursor position; and the input surface is physically supported by the first horizontal surface.

[0049] The means for adjusting the angle of the first horizontal surface with respect to the second horizontal surface may include computer software stored in a computer memory, and implemented by a computer processor.

[0050] The computer software stored in the computer memory, and implemented by the computer processor may provide suggested angle changes on the computer screen to improve input precision of the pointing input device.

[0051] The computer software stored in the computer memory may be configured to implement the suggested angle changes; and wherein after suggested angle changes are implemented with the first horizontal surface, the computer software stored in the computer memory, and implemented by the computer processor enables a user, through a user interactive device, to determine what affect the angle suggested changes had on accuracy of the pointing input device, through data displayed on the computer screen.

[0052] In at least one embodiment, an apparatus is provided comprising a means for adjusting the angle of a desk surface with respect to a horizontal surface; and wherein a pointing input device relies on an input surface for the purpose of calculating cursor position; and the desk surface physically supports the input surface.

[0053] The means for adjusting the angle of the desk surface with respect to the horizontal surface may include computer software stored in a computer memory, and implemented by a computer processor.

[0054] The computer software stored in the computer memory, and implemented by the computer processor may provide suggested angle changes on the computer screen to improve input precision of the pointing input device.

[0055] The computer software stored in the computer memory may be configured to implement the suggested angle changes with the desk surface; and wherein after suggested angle changes are implemented with the desk surface, the computer software stored in the computer memory, and implemented by the computer processor enables a user, through a user interactive device, to determine what affect the angle suggested changes had on accuracy of the pointing input device, through data displayed on the computer screen.

[0056] The computer software stored in the computer memory, and implemented by the computer processor may generate targets at different positions on the computer screen.

[0057] The computer software stored in the computer memory, and implemented by the computer processor may produce additional sensitivity settings for improving accuracy of the pointing input device by creating an additional modifier to act along with manufacturer pointing input device DPI settings and manufacturer in-application sensitivities.

[0058] The computer software stored in the computer memory, and implemented by the computer processor may use a range of computer software sensitivities and provide suggested angle changes on the computer screen to improve input precision of the pointing input device.

Description

BRIEF DESCRIPTION OF THE DRAWINGS

- [0059] FIG. **1** shows a simplified perspective view of an apparatus in accordance with an embodiment of the present invention;
- [0060] FIG. **2** shows a first flow chart of a first method for use with the apparatus of FIG. **1** in accordance with an embodiment of the present invention;
- [0061] FIG. **3**A shows a first part of a second flow chart for a second method for use with the apparatus of FIG. **1** in accordance with an embodiment of the present invention;
- [0062] FIG. **3**B shows a second part of the second flow chart for the second method for use with the apparatus of FIG. **1** in accordance with an embodiment of the present invention;
- [0063] FIG. **4** shows a third flow chart for a third method for use with the apparatus of FIG. **1** in accordance with an embodiment of the present invention;
- [0064] FIG. **5** is a simplified diagram of a layout of an apparatus in accordance with another embodiment of the present invention;
- [0065] FIG. **6** is a simplified diagram of a layout of an apparatus in accordance with yet another embodiment of the present invention;
- [0066] FIG. **7** is a simplified diagram of a layout of an apparatus in accordance with an additional embodiment of the present invention;
- [0067] FIG. **8** is a simplified diagram of a layout of an apparatus in accordance with a further embodiment of the present invention;
- [0068] FIG. **9** is a simplified diagram of a computer mouse, with means for adjusting an angle of the computer mouse with respect to a surface;
- [0069] FIG. **10** is a simplified diagram of a computer mouse with another means for indirectly adjusting the angle of the computer mouse with respect to a surface;
- [0070] FIG. **11** is a simplified diagram of a computer mouse with an additional means for indirectly adjusting the angle of the computer mouse with respect to a surface;
- [0071] FIG. **12** a flow chart of a calibration process in accordance with an embodiment of the present invention;
- [0072] FIG. **13** shows a simplified diagram of a computer mouse with a means for adjusting the angle of a user's wrist, hand, or one or more fingers with respect to a ground surface, a horizontal surface, and/or with respect to an arm of the user;
- [0073] FIG. **14**A shows a simplified diagram of a computer mouse with part of a human being's hand holding the mouse, and with a wrist and arm of the human being also being shown;
- [0074] FIG. **14**B shows a simplified diagram of the computer mouse of FIG. **14**A with part of the human being's hand holding the mouse, and with the wrist and the arm of the human being also being shown as in FIG. **14**A, but with the addition of a first means attached to the top of the computer mouse, which adjusts the angle of the hand, wrist, and/or one or more fingers of the hand with respect to a horizontal surface;
- [0075] FIG. **14**C shows a simplified diagram of the computer mouse of FIG. **14**A with part of the human being's hand holding the mouse, and with the wrist and the arm of the human being also being shown as in FIG. **14**A, but with the addition of a second means attached to the top of the computer mouse, which adjusts the angle of the hand, wrist, and/or one or more fingers of the hand with respect to a horizontal surface;
- [0076] FIG. **15**A shows a simplified diagram of a computer mouse with part of a human being's hand holding the mouse, and with a wrist and arm of the human being also being shown;
- [0077] FIG. **15**B shows a simplified diagram of the computer mouse of FIG. **15**A with part of the human being's hand holding the mouse, and with the wrist and the arm of the human being also being shown as in FIG. **15**A, but with the addition of a first means placed under the arm of the user

- which adjusts the angle of the arm with respect to a horizontal surface;
- [0078] FIG. **15**C shows a simplified diagram of the computer mouse of FIG. **15**A with part of the human being's hand holding the mouse, and with the wrist and the arm of the human being also being shown as in FIG. **15**A, but with the addition of a second means placed under the arm of the user which adjusts the angle of the arm with respect to a horizontal surface;
- [0079] FIG. **16**A shows a simplified diagram of a computer mouse with part of a human being's hand holding the mouse, and with a wrist and arm of the human being also being shown;
- [0080] FIG. **16**B shows a simplified diagram of the computer mouse of FIG. **16**A with part of the human being's hand holding the mouse, and with the wrist and the arm of the human being also being shown as in FIG. **16**A, but with the addition of a first means placed under the arm of the user which adjusts the angle of the arm with respect to a horizontal surface;
- [0081] FIG. **16**C shows a simplified diagram of the computer mouse of FIG. **16**A with part of the human being's hand holding the mouse, and with the wrist and the arm of the human being also being shown as in FIG. **16**A, but with the addition of a second means placed under the arm of the user which adjusts the angle of the arm with respect to a horizontal surface;
- [0082] FIG. **17**A shows a simplified diagram of a computer mouse with another means for adjusting the angle of the computer mouse with respect to a surface, wherein the means in FIG. **17**A is placed towards the outside of a member;
- [0083] FIG. **17**B shows a simplified diagram of a computer mouse with another means for adjusting the angle of the computer mouse with respect to a surface, wherein the means in FIG. **17**B is placed more towards the middle of a member, than in FIG. **17**A;
- [0084] FIG. **17**C shows a simplified diagram of a computer mouse with another means for adjusting the angle of the computer mouse with respect to a surface, wherein the means in FIG. **17**C is placed more towards the middle of a member, than in FIG. **17**A, and has a greater height than the mean in FIG. **17**B;
- [0085] FIG. **18**A is a simplified diagram of a computer mouse, with a first means of FIG. **18**A for adjusting an angle of the computer mouse with respect to a surface;
- [0086] FIG. **18**B is a simplified diagram of a computer mouse, with a second means of FIG. **18**B for adjusting an angle of the computer mouse with respect to a surface;
- [0087] FIG. **18**C is a simplified diagram of a computer mouse, with a second means of FIG. **18**C for adjusting an angle of the computer mouse with respect to a surface;
- [0088] FIG. **19**A is a simplified diagram of a computer mouse with a first means of FIG. **19**A for adjusting the angle of the computer mouse with respect to a surface;
- [0089] FIG. **19**B is a simplified diagram of a computer mouse with a second means of FIG. **19**B for adjusting the angle of the computer mouse with respect to a surface; and
- [0090] FIG. **19**C is a simplified diagram of a computer mouse with a third means of FIG. **19**C for adjusting the angle of the computer mouse with respect to a surface.

DETAILED DESCRIPTION OF THE DRAWINGS

- [0091] FIG. ${\bf 1}$ shows a simplified perspective view of an apparatus ${\bf 1}$ in accordance with an embodiment of the present invention.
- [0092] The apparatus **1** includes a computer **2**. The computer **2** typically includes at least a computer processor, computer memory, and one or more computer input/output ports for interacting with the internet and one or more peripheral devices. The computer **2** may be a personal computer.
- [0093] The apparatus **1** further includes a computer monitor **4**, a computer keyboard **6**, a computer mouse **8**, a table or supporting member **10**, a computer mousepad **12**, and a device **14**. The device **14** includes a flat or substantially flat member or plate **16**, having a top surface **16***a*, and support members **18**, **20**, **22**, and **24**, which are fixed beneath the member **16**, such as by fasteners, glue, or in any other known manner.
- [0094] The computer monitor **4**, the computer keyboard **6**, and the computer mouse **8** are

connected by communication links to the computer **2** and/or to a computer processor of the computer **2**, such as by wiring, wireless links or any other known communication links.

[0095] FIG. **2** shows a first flow chart **100** of a first method for use with the apparatus **1** of FIG. **1** in accordance with an embodiment of the present invention.

[0096] The first method of use shown by the first flow chart **100** includes step **102** where a mouse **8** provides one or more inputs, and step **104** an input surface **12** component provides one or more inputs to step **106**. The inputs provided to step **106** include six factors that can be adjusted to alter input device precision. The first method shown by flow chart **100** further includes step **108**, where mouse **8** precision, measurable as percentage of tracking accuracy is determined by the computer processor of the computer **2** and results are stored in computer memory of the computer **2**.

[0097] FIG. **3**A shows a first part **200***a* of a second flow chart for a second method for use with the apparatus **1** of FIG. **1** in accordance with an embodiment of the present invention.

[0098] The first part **200***a* includes step **202**, which is the start of the second method.

[0099] At step **204**, the user gathers information about the settings for the intended application, which is the software application that the user intends to improve tracking accuracy for. The user will retrieve the values for application sensitivity and field of view by checking the current values in the intended application. The user will also gather values for movement speed, pitch, yaw, and/or FOV sensitivity multiplier by reading through the application documentation, finding information about it on the software developer's website, or researching the topic on the internet.

[0100] At step **206**, the user will enter values into the calibrator for application sensitivity, field of view, and movement speed. If pitch, yaw, and/or FOV sensitivity multiplier are determined by the user to be relevant in the intended application, the user will also enter these values into the calibrator.

[0101] At step **208**, the user presses the Start Calibration button in the calibrator to begin the calibration process.

[0102] At step **210**, in the three dimensional (3D) calibration software space, the calibrator measures tracking accuracy by having the user move the mouse **8** and hold down the specified mouse button to fire on a small moving target at close range, attempting to overlap the close target with the cursor as consistently as possible. This interaction with the cursor and target is shown on the monitor **4**.

[0103] At step **212**, the calibrator increases or decreases application sensitivity during testing until best consistent tracking result is achieved. This process is described in FIG. **12**.

[0104] At step **214**, the calibrator displays the "close application sensitivity" value in the calibration software interface on the monitor **4**.

[0105] At step **216**, in the three dimensional (3D) calibration software space, the calibrator measures tracking accuracy by having the user move the mouse **8** and hold down the specified mouse button to fire on a small moving target at far range, attempting to overlap the close target with the cursor as consistently as possible. This interaction with the cursor and target is shown on the monitor **4**.

[0106] At step **218** the calibrator increases or decreases application sensitivity during testing until best consistent tracking result is achieved. This process is described in FIG. **12**.

[0107] At step **220**, the calibrator displays the "far application sensitivity" value in the calibration software interface on the monitor **4**.

[0108] At step **222**, the calibrator compares close application sensitivity value that was determined at step **214** to the far application sensitivity value that was determined at step **220**.

[0109] At step **224**, the calibrator determines which application sensitivity value is higher.

[0110] From step **224** to step **226**, the method of parts **200***a*-*b*, next starts with **200***b* part in FIG. **3**B.

[0111] At step **228**, it is determined, in one scenario, by computer processor of computer **2**, that close application sensitivity is higher than far application sensitivity and in this case, steps **230**,

232, **234**, and **248** are executed by computer processor of the computer **2**. At step **230**, the calibrator subtracts far application sensitivity from close application sensitivity, storing the difference in computer memory. This difference is then subtracted from the far application sensitivity to obtain the "approximate converged application sensitivity". At step **232**, the calibrator sets application sensitivity to match approximate converged application sensitivity. At step **234**, the user lowers front surface edge until tracking accuracy is consistent in 3D application at all ranges. At step **248**, if the front surface edge **12***a* reaches a point where it cannot be physically lowered any further before consistent accuracy is obtained, begin raising the rear surface edge **12***b* until accuracy becomes consistent at all ranges in the calibrator.

[0112] At step **236**, it is determined, in an alternative scenario, by computer processor of computer **2**, that far application sensitivity is higher than close application sensitivity and, in this case, steps **238**, **240**, **242**, and **246** are executed by the computer processor of the computer **2**. At step **238** the calibrator subtracts "close application sensitivity" from "Far application sensitivity", storing the difference in computer memory. This difference is then added to the far application sensitivity to obtain the "approximate converged application sensitivity". At step **240**, the calibrator sets application sensitivity to match approximate converged application sensitivity. At step **242**, the user raises front surface edge **12***a* until tracking accuracy is consistent in 3D application at all ranges. At step **246**, if the front surface edge **12***a* reaches a point where it cannot physically be raised any further before consistent accuracy is obtained, begin lowering the rear surface edge **12***b* until accuracy becomes consistent at all ranges in the calibrator.

[0113] At step **244**, it is determined, in an alternative scenario, that both eDPI values ("close application sensitivity" and "Far application sensitivity") are the same by the computer processor of the computer **2**.

[0114] In any of the three scenarios starting at steps **228**, **236**, and **244**, ultimately, step **250** will be executed. At step **250**, the maximum input precision at all ranges has been obtained, which can be confirmed by the user testing accuracy against targets at various ranges in the calibrator. In addition at step **250**, the input surface **16** is at an optimal angle, no further adjustments are needed.

[0115] At step **252** the method shown by parts **200***a* and **200***b*, is finished.

[0116] FIG. **4** shows a third flow chart **300** for a third method for use with the apparatus **1** of FIG. **1** in accordance with an embodiment of the present invention.

[0117] At step **302**, a user opens DPI tailor interface on the computer monitor **4**, typically by using a computer interactive device, such as one or more of computer keyboard **6** and/or computer mouse **8** shown in FIG. **1**, as programmed by computer software stored in computer memory of the computer **2**, and as implemented by a computer processor of the computer **2**.

[0118] At step **304**, the current/factory setting is displayed on the computer monitor or display **4**, as programmed by computer software stored in computer memory of the of the computer **2**, and as implemented by a computer processor of the computer **2**.

[0119] At step **306**, the user selects an "alteration modifier" by using an interactive device, such as one or more of computer keyboard **6** and/or computer mouse **8**, to select a field in the DPI tailor interface on computer monitor **4** and enter a numeric decimal value.

[0120] At step **308**, the "alteration modifier" times the "mouse DPI" is calculated by the computer processor of the computer **2** to determine the "tailored DPI" which is stored in computer memory of the computer **2**, as programmed by computer software stored in the computer memory of the computer **2** and as implemented by a computer processor of the computer **2**.

[0121] At step **310**, the "tailored DPI" multiplied by the "Application Sensitivity" would logically result in the "eDPI value". To assist in producing specific eDPI values, the DPI tailor interface would allow the user to input the application sensitivity of the intended application and would show a calculation for eDPI so that the user can see what the resultant logical eDPI value would be for any tailored DPI multiplied by whatever application sensitivity value is entered.

[0122] For the sake of brevity and easy understanding, any reference below to "adjusting input

surface angle" actually indicates that the angle A1 in FIG. 10 or A2 in FIG. 11, of the support structure or member 16 underneath the input surface or here mousepad 12 in FIG. 1, is being adjusted. Because the bottom surface of the input surface 12 sits on the surface 16a of the support structure 16, the top surface of the input surface 12 changes angle when the support structure 16 does.

[0123] Please note that the following descriptions will detail situations where a user would be using a mouse **8**, that does not have adjustable "forward to backward tilt" or "left to right tilt" options (just like in computer mice today, where these tilt options are not present) and how adjusting the angle of the input surface **12** (which in turn adjusts the angle of the mouse **8**) affects aim precision in the 3D space. Keep in mind that if the mouse **8** had adjustable "forward to backward tilt" or "left to right tilt" options, the input surface **16***a* of the member **16** could be left in a static position, the corresponding mouse **8** tilt adjustments could be made, and all of the results listed below would still take place.

[0124] It is imperative that the input surface **12** is consistently flat across the area that the mouse **8** is going to be moved across. Any bumps or dips in the input surface **12** will create inconsistency in aim precision. Also, the support structure **16** underneath the input surface **12** must be very rigid and sturdy so that neither the surface support **16** nor the input surface **12** can bow, flex, warp, or fold, which could be particularly likely to happen when the angle A1 in FIG. 10 or A2 in FIG. 11, is changed on a support structure that is not rigid and sturdy. These considerations make material composition choices of the support structure **16** and input surface **12** very important. [0125] Please note that there is not one single "perfect angle" of a mouse 8 that would be optimal for a user to use in all situations. In a given set of circumstances, when a change is made to mouse angle (such as swapping to a new mouse 8, or raising or lowering desk 10 height) or mouse/surface friction (by introducing or swapping out mousepads for input surface 12), the angle of the input surface 12 must be adjusted to compensate to correct aim precision. Once optimized, if any significant change is later made to the mouse angle (such as swapping to a new mouse 8, or raising or lowering desk **10** height) or mouse/surface friction (by introducing or swapping out mousepads for input surface **12**), the input surface angle A**1** in FIG. **10** need to be optimized again. [0126] (e) Fifth factor—Limitations of current mouse sensors, DPI settings, and in-application sensitivities. (Apparently unknown to industry)

[0127] This fifth factor relates directly to the second factor and also has a limiting effect of the accuracy that can be realized using the input surface calibration detailed in the description of one or more embodiments of the present invention for the fourth factor.

[0128] At the time of this filing, most modern mouse sensors are limited to DPI changes in increments of 50.0 or 100.0, and general consensus indicates that only DPI values between 400.0 and 1600.0 produce consistent tracking results. This limits DPI selection to 400.0, 450.0, 500.0, 550.0, 600.0, 650.0, 700.0, 750.0, 800.0, 850.0, 900.0, 950.0, 1000.0, 1050.0, 1100.0, 1150.0, 1200.0, 1250.0, 1300.0, 1350.0, 1400.0, 1450.0, 1500.0, 1550.0, or 1600.0.

[0129] Also most computer software is written so that the sensitivity multiplier can only handle two spaces after the decimal (e.g. a sensitivity of 2.36), though some can handle up to five or six spaces after the decimal (e.g. a sensitivity of 2.36653 or 2.366538).

[0130] Because both DPI and sensitivity choices are limited, only certain eDPI values are available for a user to use, even if using calculations to maximize the range of available eDPI options, including some that would be considered obscure to the average user.

[0131] For example [0132] a DPI of 800.0 and a sensitivity of 4.35 produces an eDPI value of 3480.0 [0133] a DPI of 550.0 and a sensitivity of 6.33 produces an eDPI value of 3481.5 [0134] a DPI of 900.0 and a sensitivity of 3.87 produces an eDPI value of 3483.0

[0135] Please note that there is no option to use an eDPI of 3481.0 or 3482.0, and there is also no current way to calculate a usable eDPI that is between 3480.0 and 3481.5. Once the input surface, such as input surface **12** of FIG. **1**, has been adjusted to a degree that tracking tests indicate that the

angle has been set properly, the user may find that 3480.0 is too low of an eDPI to be most accurate, and that 3481.5 is too high of an eDPI to be most accurate. In this instance, users currently have no way to adjust their eDPI to a value that is between 3480.0 and 3481.5. If it were possible to use eDPI settings that are not currently available, the user may find that the eDPI that would be needed for extremely precise aim could be approximately 3480.5, or they might determine that they need an even finer eDPI adjustment like 3480.55, or an even finer eDPI setting such as 3480.558 or 3480.5581354. Again, none of these eDPI settings are currently possible to use.

[0136] Because the importance of input surface angle was not previously known to the industry, it seems like mouse manufacturers currently don't believe that mouse sensors that can be adjusted in increments less than 50.0 would have any profound effect on input accuracy, and also a sensor with a 50.0 dpi increment limit is likely more cost effective to produce than one that could be adjusted in one degree increments (or even less). Considering the factor of input surface angle that one or more embodiments of the present invention resolves, and for the sake of accuracy that could be further optimized beyond what is possible today, new mouse sensors should be designed that are able to be adjusted in DPI increments of 0.00001 (or even less).

[0137] If this is not considered technically or financially feasible, computer software developers need to adopt a policy where sensitivity in applications will be always expressed and actioned well beyond the standard two decimal spaces. Currently, a sensitivity that functions to at least twenty decimal places would be desired.

[0138] (Please note that though the current application describes the calibration process as such that application sensitivity values are constantly being adjusted, if eDPI options with significantly more decimal places become available in the future, eDPI would be used instead of application sensitivity when completing calibration. This would allow for mouse accuracy to be fine-tuned to an even farther level than what is possible today.) [0139] (f) Sixth Factor—The height of the input surface 12 in relation to the user. (This factor does not appear to be known by the industry as having an effect on mouse 8 precision.)

[0140] This factor is classified as indirect, because if the current limitations of input sensor DPI increments and software sensitivity decimal value restrictions were removed, it may be possible that all of the first five factors could be adjusted to achieve aim precision on their own. In that scenario, any reasonable input surface height could be used.

[0141] The height of the Input surface 12 can be altered in a couple of ways. For example, an adjustable desk surface 10 could be raised, thus the input surface 12 that rests on it would move higher. Alternatively, if the support structure 14 underneath the input surface 12 had mechanisms to change height, these adjustments would also effectively alter the height of the input surface 12. [0142] As the input surface 12 is raised, from the user perspective, it will appear to gain friction. As it relates to aim precision, this gradual friction gain is more pronounced for tracking close range targets on the computer monitor 4 and is less pronounced for far range targets on the computer monitor 4. As the input surface 12 is raised, the eDPI values will need to be increased to compensate, and the close eDPI will need to increase in larger increments than the far eDPI as the input surface 12 continues to be raised. Generally speaking, for every 1.0 eDPI that the far range is increased, the close eDPI would need to be increased by approximately a value of 2.0, as the input surface 12 is raised. This two to one ratio is not exact, and appears to be affected by different friction levels for input surfaces as well as extremely low or high surface heights.

[0143] The following explains how the six elements of pointing input device precision interact with each other:

[0144] Without the use of one or more embodiments of the present invention, the friction encountered while moving the computer mouse **8** in FIG. **1**, across the input surface **12** will not be consistent. Even if the input surface **12**, the input surface support **16**, and the feet of the mouse **8** are all extremely flat and smooth, the user will still encounter constantly changing levels of friction

when moving the mouse **8** across the input surface **12**.

[0145] In at least one embodiment, examining the results of tracking accuracy is the most straightforward way to determine how much friction is being encountered when a user tracks a target. The eDPI values associated with a user's best tracking results for targets at different ranges give a clear indication of how much friction is being encountered when the user is moving the mouse **8** across the input surface **12**. The amount of friction encountered when accurately tracking a target at a specific range directly correlates to the eDPI that is required to overcome this friction. If accurately tracking a close range target requires a lower eDPI than accurately tracking a far range target, this indicates that less friction has been encountered when tracking the close range target compared to the far range target. If accurately tracking a close range target requires a higher eDPI than accurately tracking a far range target, this indicates that more friction has been encountered when tracking the close range target compared to the far range target compared to the far range target compared to the far range target.

[0146] As described previously, without the use of one or more embodiments of the present invention, it is possible to adjust mouse settings in such a way that the user will be able to maintain accurate tracking at a certain range, but will almost always find difficulty in producing a similar level of accuracy when tracking targets at any ranges that are significantly closer or farther away. This is because of the differing levels of friction encountered, and the different levels of eDPI that would be needed to overcome each level of friction. In software applications currently, there is only one eDPI value that exists in a program at any specific moment in time, and that value is equal to the multiplicative product of the mouse DPI value and the application sensitivity.

[0147] Without the use of one or more embodiments of the present invention, a user must set the mouse DPI and application sensitivity so that the resultant eDPI value is optimized for accuracy at a certain range, and then the user will have to intentionally and consciously increase or decrease the amount of mouse travel distance on the input surface when tracking targets at any other ranges in an attempt to maintain consistent accuracy. Because of the level of concentration and discipline required from the user to maintain the wide range of ever-changing mouse movement patterns, having highly accurate results using this method over a long duration are generally not sustainable. In an attempt to get around friction inconsistencies, some users will wear gloves or sleeves made of low friction material to situationally assist with friction inconsistencies when making long distance movements of the mouse 8, but these products produce mixed results at best. Before the creation of one or more embodiment of the current invention, there was no way to effectively overcome the inherent friction inconsistencies encountered.

[0148] To move a mouse **8** across an input surface **12**, the user applies force to the mouse **8**. The inconsistency of friction that the user will encounter when moving the mouse **8** is caused by differences in how this force is distributed between the mouse **8** and the input surface **12** as the mouse 8 moves closer to or farther away from the user on the input surface 12, and these differences are affected by a number of relevant physical angles. The angle of the input surface support **16**, the angle of the input surface **12**, the angle of the mouse **8**, the angle of the hand of the user as the user's hand grips the mouse **8**, and the angle of the wrist of the user, with respect to the horizontal desk surface 10, with respect to some other horizontal surface, with respect to a ground surface, or with respect to some part of a user's body, all affect the level of friction felt when the mouse **8** is moved. (Regarding all of the angles that factor into friction, determining which angles produce more or less friction in any given situation is beyond the scope of this documentation.) [0149] In a given set of conditions, many of these angles cannot reasonably be changed to any significant degree. A desk chair with a wide range of adjustable height settings is still functionally limited to a height range totaling only a few inches that would be comfortable for any specific user. Setting the chair higher or lower than this range will produce discomfort or pain for the user almost immediately. Most desks do not have height adjustment capabilities, but even those that do currently lack the ability to make minute adjustments to the height, and the difference between the highest and lowest height settings are generally less than 12.0 total inches. Even within this 12.0

inch range, the user will probably find that the top half of this range is unusable from a seated position because it makes the user's wrist or arm uncomfortable.

[0150] With a particular computer mouse at a particular desk height, a user will find that there is functionally only a very small range of angles (likely all within one degree) for the positioning of the hand and wrist that is comfortable and also produces the result of a high level of accuracy for that particular user. Without the use of the present invention, at a particular desk height, there is generally no reasonable way to adjust the angle of the input surface support or the input surface. [0151] The main goal of this invention is to adjust one or more of the angles that can reasonably be changed by the user, overcoming the limitations that occur from the combination of all of the other relevant angles that cannot reasonably be changed, for the sake of producing the highest tracking accuracy results possible. This goal is considered to be met when the eDPI required to track targets at a vast array of ranges (or optimally, all ranges) is found to be the same throughout those ranges. This indicates that the relevant modifiable angles have been adjusted in such a way that the friction encountered while moving a mouse across an input surface is consistent across that input surface. [0152] Please note that once this consistency has been obtained, if any of the previously mentioned angles are changed, such as from changing to a new mouse (which would change the hand and/or wrist angle), or from the user intentionally attempting to use a different wrist angle, or from the user previously sitting but now standing (which would change the hand and/or wrist angle), or from the desk height changing (which would change the hand and/or wrist angle), this newfound consistency will cease to exist, and the calibration process will need to be completed again to create friction consistency under the new conditions.

[0153] Please note that changing the height position of any of the previously mentioned elements (such as the pointing input device **8**, input surface **12**, input surface support **16**, desk surface **10**, user's arm, or user's hand) in relation to any of the other elements also effectively changes the angle between these elements.

Possible Limitation Workarounds

[0154] As previously detailed, the current state of mouse sensor DPI increments and software sensitivity decimal point values only allows certain eDPI values to be calculated. If software were developed that could operate as an additional multiplier in the eDPI calculation, it would allow for significantly more eDPI values than what is currently possible. No software like this appears to exist today. The present invention in one or more embodiments discloses methods including computer software which will be referred to as "DPI tailor".

[0155] In at least one embodiment of the present invention, the DPI tailor takes the form of an application that runs in the background, or firmware that exists in the mouse **8**. When the user opens the DPI tailor interface, using the computer **2** on the monitor **4**, the current mouse DPI setting is displayed. The user types in or chooses an "alteration modifier", which is then multiplied to the mouse DPI to produce a "tailored DPI". This tailored DPI would then be multiplied to application sensitivity to produce the eDPI value.

[0156] As detailed in a previous section, though today eDPI values of 3480.0 and 3481.5 can be logically calculated, no eDPI value between these numbers can be, including 3481.0. If the DPI tailor were designed to allow alteration modifiers that were valid to at least twenty decimal places, a significant number of new possible eDPI values between 3480.0 and 3481.5 could be achieved and easily calculated by a user. [0157] Using an input DPI of 1000.0 with an alteration modifier of 3.48075 creates a tailored DPI of 3480.75. If an application sensitivity of 1.0 is used, it results in an eDPI of 3480.8125 [0158] Using an input DPI of 1000.0 with an alteration modifier of 3.4808125 creates a tailored DPI of 3480.8125. If an application sensitivity of 1.0 is used, it results in an eDPI of 3480.8125 [0159] Using an input DPI of 1000.0 with an alteration modifier of 3.480875 creates a tailored DPI of 3480.875. If an application sensitivity of 1.0 is used, it results in an eDPI of 3480.875 [0160] Using an input DPI of 1000.0 with an alteration modifier of 3.4809375 creates a tailored DPI of 3480.9375. If an application sensitivity of 1.0 is used, it results in an eDPI of

3480.9375 [0161] Using an input DPI of 1000.0 with an alteration modifier of 3.481 creates a tailored DPI of 3481.0. If an application sensitivity of 1.0 is used, it results in an eDPI of 3481.0 [0162] Please note that though setting the alteration modifier in the DPI tailor software has been described as a manual process that the user completes, this could also be done automatically by the calibrator software. Having alteration modifiers set and adjusted automatically during the calibration process would be much preferred to the user having to make multiple small adjustments to the values.

[0163] Instead of DPI tailor software, adjustments to input surface **12** height can situationally be used as a workaround to achieve a higher degree of aim precision than what would otherwise be possible.

[0164] For a given set of circumstances, once an optimal surface angle is achieved, if it is determined that the eDPI value that needs to be used is one that is impossible to be calculated (because of current mouse sensor DPI increments and software sensitivity decimal point restrictions), the user could attempt a workaround by setting the closest valid eDPI value, and then altering input surface height. This process would involve continuing to adjust the surface height and surface angle until a height/angle combination is found that results in the most precise aim. [0165] Most users will probably find that this process is too manual, and takes too long to complete, so the calibrator software should be used to assist in determining combinations that produce the most optimal tracking accuracy.

[0166] In at least one embodiment of the present invention, the member **16** of the device **14** may be a thin rigid board made of metal, tempered glass, or some similar material (which would be placed on table/desk surface **10**) that has small boxes **18**, **20**, **22**, and **24** on each of its four corners, as shown in FIG. **1**. The boxes **18**, **20**, **22**, and **24** may contain plastic shim wedges and motors that would move them according to how the computer software directed them. In at least one embodiment, the boxes **18**, **20**, **22**, and **24** are connected to each other with a wire under the board **16**, and are connected to the computer **2** and powered with a USB cable. There is an input surface **12**, which is made from a premium material such as textured leather or rubber, attached to the board **16**.

[0167] In at least one embodiment, as shown in FIG. 7, wedges **608** and **618** may be provided that go underneath input surface support **606** to adjust angle of input surface **616**.

[0168] In another embodiment, wedges (not shown) may go under the table/desk support structure **10** to adjust angle of table/desk surface **10**.

[0169] In at least one embodiment of the present invention, as shown in FIG. **8**, thin stackable shims **708** and **718** go underneath input surface support **706** to adjust angle of input surface **716**. These may be made of paper, plastic, thin rigid metal, or similar materials.

[0170] In at least one embodiment of the present invention, as shown in FIG. **9**, thin stackable shims **804** go underneath and attach to the mouse **802** to adjust the front to back height angle of the mouse. These would be made of plastic.

[0171] FIG. **13** shows a diagram **1200** of a computer mouse **1202** (which may be identical to mouse **8** of FIG. **1**) having a top surface **1202***b* and a bottom surface **1202***a*. The bottom surface **1202***a* of the mouse **1202** sits on a horizontal surface **1212**, which sits on a horizontal surface **1214**. The horizontal surfaces **1212** and **1214** may sit on a horizontal ground surface, not shown. FIG. **13** also shows a hand **1210**, with an index finger **1210***a* and a thumb **1210***b* shown. The hand **1210** is connected to a wrist **1211**.

[0172] In at least one embodiment of the present invention, as shown in diagram **1200** in FIG. **13**, thin stackable shims **1204** and **1206** have been attached to the top surface **1202***b* of a mouse **1202**, such as by adhesive to help adjust a hand or wrist angle A**3** that the user would use when gripping the mouse **1202**. The shims **1204** and **1206** may be made of plastic. In the example of FIG. **13**, the wrist angle A**3**, is presumed to be the angle between a line L**1** and a horizontal surface, such as one of surfaces **1212** and **1214**, or a horizontal ground surface. In this example, L**1** is a line which may

- divide the mass of a hand **1210** in half, with half of the mass of the hand **1210** being above line L**1** and half of the mass of hand **1210** being below the line L**1**.
- [0173] In at least one embodiment, a mouse **8** with adjustable height/tilt functions (not shown) is provided. The top shell and bottom shell are connected with an adjustable segment, allowing adjustable height and tilt positions for the top of the mouse.
- [0174] In at least one embodiment, sturdy poles (not shown) go underneath desk/table surface **10**, with manual or automatic adjustments to extend or contract the poles to allow the front or back of the desk/table **10** to be raised in small increments.
- [0175] In at least one embodiment, a small table (not shown) with angle/height adjustments for height/angle of the table surface.
- [0176] In at least one embodiment, a desk (not shown) with angle/height adjustments for height/angle of the desk surface.
- [0177] FIG. **5** is a simplified diagram of a layout **400** of an apparatus in accordance with another embodiment of the present invention.
- [0178] In at least one embodiment, a tempered glass plate, not shown, would sit over what is pictured, i.e., in one example, overlapping the exact outline the entire rectangular shape **402** of the layout **400** of FIG. **5**.
- [0179] The input surface (i.e. the mousepad, not shown) would sit on the center of the glass plate. The layout shows a dotted line **406**, which indicates the center of the input surface support, underneath the rectangular shape **402**. There are small platforms **410**, **412**, and **414** on each of three grids **402***a*, **402***b*, and **402***c*, respectively, and height shims, (not shown, made of paper, plastic, thin rigid metal, or similar materials) would sit on the platforms **410**, **412**, and/or **414** or be built directly into the platforms **410**, **412**, and **414**. For the purposes of this explanation, any further reference to a platform indicates that a shim is built into it, or a shim is present on the platform. One or more motors, not shown, would move these platforms **410**, **412**, and **414** along the X and Y axis, with respect to rectangular shape **402**. The optimal positions for the platforms **410**, **412**, and **414** would be determined by the results of the calibrator.
- [0180] FIG. **6** is a simplified diagram of a layout **500** of an apparatus in accordance with another embodiment of the present invention. In at least one embodiment, a tempered glass plate, not shown, would sit over what is pictured, i.e., in one example, overlapping the exact outline the entire rectangular shape **502** of the layout **500** of FIG. **6**.
- [0181] The input surface (i.e. the mousepad, not shown) would sit on the center of the glass plate. The layout shows a dotted line **506**, which indicates the center of the input surface support, underneath the rectangular shape **502**. There are small platforms **510**, **512**, and **514** on each of three grids **502***a*, **502***b*, and **502***c*, respectively, and height shims, (not shown, made of paper, plastic, thin rigid metal, or similar materials) would sit on the platforms **510**, **512**, and/or **514** or be built directly into the platforms **510**, **512**, and **514**. For the purposes of this explanation, any further reference to a platform indicates that a shim is built into it, or a shim is present on the platform. One or more motors, not shown, would move these platforms **510**, **512**, and **514** along the X and Y axis, with respect to rectangular shape **502**. The optimal positions for the platforms **510**, **512**, and **514** would be determined by the results of the calibrator.
- [0182] The position of platforms **410**, **412**, and **414** for FIG. **5**, or platforms **510**, **512**, and **514** for FIG. **6** has a significant effect on the tilt of the input surface support, and the presence of the innermost platform also acts as a stabilizer to reduce any flex that input surface support has. In FIG. **5**, the innermost platform is platform **412**. In FIG. **6**, the innermost platform is platform is platform **512**. (On its own, tempered glass often has a significant amount of flex when pressure is applied to it.)
- [0183] Once a calibrator stored in computer memory of computer **2** and executed by a computer processor of computer **2**, begins its process, the platform (such as platform **412** or **512**) is moved first to make rough changes to the angle of the input surface. Please note that platforms **410**, **412**,

and **414** in FIG. **5** are identical to the platforms **510**, **512**, and **514** in FIG. **6**, other than the position location of each platform. Platforms **410**, **412**, and **414** are closest to the front surface edge **416**, while platforms **510**, **512**, and **514** are closest to the rear surface edge **518**. The movement adjustments of the platform (such as platform **412** and **512**) is configured to be small, and is typically measured in increments less than a millimeter.

[0184] While platform **412** or **512**, for example, is being moved, the calibrator of computer **2**, determines whether each platform movement has resulted in the tracking accuracy percentage increasing or decreasing. The platform repositioning will continue, as executed by the computer **2**, until the tracking precision reaches the highest percentage of accuracy recorded during the calibration process. At this point, the calibrator returns the platform **412** or **512** to the position that produced the highest tracking accuracy percentage and then stops the movement of platform **412** or **512**.

[0185] The positions of the outermost platforms (platforms **410** and **414** in FIG. **5** and platforms **510** and **514** in FIG. **6**) control the fine tuning of the angle of the input surface **402**.

[0186] Once platform **412** or **512** has been moved to what has been determined to be the optimal position, platforms **410** and **414** or **510** and **514** will alternate being moved into various positions on the X and Y axis. The platforms **410** and **414** or **510** and **514** movement adjustments will be small, and typically is measurable in increments less than a millimeter.

[0187] After platforms **410** and **414** or **510** and **514** are moved, the calibrator of the computer **2**, is programmed to determine whether each platform movement of platforms **410** and **414** or **510** and **514** has made the tracking precision better or worse after the user fires on the target indicated. While platforms **410** and **414** or **510** and **514** are being moved in a particular direction, as long as the tracking results stay similar or improve, the particular platform of platforms **410** and **414** or **510** and **514**, will continue to move in the same direction. At some point during this movement, the tracking result will worsen. Once this occurs, that platform of platforms **410** and **414** and **510** and **514** will be moved back into the position that resulted in the highest tracking accuracy. [0188] The platform repositioning will continue, as programmed by computer software in the

[0188] The platform repositioning will continue, as programmed by computer software in the computer **2**, until the tracking precision reaches the highest percentage of accuracy recorded during the calibration process. At this point, the calibrator will stop the platform movement, and display to the user on computer monitor **4** that the calibration process has been completed.

[0189] When the three platforms **410**, **412** and **414** of FIG. **5** or **510**, **512**, and **514** of FIG. **6** are positioned closest to the input surface support front edge **416** and **516** (as shown in FIG. **5**) and the platforms **410**, **412**, and **414** or **510**, **512**, and **514**, are moving towards the center of the input surface support **402** or **502**, this is known as "raising the front surface edge"

[0190] When the three platforms **410**, **412**, and **414** of FIG. **5** or **510**, **512**, and **514** of FIG. **6** are positioned closest to the input surface support front edge **416** and **516** (as shown in FIG. **5**) and the platforms **410**, **412**, and **414** or **510**, **512**, and **514** are moving away from the center of the input surface support, this is known as "lowering the front surface edge".

[0191] When the three platforms **410**, **412**, and **414** or **510**, **512**, and **514** are positioned closest to the input surface support rear edge **418** and **518** (as shown in FIG. **6**), and the platforms are moving towards the center of the input surface support, this is known as "raising the rear surface edge". [0192] When the three platforms **410**, **412**, and **414**, or **510**, **512**, and **514** are positioned closest to the input surface support rear edge **418** and **518** (as shown in FIG. **6**), and the platforms **410**, **412**, and **414** or **510**, **512**, and **514** are moving away from the center of the input surface support **402** or **502**, this is known as "lowering the rear surface edge".

[0193] FIG. **7** is a simplified diagram of a layout of an apparatus **600** in accordance with an additional embodiment of the present invention. The apparatus **600** includes wedges **608** and **618** that are configured to be moved underneath the input surface support **606**. The mouse **604** rests on the input surface **616**, which rests on the input surface support **606**. The apparatus **600** may include one or more rubber bumpers **610** to help prevent the input surface support **606** from sliding around

when elevated above the surface of the desk **612**. Movement adjustments to the wedges **608** and **618** will raise or lower the input surface support, which will cause changes to input precision of the mouse **604**.

[0194] FIG. **8** is a simplified diagram of a layout of an apparatus **700** in accordance with an additional embodiment of the present invention. The apparatus **700** includes the stackable shims **708** and **718** that are configured to be moved underneath the input surface support **706**. The mouse **704** rests on the input surface **716**, which rests on the input surface support **706**. The apparatus **700** may include one or more rubber bumpers **710** to help prevent the input surface support **706** from sliding around when elevated above the surface of the desk **712**. Movement adjustments to the stackable shims **708** and **718** will raise or lower the input surface support, which will cause changes to input precision of the mouse **704**.

[0195] FIG. **9** is a simplified diagram of an apparatus **800** including a computer mouse **802**, with means for adjusting an angle of the computer mouse **802** with respect to a surface. The apparatus **800** includes shims **804** that attach to the mouse **802** to adjust its height angle. The mouse **802** rests on an input surface **806** which rests on the desk **808**.

[0196] FIG. **10** is a simplified diagram of an apparatus **900** including a computer mouse **902**, with means for directly adjusting the angle of an input surface support **906** with respect to a surface and indirectly adjusting an angle of the computer mouse **902** with respect to a surface. The apparatus **900** may include a mouse **902**, an input surface **904**, an input surface support **906**, rubber bumpers **908** and **914**, a shim **912**, and a desk surface **910**. The mouse **902** is shown at an angle of A1 with respect to a surface.

[0197] FIG. **10** shows the angle of an input surface support **906** (as it relates to a horizontal surface) with the use of the shim **912**. Please note that though not explicitly shown as such in the images, this input surface support angle could also be expressed as being in relation to the desk **910**, the ground surface, some other horizontal surface, or some part of the user's body.

[0198] FIG. **11** is a simplified diagram of an apparatus **1000** including a computer mouse **1002** with an additional means for directly adjusting the angle of an input surface support **1006** with respect to a surface and indirectly adjusting the angle of the computer mouse **1002** with respect to a surface. The apparatus **1000** may include a mouse **1002**, an input surface **1004**, an input surface support **1006**, rubber bumpers **1008** and **1014**, a shim **1010**, and a desk surface **1012**. The mouse **1002** is shown at an angle of **A2** with respect to a surface.

[0199] FIG. **11** shows the angle of an input surface support **1006** (as it relates to a horizontal surface) with the use of the shim **1010**. Please note that though not explicitly shown as such in the images, this input surface support angle could also be expressed as being in relation to the desk **1012**, the ground surface, some other horizontal surface, or some part of the user's body. Also note that the angle in FIG. **10** is larger than the angle in FIG. **11**.

[0200] FIG. **12** a flow chart **1100** of a calibration process in accordance with an embodiment of the present invention.

[0201] The process of FIG. **12** starts at step **1102**. Next, the calibrator, at step **1104** which may be implemented through computer software stored in computer memory of computer **2**, and executed by a computer processor of computer **2**, is programmed by the computer software on computer **2** to indicate which target to fire upon, by providing information, such as through displaying on a computer monitor **4**.

[0202] Then, at step **1106**, during testing duration, a user fires on a target, using a pointing input device, such as a computer mouse **8**, and optionally using another input such as a keyboard **6** for avatar movement, while the calibrator computer software on the computer **2** measures accuracy percentage.

[0203] The flow continues at step **1108** where the calibrator lowers application sensitivity one increment, and stored this sensitivity in computer memory of computer **2**, and then instructs the user, such as through display on the computer monitor **4**, to begin firing on a target again for

another testing duration.

[0204] Next, at step **1110**, the calibrator compares the accuracy of both testing durations. The calibrator determines whether the accuracy improved in the latest duration.

[0205] If the accuracy increased during the latest duration, then step **1112** is executed, and then step **1116**. At step **1116**, the calibrator lowers application sensitivity one increment, in computer memory of computer **2**, and then instructs the user (such as visually through display on computer monitor **4** or through an audio message through a speaker), to begin firing on target for another testing duration. Following step **1116**, the calibrator compares accuracy of last two testing durations at step **1120**. If the accuracy percentage increased, then step **1122** is executed and then step **1116** is executed in a loop until the accuracy percentage is decreased as shown at step **1128**. [0206] If the accuracy percentage was decreased at step **1110**, then steps **1114** and **1118** are

[0206] If the accuracy percentage was decreased at step **1110**, then steps **1114** and **1118** are executed. At step **1118**, the calibrator raises application sensitivity one increment, in computer memory of computer **2**, and then instructs the user (such as visually through display on computer monitor **4** or through an audio message through a speaker) to begin firing on target for another testing duration. At step **1124**, the calibrator compares accuracy of the last two testing durations. If the accuracy percentage increased, then step **1126** is executed and then step **1118** is executed in a loop until the accuracy percentage is decreased as shown at step **1130**.

[0207] After the accuracy percentage has been decreased at either steps **1128** or **1130**, step **1132** is executed. At step **1132**, of the previous two testing durations, the calibrator displays on the computer monitor the sensitivity of the earlier duration. In at least one embodiment, this is the most optimal sensitivity for targets at the current range (stored in computer memory). At step **1134**, the calibrator process is finished.

[0208] When a computer mouse, such as any of computer mice **8**, **604**, **704**, **802**, **902**, or **1002** is being used, there are certain physical elements that are generally present. The computer mouse rests on an input surface (e.g. a mousepad), such as any of **12**, **616**, **716**, **806**, **904**, **1004**, which in turn rests on an "input surface support", such as any of **16**, **606**, **706**, **808**, **906** or **1006**. [0209] Though a desk **10** or table is generally used as the input surface support, the present application will assume that the input surface support is a thin rigid board made of tempered glass that will be present between the desk **10** and the mousepad **12**. As compared to a desk **10** or table, the glass board **16** would require less effort to make angle adjustments to and will closely resemble the standard implementation of the present invention.

[0210] By adjusting the angle of the input surface support **16** that the input surface **12** either rests on or is attached to, the angle of the input surface **12** changes accordingly. In turn, as the angle of the input surface **12** that the mouse **8** rests and moves on changes, the height angle of the mouse **8** changes accordingly. Adjusting these angles to find those that are most optimal, without the aid of additional software, is very difficult and time consuming. Considering this, calibration software should be relied upon to speed up the process and ensure that all angles are set to achieve the maximum potential accuracy.

[0211] The calibration software (hereby known as "the calibrator") in at least one embodiment, contains many settings that will need to be adjusted so that the calibration environment matches whatever application that the user is trying to optimize aim for (hereby known as "the intended application") as closely as possible. These settings include application sensitivity, field of view, and in some applications will also include pitch, yaw, and FOV sensitivity multiplier. Whenever the user needs to determine whether any of these settings are relevant for a specific intended application, it will require the user to look through the application documentation, find information about it on the software developer's website, or research the topic on the internet. In these instances, for the sake of brevity, any further mention of this requirement will be noted only as "will require the user to research."

[0212] There would be many benefits for presets for popular applications to be available in the calibrator, so that the user can just select the intended application from the list, and the relevant

settings would be set or presented for adjustment. This would remove the research requirements previously mentioned. To make this option possible, the software developer would need to continuously update the software, adding presets for any new popular application that is released. [0213] In at least one embodiment, to begin calibration, the user opens the calibrator computer software on a user computer and adjusts settings for both field-of-view ("FOV") and the application sensitivity multiplier. If, for example, the intended application has a field-of-view of 103.0 and a sensitivity of 4.0, then both of these values should be entered in for the settings of the same name in the calibrator. (The field-of-view setting defines how much of the software environment is being generated on the computer monitor **4** or screen. Setting a smaller value in field-of-view would produce an effect similar to "being zoomed in" constantly, while each increment added to this value would be like slightly "zooming out" the view.) The user should adjust movement speed settings in the calibrator to mimic the intended application so that aiming while moving in the calibrator is similar to the intended application. During the calibration process, if the user does not move an avatar or uses different movement speed settings than the intended application, aim precision in the intended application may not be as optimized as it would be if the movement in the calibrator were set to mirror that of the intended application. [0214] For many applications no other settings will need to be modified, but for some others, additional modifiers would need to be accounted for. The additional settings are pitch, yaw, and

FOV sensitivity multiplier. Determining whether an application needs these other settings to be accounted for will require the user to research.

[0215] In the applications that use them, pitch and/or yaw act as additional multipliers to application sensitivity. Pitch is a multiplier applied to vertical sensitivity, and yaw is a multiplier applied to horizontal sensitivity. For example, with a DPI of 800.0, an application sensitivity of 7.0 (which creates an eDPI of 5600.0), if the pitch were set as 0.522 and the yaw were set as 0.5625, the total vertical eDPI would be 2923.2 (800×7.0×0.522=2923.2) and the total horizontal eDPI would be 3150.0 (800.0×7.0×0.5625=3150.0).

[0216] In the applications that use FOV as a modifier to application sensitivity, pitch and yaw values are generally hidden and cannot be modified directly. Making adjustments to the FOV value adjusts pitch and yaw values. If the POV values are increased, the pitch and yaw values both increase accordingly. If the POV values decrease, the pitch and yaw values both decrease accordingly. For each application, determining which FOV values correspond with which pitch and yaw values will require the user to research. For applications that use an FOV sensitivity modifier, once the values relevant to the intended application have been gathered, the user would enable an option present in the calibrator to apply the POV multiplier to the application sensitivity. The user would then input the relevant POV value.

[0217] Once all previously described settings have been adjusted, the user presses the "Start Calibration" button, which begins the process at step **1102**, as shown in FIG. **12**. In the calibrator, a 3D environment will appear on the computer monitor, such as computer monitor 4 in FIG. 1, that will (at a minimum) contain two targets, a background or floor to help convey a sense of threedimensional depth, and nothing else. In this case, one target would appear to be at close range of an avatar, and the other target would be at far range from the avatar. Both targets would move around independently of each other and would occasionally change directions. The user would be instructed to press and hold a specific button on the mouse **8** (hereby known as "hold down the fire button") and begin tracking the close range target. The user would track this first target for a short amount of time (hereby known as the "testing duration", for the purposes of this example, we will assume each duration lasts for approximately 15.0 seconds), and during this period, the calibrator would internally monitor and calculate the accuracy percentage of the user's tracking attempt at step **1106** shown in FIG. **12**.

[0218] Once the testing duration has expired, the calibrator would momentarily halt monitoring accuracy and will automatically lower the sensitivity setting, at step 1108, in the calibration

software by a small increment. For the purposes of this example, we will assume that the initial mouse DPI was 800.0, and that the user had originally set the sensitivity in the calibrator to 4.0, which gives us an eDPI of 3200.0. Now that the calibrator is lowering the sensitivity, the sensitivity would change to 3.99 (which would give us an eDPI **3192**). Once this has been done, the calibrator resumes monitoring of the tracking accuracy of the user. The user would track the first target again while holding down the fire button, and during this, the calibrator would internally monitor and calculate the accuracy percentage of the user's tracking attempt.

[0219] Once the testing duration has expired, the calibrator would momentarily halt monitoring accuracy, and the calibrator would determine whether the tracking was more accurate at the initial sensitivity value (4.0) or at the first lowered increment sensitivity value (3.99) at step **1110** of FIG. **12**. If the lower sensitivity were more accurate, the calibrator sets the sensitivity another increment lower to 3.98, at step **1116** of FIG. **12**, and the testing would begin again. The calibrator would then compare the accuracy of testing with the new sensitivity setting (3.98) to the accuracy at the most recent sensitivity setting (3.99) at step **1120** of FIG. **12**, and if the accuracy percentage had improved, the calibrator would automatically set the sensitivity another increment lower to 3.97 at step **1116**, and the testing would begin again at step **1120**. This would continue until the testing results indicate that the accuracy percentage had worsened when compared to the test just before it, at step **1128** of FIG. **12**.

[0220] If accuracy had improved at every incremental reduction of sensitivity setting from 4.0 to 3.91, but the accuracy percentage had decreased, once the sensitivity setting was reduced further to 3.90, the calibrator would adjust the sensitivity setting back to where it had been the most accurate, 3.91 sensitivity, at step **1132** of FIG. **12**, (which results in an eDPI of 3128.0). The calibrator would then display the current most optimal tested sensitivity value for the close target (3.91) as text, labeled "close application sensitivity".

[0221] Please note that at the original sensitivity comparison for close range targets at 4.0 and 3.99, if the higher sensitivity had been more accurate at step **1114** of FIG. **12**, the calibrator would have then set the sensitivity one increment higher at step **1118** (instead of in the previous case, where it was set lower) than the initial sensitivity (to 4.01) and the testing would have begun again at step **1124**. This calibrator would have continued adjusting the sensitivity setting higher until the testing results would indicate that the accuracy percentage had worsened when compared to the test just before it, at step **1130** of FIG. **12**. If accuracy had improved on the close range target at every incremental sensitivity setting from 4.0 to 4.09, but the accuracy percentage had decreased once the sensitivity setting was increased further to 4.10, the calibrator would adjust the sensitivity setting back to where it had been the most accurate, 4.09.

[0222] In summary, when the calibrator compared the tracking accuracy at the two original sensitivity values of 4.0 and 3.99, it would determine if the higher or lower sensitivity value had produced the better result. If the higher value had been better, the calibrator would have then continued raising the sensitivity between testing durations, but if the lower value had been better, it would have instead continued lowering the sensitivity between testing durations. The calibrator would have continued doing this until it had determined that the accuracy values had begun to worsen. It would have then set the close application sensitivity to whatever sensitivity value that had produced the highest measured accuracy.

[0223] Now that the close application sensitivity value has been determined at step **1132** of FIG. **12**, the sensitivity setting in the calibrator would temporarily remain at this current most optimal tested sensitivity value (3.91), and the user would be instructed (such as visually through computer monitor **4** or through an audio message, to hold down the fire button and begin tracking the far range target. The user would track this second target for the testing duration, and the calibrator would internally monitor and calculate the accuracy percentage of the user's tracking attempt. The calibrator would then lower the sensitivity setting one increment (3.90) and the tracking on the far range target would begin again for the testing duration. Once the testing duration expires, the

calibrator would compare the tracking accuracy between the two sensitivity values that were used for the far range target (3.91 and 3.90).

[0224] If the lower sensitivity setting (3.90) produced the best accuracy percentage, the calibrator would lower the sensitivity again and then test tracking. These two steps would continue to be done until the calibrator determines that lowering the sensitivity worsens tracking accuracy. When this happens, the calibrator would adjust the sensitivity setting back to where it had been the most accurate. For this example, we will say that optimal accuracy for the far range target was determined to be 3.78 sensitivity (resulting in an eDPI of 3024.0). The calibrator would then display the current most optimal tested sensitivity value for the far target (3.78) as text, labeled "far application sensitivity".

[0225] (Please note that at the original sensitivity comparison for far range targets at 3.90 and 3.91, if the higher sensitivity had been more accurate, the calibrator would have set the sensitivity one increment above the highest of the two far application sensitivity settings being tested (to 3.92) and the testing would have begun again. This calibrator would have continued to adjust the sensitivity setting higher until the testing results would indicate that the accuracy percentage had worsened when compared to the test just before it. If accuracy had improved on the far range target at every incremental sensitivity setting from 3.91 to 4.19, but the accuracy percentage had decreased at 4.20, the calibrator would adjust the sensitivity setting back to where it had been the most accurate, 4.19.)

[0226] The calibrator would now compare the close application sensitivity and the far application sensitivity to determine the "approximate converged sensitivity". If the close application sensitivity value is greater than the far application sensitivity value, then the far application sensitivity value is subtracted from the close application sensitivity value. The resulting difference is then subtracted from the far application sensitivity value to obtain the approximate converged sensitivity value. For example, if the close application sensitivity value is 3.75 and the far application sensitivity value is 3.47, the difference is 0.28. This difference subtracted from the far application sensitivity value of 3.47 would produce a value of 3.19. This means that the approximate converged sensitivity value is 3.19.

[0227] If the comparison of the close application sensitivity value and the far application sensitivity value had resulted in a far application sensitivity value that was greater than the close application sensitivity value, then instead the close application sensitivity value would be subtracted from the far application sensitivity value. The resulting difference would then be added to the far application sensitivity value to obtain the approximate converged sensitivity value. For example, if the close application sensitivity value is 3.57, the difference is 0.22. This difference added to the close application sensitivity value of 3.57 would produce a value of 3.79. This means that the approximate converged sensitivity value is 3.79. [0228] If the comparison of the close application sensitivity value and the far application sensitivity value had indicated that both are the same, then both values would be the same as the approximate converged sensitivity. No additional calculations would be required in this instance. [0229] At this point, the input surface support **16** will need to be adjusted to optimize its angle. Which direction the angle needs to be adjusted will depend on whether, in the previous comparison, the close application sensitivity had the greatest value, or the far application sensitivity had the

[0230] If the close application sensitivity was originally greater, this indicates that the "front surface edge" such as any of **12***a*, **416**, **516**, **614**, **714** of the input surface support such as any of **16**, **606**, **706** as it relates to the user is too high, and the front surface edge such as any of **12***a*, **416**, **516**, **614**, **714** needs to be lowered to optimize the angle. If the far application sensitivity was originally greater, this indicates that the front surface edge **12***a* of the input surface support **16** as it relates to the user is too low, and the front surface edge **12***a* needs to be raised to optimize the angle. If the close application sensitivity and far application sensitivity were already the same value

greatest value.

(which is extremely unlikely), no angle adjustments need to be made.

[0231] How the input surface support **12***a* is raised or lowered is determined by which version of the invention is being used. There are two different main versions of the invention, and these will be referred to as "basic" and "professional" versions, with details of the differences of each version provided.

[0232] The first version of the invention is described as the basic version. In this version, the device is at its simplest form; it is not motorized and there is no direct connectivity between the invention and the computer. The user will place shims **708** and **718** of FIG. **8** underneath the left and right side edges of the input surface support **706** of FIG. **8**, near the front surface edge **714** of FIG. **8**. When the calibrator instructs the user to raise or lower the front surface edge **714**, the user will move the shims **708** and **718**. The initial movements of the shims **708** and **718** will be such that the distance would be in measurements of approximately one centimeter, but once high accuracy numbers have been obtained, the final adjustments will be in tiny increments of less than a millimeter.

[0233] As the position of the shims **708** and **718** is changed, the degree of the angle of the input surface support **706** also changes. Please note that the imaginary dividing line that exists on the input surface support **706** halfway between the front surface edge **714** and the rear surface edge **702** is an extremely important reference point when making adjustments to the position of the shims **708** and **718**. The movement of the shims **708** and **718** in one particular direction would either have the effect of raising or lowering the front surface edge **714**, depending on whether the shims **708** and **718** are on the "front half" (the side that is closest to the user) of the input surface support **706**, or on the "rear half" (the side that is farthest from the user).

[0234] For reference, moving the shims **708** and **718** away from the user will be described as "upwards", and moving the shims **708** and **718** towards the user will be described as "downwards". If the shims **708** and **718** are located at the front half, and the user moves them upwards (which would be towards the center of the input surface support **706**), this would have the effect of raising the front surface edge **714**. If the shims **708** and **718** are located at the front half, and the user moves them downwards (which would be away from the center of the input surface support **706**), this would have the effect of lowering the front surface edge **714**.

[0235] If the shims **708** and **718** are located at the rear half, and the user moves them upwards (which would be away from the center of the input surface support **706**), this would have the effect of lowering the rear surface edge **702**. If the shims **708** and **718** are located at the rear half, and the user moves them downwards (which would be towards the center of the input surface support **706**), this would have the effect of raising the rear surface edge **702**.

[0236] If the front surface edge **714** ever reaches a point where it physically cannot be lowered any further, but the calibrator indicates that it still needs additional lowering, then the "rear surface edge" **702** will be raised instead. (Raising the rear surface edge **702** has a similar effect on the input surface support angle as lowering the front surface edge **714**. This lowers the degree of the angle of the input surface support **706** as it relates to the user.)

[0237] By the same token, if the front surface edge **714** ever reaches a point where it physically cannot be raised any further, but the calibrator indicates that it still needs additional raising, then the rear surface edge **702** will be lowered instead. (Lowering the rear surface edge **702** has a similar effect on the input surface support angle as raising the front surface edge **714**. This increases the degree of the angle of the input surface support **706** as it relates to the user)

[0238] After the user has made a change in the position of the shims **708** and **718**, the user will begin tracking the targets in the calibrator again, swapping between targets as the calibrator instructs. The calibrator will continue to prompt the user to either raise or lower the front surface edge **714**.

[0239] This process will continue until the highest accuracy is measured while tracking both the close range target and the far range target. After this has occurred, the user will slightly pull one of

the shims **708** or **718** horizontally away from the center of the input surface support **706** ("outward") and test accuracy again. In the instance that accuracy had increased, the user would continue to pull the shim **708** or **718** outward in small increments and test accuracy until it is determined that accuracy decreases. In the instance that accuracy had instead decreased, the user would push the shim **708** or **718** towards the center of the input surface support **706** ("inward") in small increments and test accuracy until it is determined that accuracy decreases. In either instance, when accuracy no longer increases, and begins to decrease, the shim **708** or **718** should be moved back to the position which produced the highest tracking accuracy result.

[0240] For reference, please note that moving the shims **708** and **718** upwards or downwards affects the angle of the input surface support **706** as it relates to the Y axis, or the "front to back" angle of the surface, which could be described as leaning the input surface support **706** toward or away from the user. Also, moving the shims **708** and **718** outwards or inwards affects the angle of the input surface support **714** as it relates to the X axis, or the "left to right" angle of the surface, which could be described as leaning the input surface support **706** leftward or rightward from the user. Tracking accuracy must be tested after every adjustment to the angles for both the X axis and Y axis to ensure that the most optimal angles have been found so that the most precise aim possible has been achieved.

[0241] The second version of the invention is described as the professional version. In this version, as shown in FIG. 5, the invention is motorized and has direct connectivity to the computer that hosts the calibrator. Like the basic version, the professional version will also use shims to raise or lower the input surface support, but there will be no prompts for the user to make these adjustments. The required movements will be handled automatically by the motors underneath the surface support. The calibrator will send commands directly to the motors, which will move the small platforms **410**, **412**, and **414** that the shims are attached to.

[0242] In at least one embodiment of the present invention, the member 16 of the device 14 may be a thin rigid board made of metal, tempered glass, or some similar material (which would be placed on table/desk surface 10) that has small boxes 18, 20, 22, and 24 on each of its four corners, as shown in FIG. 1. The boxes 18, 20, 22, and 24 may contain plastic shim wedges and motors that would move them according to how the computer software directed them. In at least one embodiment, the boxes 18, 20, 22, and 24 are connected to each other with a wire under the board 16, and are connected to the computer 2 and powered with a USB cable. The boxes 18, 20 22, and 24 may be connected to and communicate with the computer 2 and/or a computer processor of the computer 2, through hardwired connection or through wireless connection or other communication links. The input surface 12 may be made from a premium material such as textured leather or rubber, attached to the board 16. In at least one embodiment, the boxes 18, 20, 22, and 24 contain small fans with vents that circulate air across the input surface 12, helping to disperse any moisture such as sweat. This aids in keeping the surface friction consistent.

[0243] In one or more embodiments of the present invention, computer software stored in the computer memory of the computer **2**, and implemented by the computer processor of the computer **2**, is configured to produce additional sensitivity settings, for improving accuracy of the pointing input device (computer mouse **8**) accuracy on the computer screen **4** by creating an additional modifier which acts along with manufacturer pointing input device (computer mouse **8**) DPI settings and manufacturer in computer software application sensitivities, which may be originally stored in the computer **2**.

[0244] In one or more embodiments of the present invention, computer software stored in the computer memory of the computer **2**, and implemented by the computer processor of the computer **2**, uses a computer web camera (or equivalent) to capture information about the angles of the pointing input device **8**, input surface **12**, input surface support **16**, desk surface **10**, user's arm, and user's hand. The software analyzes this angle information and provides suggested angle changes on the computer screen **4**.

[0245] FIG. **14**A shows a simplified diagram **1300***a* of a computer mouse **1302** with part of a human being's hand **1310** holding the mouse **1302**, and with a wrist **1311** and arm **1312** of the human being also being shown. The mouse **1302** rests on an input surface **1315**, which in FIG. **14**A is situated so that it is parallel to a horizontal ground surface, though this may not always be the case in other instances that are not shown.

[0246] FIG. **14**B shows a simplified diagram **1300***b* of the computer mouse **1302** with part of the human being's hand **1310** holding the mouse **1302**, and with the wrist **1311** and the arm **1312** of the human being also being shown as in FIG. **14**A, but with the addition of a first means **1320**, which may include two stackable shims, attached to the top surface **1302***a* of the computer mouse **1302**, which adjusts the angle of the hand **1310**, wrist **1311**, and/or one or more fingers of the hand **1310** with respect to a horizontal surface. In FIG. **14**B, the input surface **1315** is parallel to a horizontal ground surface, though this may not always be the case in other instances that are not shown. [0247] FIG. **14**C shows a simplified diagram **1300***c* of the computer mouse **1302** with part of the human being's hand **1310** holding the mouse **1302**, and with the wrist **1311** and the arm **1312** of the human being also being shown as in FIG. **14**A, but with the addition of a second means **1322** attached to the top surface **1302***a* of the computer mouse **1302**, which adjusts the angle of the hand **1310**, wrist **1311**, and/or one or more fingers, such as finger **1310***a* of the hand **1310** with respect to a horizontal surface. In FIG. **14**C, the input surface **1315** is parallel to a horizontal ground surface, though this may not always be the case in other instances that are not shown.

[0248] FIG. **14**A, FIG. **14**B, and FIG. **14**C all show the angles of a human hand (as it relates to a horizontal surface) being changed as the means **1320** and **1322** are introduced. Please note that though not explicitly shown as such in the images, these hand angles could also be expressed as being in relation to the input surface **1315**, the ground surface, some other horizontal surface, or some other part of the user's body. Also note that the angle in FIG. **14**A is smaller than the angle in FIG. **14**B, which is smaller than the angle in FIG. **14**C.

[0249] FIG. **15**A shows a simplified diagram **1400***a* of a computer mouse **1402** with part of a human being's hand **1410** holding the mouse **1402**, and with a wrist **1411** and arm **1412** of the human being also being shown. The mouse **1402** rests on an input surface **1415**, which in FIG. **15**A, is parallel to a horizontal ground surface, though this may not always be the case in other instances that are not shown.

[0250] FIG. **15**B shows a simplified diagram of the computer mouse **1402** of FIG. **15**A with part of the human being's hand **1410** holding the mouse **1402**, and with the wrist **1411** and the arm **1412** of the human being also being shown as in FIG. **15**A, but with the addition of a first means **1420**, which may include a plurality of stackable shims, being placed under the arm **1412** of the user which adjusts the angle of the arm **1412** with respect to a horizontal surface. In FIG. **15**B, the input surface **1415** is parallel to a horizontal ground surface, though this may not always be the case in other instances that are not shown.

[0251] FIG. **15**C shows a simplified diagram of the computer mouse **1402** of FIG. **15**A with part of the human being's hand **1410** holding the mouse **1402**, and with the wrist **1411** and the arm **1412** of the human being also being shown as in FIG. **15**A, but with the addition of a second means **1422**, including a plurality of shims placed under the arm **1412** of the user which adjusts the angle of the arm **1412** with respect to a horizontal surface. In FIG. **15**C, the input surface **1415** is parallel to a horizontal ground surface, though this may not always be the case in other instances that are not shown.

[0252] FIG. **15**A, FIG. **15**B, and FIG. **15**C all show the angles of a human forearm (as it relates to a horizontal surface) being changed as the means **1420** and **1422** are introduced. Please note that though not explicitly shown as such in the images, these forearm angles could also be expressed as being in relation to the input surface **1415**, the ground surface, some other horizontal surface, or some other part of the user's body. Also note that the angle in FIG. **15**A is smaller than the angle in FIG. **15**B, which is smaller than the angle in FIG. **15**C.

[0253] FIG. **16**A shows a simplified diagram **1500***a* of a computer mouse **1502** with part of a human being's hand **1510** holding the mouse **1502**, and with a wrist **1511** and arm **1512** of the human being also being shown. The input surface **1515**, on which the mouse **1502** rests, is also shown. In FIG. **16**A, the input surface **1515** is parallel to a horizontal ground surface, though this may not always be the case in other instances that are not shown.

[0254] FIG. **16**B shows a simplified diagram **1500***b* of the computer mouse **1502** of FIG. **16**A with part of the human being's hand **1510** holding the mouse **1502**, and with the wrist **1511** and the arm **1512** of the human being also being shown as in FIG. **16**A, but with the addition of a first means **1520** placed under the arm **1512** of the user which adjusts the angle of the arm **1512** with respect to a horizontal surface. In FIG. **16**B, the input surface **1515** is parallel to a horizontal ground surface, though this may not always be the case in other instances that are not shown.

[0255] FIG. **16**C shows a simplified diagram **1500***c* of the computer mouse **1502** of FIG. **16**A with part of the human being's hand **1510** holding the mouse **1502**, and with the wrist **1511** and the arm **1512** of the human being also being shown as in FIG. **16**A, but with the addition of a second means **1522** placed under the arm **1512** of the user which adjusts the angle of the arm **1512** with respect to a horizontal surface. In FIG. **16**C, the input surface **1515** is parallel to a horizontal ground surface, though this may not always be the case in other instances that are not shown.

[0256] FIG. **16**A, FIG. **16**B, and FIG. **16**C all show the angles of an upper arm of a human (as it relates to a horizontal surface) being changed as the means **1520** and **1522** are introduced. Please note that though not explicitly shown as such in the images, these upper arm angles could also be expressed as being in relation to the input surface **1515**, the ground surface, some other horizontal surface, or some other part of the user's body. Also note that the angle in FIG. **16**A is smaller than the angle in FIG. **16**B, which is smaller than the angle in FIG. **16**C.

[0257] FIG. **17**A shows a simplified diagram **1600***a* of an apparatus including a computer mouse **1602** with another means for directly adjusting an input surface support, and indirectly adjusting the angle of the computer mouse **1602**, with respect to a surface. The apparatus of diagram **1600***a* may include a mouse **1602**, an input surface **1604**, an input surface support **1606**, rubber bumpers **1608** and **1614**, a shim **1610**, and a desk surface **1612**. The mouse **1602** is shown at an angle of A4 with respect to a horizontal surface. In FIG. 17A, the desk surface 1612 is parallel to a horizontal ground surface, though this may not always be the case in other instances that are not shown. [0258] FIG. **17**B shows a simplified diagram **1600***b* of an apparatus including the computer mouse **1602** with another means for directly adjusting an input surface support, and indirectly adjusting the angle of the computer mouse **1602**, with respect to a surface. The apparatus of diagram **1600***b* may include the mouse **1602**, the input surface **1604**, the input surface support **1606**, rubber bumpers 1608 and 1614, the shim 1610, and the desk surface 1612. The bottom surface of the mouse **1602**, and surface **1606** are shown at an angle of A5 with respect to a horizontal surface. In FIG. 17B, the desk surface 1612 is parallel to a horizontal ground surface, though this may not always be the case in other instances that are not shown. In FIG. 17B, the shim 1610 has been slid more towards the center of member **1606** to cause an increase in angle, i.e. angle A**5** in FIG. **17**B is greater than angle A4 in FIG. 17A.

[0259] FIG. **17**C shows a simplified diagram **1600***c* of an apparatus including the computer mouse **1702** with another means for directly adjusting an input surface support, and indirectly adjusting the angle of the computer mouse **1602** (or the bottom surface of the computer mouse **1602**), with respect to a surface. The apparatus of diagram **1600***c* may include the mouse **1602**, the input surface **1604**, the input surface support **1606**, rubber bumpers **1608** and **1614**, the shim **1610**, and the desk surface **1612**. The bottom surface of the mouse **1602**, and surface **1606** are shown at an angle of **A6** with respect to a horizontal surface. In FIG. **17**C, the desk surface **1612** is parallel to a horizontal ground surface, though this may not always be the case in other instances that are not shown. In FIG. **17**C, the shim **1610** has been replaced by shim **1611** which include two shims, and which has a greater height than shim **1610** of FIG. **17**B, so that angle **A6** in FIG. **17**C is greater

than angle A5 in FIG. 17B.

[0260] FIG. **17**A, FIG. **17**B, and FIG. **17**C all show the angles of an input surface support **1606** (as it relates to a horizontal surface) being changed as the shims **1610** and **1611** are introduced and moved. Please note that though not explicitly shown as such in the images, these input surface support angles could also be expressed as being in relation to the input surface **1604**, the ground surface, some other horizontal surface, or some part of the user's body.

[0261] FIG. **18**A is a simplified diagram **1700***a* of a computer mouse **1702**, with a first means **1704**, which may be a shim, of FIG. **18**A for adjusting an angle of a bottom surface **1702***a* of the computer mouse **1702** with respect to a horizontal surface. The input surface **1706** sits on a desk surface **1708**. In FIG. **18**A, the input surface **1706** and desk surface **1708** are both parallel to a horizontal ground surface, though this may not always be the case in other instances that are not shown.

[0262] FIG. **18**B is a simplified diagram **1700***b* of a computer mouse **1702**, with a second means **1714**, which may be a shim of combination of shims (having a greater height than the means **1704** in FIG. **18**A), of FIG. **18**B for adjusting an angle of a bottom surface **1702***a* of the computer mouse **1702** with respect to a horizontal surface. The angle in FIG. **18**B is greater than the angle in FIG. **18**A. The input surface **1706** sits on a desk surface **1708**. In FIG. **18**B, the input surface **1706** and desk surface **1708** are both parallel to a horizontal ground surface, though this may not always be the case in other instances that are not shown.

[0263] FIG. **18**C is a simplified diagram **1700***c* of a computer mouse **1702**, with a third means **1724**, which may be a shim of combination of shims (having a greater height than the means **1704** in FIG. **18**A and a greater height that the means **1714** in FIG. **18**B), of FIG. **18**B for adjusting an angle of a bottom surface **1702***a* of the computer mouse **1702** with respect to a horizontal surface. The angle in FIG. **18**C is greater than the angle in FIG. **18**A or the angle in FIG. **18**B. The input surface **1706** sits on a desk surface **1708**. In FIG. **18**C, the input surface **1706** and desk surface **1708** are both parallel to a horizontal ground surface, though this may not always be the case in other instances that are not shown.

[0264] FIG. **18**A, FIG. **18**B, and FIG. **18**C all show the angles of a pointing input device **1702** (as it relates to a horizontal surface) being changed as the shims **1704**, **1714**, and **1724** are introduced. Please note that though not explicitly shown as such in the images, these pointing input device angles could also be expressed as being in relation to the input surface **1706**, the ground surface, some other horizontal surface, or some part of the user's body.

[0265] FIG. **19**A is a simplified diagram **1800***a* of a computer mouse **1802**, with a first means **1810**, which may be a shim, of FIG. **19**A for directly adjusting an input surface **1808** that is rigid, and indirectly adjusting an angle of a bottom surface **1802***a* of the computer mouse **1802**, with respect to a horizontal surface. The diagram **1800***a* shows rubber bumper **1804**, an input surface **1808** that is rigid, desk surface **1806**, rubber bumper **1812**, as well as shim **1810**. In FIG. **19**A, the desk surface **1806** is parallel to a horizontal ground surface, though this may not always be the case in other instances that are not shown.

[0266] FIG. **19**B is a simplified diagram **1800***b* of a computer mouse **1802**, with a second means **1810**, which may be a shim, of FIG. **19**B for directly adjusting an input surface **1808** that is rigid, and indirectly adjusting an angle of a bottom surface **1802***a* of the computer mouse **1802**, with respect to a horizontal surface. The diagram **1800**B shows rubber bumper **1804**, input surface **1808** that is rigid, desk surface **1806**, rubber bumper **1812**, as well as shim **1810**. In FIG. **19**B the shim **1810** has been moved more towards the center of the surface **1808**, on which the mouse **1802** rests, in order to increase the angle of the bottom surface **1802***a* of the mouse **1802** and the surface **1808**, with respect to a horizontal surface. In FIG. **19**B, the desk surface **1806** is parallel to a horizontal ground surface, though this may not always be the case in other instances that are not shown. The angle in FIG. **19**A is less than the anglein FIG. **19**B.

[0267] FIG. **19**C is a simplified diagram **1800***c* of a computer mouse **1802**, with a second means

1811, which may be a shim or combination of shims (which has a greater height than the height of shim **1810** in FIG. **19**B), of FIG. **19**C for directly adjusting an input surface **1808** that is rigid, and indirectly adjusting an angle of a bottom surface **1802***a* of the computer mouse **1802**, with respect to a horizontal surface. The diagram **1800**C shows rubber bumper **1804**, input surface **1808** that is rigid, desk surface **1806**, rubber bumper **1812**, as well as shim **1811**. In FIG. **19**C the shim **1811** is more towards the center of the surface 1808, on which the mouse 1802 rests, in order to increase the angle of the bottom surface **1802***a* of the mouse **1802** and the surface **1808**, with respect to the horizontal surface. In FIG. 19C, the desk surface 1806 is parallel to a horizontal ground surface, though this may not always be the case in other instances that are not shown. The angle in FIG. **19**A is less than the angle in FIG. **19**B, which is less than the angle in FIG. **19**C. [0268] FIG. **19**A, FIG. **19**B, and FIG. **19**C all show the angles of an input surface **1808** (as it relates to a horizontal surface) being changed as the shims **1810** and **1811** are introduced and moved. Please note that though not explicitly shown as such in the images, these angles being changed could also be expressed as being in relation to the input surface support 1806, the ground surface, some other horizontal surface, or some part of the user's body. [0269] Although the invention has been described by reference to particular illustrative embodiments thereof, many changes and modifications of the invention may become apparent to those skilled in the art without departing from the spirit and scope of the invention. It is therefore intended to include within this patent all such changes and modifications as may reasonably and properly be included within the scope of the present invention's contribution to the art.

Claims

- **1**. An apparatus comprising a means for adjusting the angle of a pointing input device with respect to a horizontal surface; and wherein the pointing input device relies on an input surface for the purpose of calculating cursor position; wherein the means for adjusting the angle of the pointing input device with respect to the horizontal surface include computer software stored in a computer memory, and implemented by a computer processor; and wherein the computer software stored in the computer memory, and implemented by the computer processor provides suggested angle changes on the computer screen to improve input precision of the pointing input device.
- **2.** The apparatus of claim 1 wherein the computer software is configured to implement the suggested angle changes from the computer software, with the pointing device; and wherein after the suggested angle changes are implemented with the pointing input device, the computer software stored in the computer memory, and implemented by the computer processor enables a user, through a user interactive device, to determine what affect the suggested angle changes had on accuracy of the pointing input device, through data displayed on the computer screen.
- **3.** The apparatus of claim 1 wherein the computer software stored in the computer memory, and implemented by the computer processor generates targets at different positions on the computer screen.
- **4.** The apparatus of claim 1 wherein the computer software stored in the computer memory, and implemented by the computer processor produces additional sensitivity settings for improving accuracy of the pointing input device by creating an additional modifier to act along with manufacturer pointing input device DPI settings and manufacturer in-application sensitivities.
- **5.** The apparatus of claim 1 wherein the computer software stored in the computer memory, and implemented by the computer processor uses a range of dots per inch (DPI) settings and provides suggested angle changes on the computer screen to improve input precision of the pointing input device.
- **6.** The apparatus of claim 1 wherein the computer software stored in the computer memory, and implemented by the computer processor uses a range of computer software sensitivities and provides suggested angle changes on the computer screen to improve input precision of the

pointing input device.

- 7. An apparatus comprising a means for adjusting the angle of an input surface with respect to a horizontal surface; and wherein a pointing input device relies on the input surface for the purpose of calculating cursor position; wherein the means for adjusting the angle of the input surface with respect to the horizontal surface include computer software stored in a computer memory, and implemented by a computer processor; and wherein the computer software stored in the computer memory, and implemented by the computer processor provides suggested angle changes on the computer screen to improve input precision of the pointing input device.
- **8.** The apparatus of claim 7 wherein the computer software stored in the computer memory is configured to implement the suggested angle changes with the input surface; and wherein after the suggested angle changes are implemented with the input surface, the computer processor enables a user, through a user interactive device, to determine what affect the angle suggested changes had on accuracy of the pointing input device, through data displayed on the computer screen.
- **9.** The apparatus of claim 7 wherein the computer software stored in the computer memory, and implemented by the computer processor generates targets at different positions on the computer screen.
- **10.** The apparatus of claim 7 wherein the computer software stored in the computer memory, and implemented by the computer processor produces additional sensitivity settings for improving accuracy of the pointing input device by creating an additional modifier to act along with manufacturer pointing input device DPI settings and manufacturer in-application sensitivities.
- **11.** The apparatus of claim 7 wherein the computer software stored in the computer memory, and implemented by the computer processor uses a range of dots per inch (DPI) settings and provides suggested angle changes on the computer screen to improve input precision of the pointing input device.
- **12**. The apparatus of claim 7 wherein the computer software stored in the computer memory, and implemented by the computer processor uses a range of computer software sensitivities and provides suggested angle changes on the computer screen to improve input precision of the pointing input device.
- **13**. A method comprising: using computer software to suggest changes to a physical angle of an object with respect to a first surface; and using the computer software to determine if the changes to the physical angle of the object with respect to the surface product higher accuracy of a pointing input device used with a computer monitor.
- **14.** The method of claim 13 wherein the object is a second surface that the pointing input device is configured to use to calculate cursor position.
- **15**. The method of claim 13 wherein the object is a second surface which is underneath a third surface that the pointing input device is configured to use to calculate cursor position on the computer monitor.
- **16.** The method of claim 13 wherein the object and the pointing input device are one and the same.