

US0D1088782S

(12) United States Design Patent (10) Patent No.:

Torres

(10) Patent No.: US D1,088,782 S

(45) Date of Patent: ** Aug. 19, 2025

(54) CORK HOLDING DEVICE

- (71) Applicant: Kevin Torres, Little Falls, NJ (US)
- (72) Inventor: **Kevin Torres**, Little Falls, NJ (US)
- (73) Assignee: Kevin Torres, Little Falls, NJ (US)
- (**) Term: 15 Years
- (21) Appl. No.: 29/808,337
- (22) Filed: Sep. 17, 2021
- (52) U.S. Cl.

USPC **D8/395**; D7/633

(58) Field of Classification Search

USPC D7/600.1, 633, 669, 708.1; D8/33, 39, D8/40, 42, 394; D24/128, 143
CPC B67B 7/00; B67B 7/02; B67B 7/04; B67B 7/06; B67B 7/0423; B67B 7/0447; A61B 17/122; A61B 17/128; A61B 17/1227

See application file for complete search history.

(56) References Cited

U.S. PATENT DOCUMENTS

D276,272	\mathbf{S}	*	11/1984	Weissenburger D24/176
D277,534	S	*	2/1985	Warmath D6/328
D360,053	S	*	7/1995	Wilborn, II D28/38
D549,417	\mathbf{S}	*	8/2007	Siegel D8/395
8,201,310	В1	*	6/2012	Abdi D06F 55/02
				24/507
D664,838	S	*	8/2012	Parks D8/395
D814,284	S	*	4/2018	Howard D8/395
D873,126	S	*	1/2020	Tang D8/395

D938,814	\mathbf{S}	*	12/2021	Wickham D8/	394
D987,707	S	*	5/2023	Foster D8/	395
D988,395	S	*	6/2023	Foster D8/	395
D1,057,554	S	*	1/2025	Zheng D8/2	394
2022/0363439	A1	*	11/2022	Torres B65D 23	3/12

^{*} cited by examiner

Primary Examiner — Erich G Herbermann Assistant Examiner — Rene H. Kadoo

(57) CLAIM

The ornamental design for a cork holding device, as shown and described.

DESCRIPTION

FIG. 1 is a left side perspective view of the cork holding device in accordance with the present design;

FIG. 2 is a left side elevational view of the cork holding device of FIG. 1;

FIG. 3 is a top elevational view of the cork holding device of FIG. 1;


FIG. 4 is a rear elevational view of the cork holding device of FIG. 1; and,

FIG. 5 is a front elevational view of the cork holding device of FIG. 1.

The right side elevational view is not shown because it is symmetric to the left side elevational view, and the bottom elevational view is not shown because it is symmetric to the top elevational view.

The broken lines depict portions of the cork holding device and form no part of the claimed design.

1 Claim, 5 Drawing Sheets






FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5