

(12) **United States Design Patent** (10) **Patent No.:** **US D1,087,734 S**
Yao (45) **Date of Patent:** **** Aug. 12, 2025**

(54) **ARBOR CONNECTING BRACKET**

FOREIGN PATENT DOCUMENTS

(71) Applicant: **Suqian Qiuze Trading Co., Ltd.**,
Jiangsu (CN)

JP D1081220 * 7/2000

(72) Inventor: **Yuebing Yao**, Jiangsu (CN)

OTHER PUBLICATIONS

(73) Assignee: **Suqian Qiuze Trading Co., Ltd.**,
Jiangsu (CN)

Wild Hog Linx, Home Depot, Apr. 1, 2021, <https://www.homedepot.com/p/WILD-HOG-LINX-4-in-TriFit-Black-Steel-Corner-Bracket-Pergola-for-4x4-Wood-Posts-1-Pack-3051879/315749957> (Year: 2021).
Pergola Bracket Kit Woodworking Pergola Brackets, Amazon, Jul. 22, 2024, <https://www.amazon.de/-/en/Pergola-Bracket-Woodworking-Brackets-Unidirectional/dp/B0D9VVB48V?th=1> (Year: 2024).*

(**) Term: **15 Years**

* cited by examiner

(21) Appl. No.: **29/896,077**

(22) Filed: **Jun. 29, 2023**

Primary Examiner — Lilyana Bekic

(51) **LOC (15) Cl.** **08-05**

Assistant Examiner — Elizabeth Sun Ko

(52) **U.S. Cl.**

(74) *Attorney, Agent, or Firm* — Bartholomew Law PC;
Michael Bartholomew

USPC **D8/354**

(58) **Field of Classification Search**

(57) **CLAIM**

USPC D8/354–360.1, 366, 373–374, 380, 499
CPC A47B 1/08; A47B 1/10; E04C 5/18; E04C
2/384; E04C 2003/026; E04C 5/162

The ornamental design for a arbor connecting bracket as shown and described.

See application file for complete search history.

DESCRIPTION

(56) **References Cited**

U.S. PATENT DOCUMENTS

D783,390 S * 4/2017 Nelson D8/382
D843,818 S * 3/2019 House D8/366
D927,965 S * 8/2021 Bowron D8/382
D944,079 S * 2/2022 Young D12/345
D1,022,676 S * 4/2024 Yao D8/366
D1,029,628 S * 6/2024 Jensen D8/380
D1,051,701 S * 11/2024 Murayama D8/354
D1,073,445 S * 5/2025 Xu D8/354
2019/0000220 A1 * 1/2019 Lemmens A45F 3/24
2019/0301504 A1 * 10/2019 Nelson F16B 12/50

FIG. 1 is a front, right and top perspective view of a arbor connecting bracket, showing my design.

FIG. 2 is a rear, left and bottom perspective view thereof.

FIG. 3 is a front elevation view thereof.

FIG. 4 is a rear elevation view thereof.

FIG. 5 is a left side elevation view thereof.


FIG. 6 is a right side elevation view thereof.

FIG. 7 is a top plan view thereof; and,

FIG. 8 is a bottom plan view thereof.

The broken lines depict portions of the arbor connecting bracket that form no part of the claimed design.

1 Claim, 8 Drawing Sheets






FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7




FIG. 8