Operation of Switches

William Lucid 04/01/2023

Switch pin assignments:

Switch1Pin GPIO13 //Switch 1
Switch2Pin GPIO14 //Switch 2
Switch3Pin GPIO23 //Switch 3

- 1. Red led only "ON": Press briefly (pb) Switch 2 (GPIO14) twice, then pb Switch 1 (GPIO13) once. Repeat step if fails first time.
- 2a. **Entering Deep Sleep:** Must be interrupted when running "noMotion". Red and Blue leds, both "ON", pb Switch 3 (GPIO23) once, then pb Switch 1 (GPIO13) once or twice. Blue led will turn "OFF"
- 2b. Wake up from Deep Sleep: Press Switch 1 once; Serial Monitor will show start up details.
- 3. **Switching effects:** pb Switch 3 (GPIO23) once, then pb Switch 2 (GPIO14) twice. Motion function will start.

Project: MPU6050_WLED_withThree_Switches_1600 04/01/2023