

INSPECTION REPORT

PLEASE TYPE OR PRINT IN BLOCK LETTERS AND USE ONE INSPECTION REPORT PER INSPECTION

1. GENERAL

Inspection No.	K-01-2023	Inspection Report Date	18-10-2023
Inspection Begin Date	17-10-2023 (6PM)	Inspection End Date	17-10-2023 (07:00PM)
To: MR. AFTAB	From: RAZA		
Email: _____	E-mail: raza@nmzassociates.com		

Inspection Partner	RAZA/MANZAR	Product family photo  	
Inspection Partner File No.			
Inspection Partner Office			
Client	MADINAPAK		
NMZ Company			
NMZ Office			
NMZ BDM Name			
NMZ Merchandiser Name			
NMZ QCM Name			
NMZ Department No.			
Vendor	P		
Factory	P		
Inspection Location City	KARACHI		
Inspection Location Country	PAKISTAN		
Previous inspection No. (only for RE-FRI)			
Style No.	BAGS	Size	
Product Type	NON-WOVEN BAGS	Color	
Product description	NON-WOVEN REUSABLE BAGS IN DIFFERENT SIZE AND COLOR		
P.O. No.	10654	Service requested	☐ MPC / FRI ☐
PO#, Actual inspected No. of style / Total No. of Styles on PO	10654		
Combined sampling	YES	Inspection booking date (if needed)	16-10-2023
Comments on Lab Test Report	Test Report Number # ☐ Pass ☐ Accepted by ECI ☐ No Pass, but approved for Inspection through E-mail ☒ N/A		

Note: When more than one option per field is possible, write them separately by a slash. (For example, for different P.O. No. write: PO1 / PO2 / PO3).

OVERALL INSPECTION REPORT RESULT

FAIL (DUE TO PACKING)

2. QUANTITY

Note: When combined sampling, write the different style numbers in the same row and the different quantities for each one.

Style No.	PO No.	Order Qty.	Shipment Qty.	Presented Qty. for inspection		Inspection Qty.				
				Units	%	Packed			Not packed	
						Units	%	Cartons	Units	Cartons
FOLLOW NEXT PAGE FOR QUANTITIES										
Total										

* Add as many fields as required.

INSPECTION REPORT

2. QUANTITY

Note: When combined sampling, write the different style numbers in the same row and the different quantities for each one.

Style No.	color	Order Qty.		Shipment Qty.		Presented Qty. for inspection		Inspection Qty.				
						Units	%	Packed			Not packed	
								Units	%	Cartons	Units	Cartons
12X22	BLACK	12000	PCS	12000	PCS	12000	100%	12000	100%	24	0%	0
12X22	BLUE	12000	PCS	12000	PCS	12000	100%	12000	100%	34	0%	0
12X22	GREEN	15500	PCS	15500	PCS	15500	100%	15500	100%	31	0%	0
12X22	ORANGE	18500	PCS	18500	PCS	18500	100%	18500	100%	37	0%	0
12X24	ORANGE	14000	PCS	14000	PCS	14000	100%	14000	100%	28	0%	0
12X24	BLACK	15000	PCS	15000	PCS	15000	100%	15000	100%	30	0%	0
12X24	BLUE	19500	PCS	19500	PCS	19500	100%	19500	100%	39	0%	0
12X24	GREEN	13500	PCS	13500	PCS	13500	100%	13500	100%	27	0%	0
14X24	BLACK	13000	PCS	13000	PCS	13000	100%	13000	100%	26	0%	0
14X24	GREEN	13000	PCS	13000	PCS	13000	100%	13000	100%	26	0%	0
14X24	ORANGE	14500	PCS	14500	PCS	14500	100%	14500	100%	29	0%	0
14X24	BLUE	13000	PCS	13000	PCS	13000	100%	13000	100%	26	0%	0
17.5X15	PINK	9300	PCS	9300	PCS	9300	100%	9300	100%	31	0%	0
17.5X15	YELLOW	9300	PCS	9300	PCS	9300	100%	9300	100%	31	0%	0
18X5X14	BLUE	2000	PCS	2000	PCS	2000	100%	2000	100%	10	0%	0
18X5X14	BLACK	5400	PCS	5400	PCS	5400	100%	5400	100%	18	0%	0
18X5X14	GREY	5100	PCS	5100	PCS	5100	100%	5100	100%	17	0%	0
18X5X14	BLEACHED	6300	PCS	6300	PCS	6300	100%	6300	100%	21	0%	0
18X5X14	BROWN	5700	PCS	5700	PCS	5700	100%	5700	100%	19	0%	0
	mix	sample box		not presented during inspection								
	mix	sample box		not presented during inspection								
TOTAL		216600	PCS	216600	PCS	216600	100%	216600	100%	504	0%	0

* Add as many fields as required.

INSPECTION REPORT

Samples selected from carton numbers:	Carton No.:	303	6	40	70	130	100	160	190	230
		400	410	421	435	455	470	490	363	340
	Total number of cartons opened for sampling:									
No. of re-packed cartons identified by stamps / closing tape:		18								
Quantity remarks	OK									

3. INSPECTION RESULT SUMMARY

Note: When combined sampling, write the different style numbers in the same raw and then its general result.

Style No. PO NO.	Inspection Result	Fail Reason						
		Write one option: PASS/ FAIL/ PENDING/ NOT APPLICABLE (N/A)						
		Quantity	Workmanship	Packing	Shipping Marks	Data measurements & Tests	Style/ Color conformity	REMARK
10654	FAIL	OK	OK	FAIL	FAIL	OK	OK	FAIL

* Add as many fields as required.

PROBLEM REMARK			
Style No.	Inspection Result	Code No.	Problem description
10654	FAIL	PACKING	PACKING IS DAMAGING PRODUCT.

Inspection starting time:	Inspection ending time:
Inspector:	Vendor/ Factory representative:
RAZA / MANZAR	UMAIR / AFTAB

4. INSPECTION CRITERIA

Golden sample	n/a
BUYER instruction/specification	n/a
Completed QC File	n/a
Other	n/a

5. WORKMANSHIP

Appearance and functional inspection findings (including labels & hangtags findings)

Note: Use a table per style. Only in case of combined sampling, a table can be used for different styles.

INSPECTION REPORT

all about clothing

Inspection method applied									
ANSI/ASQ Z1.4-2008, Single sampling plans for normal inspection							Level:	II	
Acceptable Quality Limit (AQL) for			Critical:	00	Major:	2.5	Minor:	4.0	
Sample size:									
Style No.	PO No.	Colors	Sample size	Code No.	Description	C	M	m	
1 2 X 2 2	1 0 6	B L A C K			remove metal binding straps				
1 2 X 2 2		B L U E			inside and outside of the box				
1 2 X 2 2		G R E E N							
1 2 X 2 2		O R A N G E			do not fold the bags inside polybag				
1 2 X 2 4		O R A N G E			it must be straight flat packed in a				
1 2 X 2 4		B L A C K			bag and straight packed in a box				
1 2 X 2 4		B L U E							
1 2 X 2 4		G R E E N							
1 4 X 2 4		B L A C K			box bag handles should be straight				
1 4 X 2 4		G R E E N			outside or either inside to avoid				
1 4 X 2 4		O R A N G E			crashing				
1 4 X 2 4		B L U E			stake the pieces reverse side of				
1 7 . 5 X 1 5		P I N K			each 10 bags to divide the weight				
1 7 . 5 X 1 5		Y E L L O W			equally				
1 8 X 5 X 1 4		B L U E							
1 8 X 5 X 1 4		B L A C K			need net weight and gross weight				
1 8 X 5 X 1 4		G R E Y			on each carton				
1 8 X 5 X 1 4		B L E A C H							
1 8 X 5 X 1 4		B R O W N							
Total				Total defects					
Maximum allowed						0	10	14	
WORKMANSHIP RESULT							PASS		

* Add as many fields for defects as required.

Workmanship remarks	WORKMAN SHIP PASS BUT BAD PRESSING AND RIB HEIGHT DIFFERENCES AMONG PIECES
Other defects observed but not counted in the AQL result:	FAIL DUE TO PACKING AND CRASHING INSIDE BOX, ALL THE PRODUCT SHOULD BE FLAT PACKED TO AVOID CRUSHING, AVOID EMPTY SPACE IN THE BOX

6. PACKING

Note: Use a table per style. Only in case of combined sampling or when the same features are found for all styles, one table can be used for different styles.

Style No.:	P.O. No.
6.1. Carton conformity	PLEASE ADD CARTON DIMENSION GROSS WEIGHT, NET WEIGHT ON EACH CARTON
Carton dimension found L x W x H	
Carton weight found	WEIGHT SHEET ATTACHED,
Remarks:	FOUND DURING INSPECTION FOR THE SELECTED CARTONS.
6.2. Packaging	
A. Individual packing conformity (plastic bags, inner box, alarms, etc.)	

INSPECTION REPORT

Remarks:	
B. Assortment	OK
Assortment checked on ____ cartons	OK
Remarks:	
PACKING RESULT	OK

7. SHIPPING MARKS

Note: Use a table per style. Only in case of combined sampling or when the same features are found for all styles, one table can be used for different styles.

Style No.:	P.O. No.:
7.1. Side labels conformity	MISSING NET AND GROSS WEIGHT AND CARTON SIZE
Remarks:	ON SHIPPING MARK
7.2. Shipping marks conformity	
Remarks:	
SHIPPING MARK RESULT	PLEASE SHIPPING MARKS IN LENGTH AND WIDTH 2 SIDED

8. DATA MEASUREMENTS & TESTS

8.1. Data measurements																
Sample size for data measurement																
<table border="1"> <thead> <tr> <th>Style</th> <th>Size</th> <th>Color</th> <th>Sample size</th> <th>Result</th> </tr> </thead> <tbody> <tr><td> </td><td> </td><td> </td><td> </td><td> </td></tr> <tr><td> </td><td> </td><td> </td><td> </td><td> </td></tr> </tbody> </table> * Add as many fields as required.		Style	Size	Color	Sample size	Result										
Style	Size	Color	Sample size	Result												
Remarks:																
Please, attach size measurement sheet. OK																

8.2. Tests	CONFORM		
Style No.:		P.O. No.:	
#	Test		Findings/Remarks
	Sample size		N/A
	Test performed with factory equipment?		
	If factory equipment used, calibration record		
	☐ Yes ☐ No		
☐ Yes, period: ☐ No			

* Add as many tables as tests performed and number them.
* Add as many tables as styles inspected and include styles inspected.

INSPECTION REPORT

DATA MEASUREMENTS & TESTS RESULT

N/A

9. STYLE/COLOR CONFORMITY

Note: Use a table per style. Only in case of combined sampling, a table can be used for different styles.

Style No.:		P.O. No.:	
9.1. Style conformity		OK	
Remarks:			
9.2. Material conformity (hand feeling)		OK	
Remarks:			
9.3. Color conformity		OK	
Remarks:			
STYLE/COLOR CONFORMITY RESULT		PASS	

10. NOTE

☐ Any problems found during inspection but accepted by merchandiser and QC manager from NMZ.

Remarks:	N/A
----------	-----

☐ Production/ Defective sample(s) will be sent to NMZ for reference by the Inspection Agency.

Style No.	Color	Size	Defect / Information	Quantity

* Add as many fields for defects as required.

☐ Production/ Defective sample(s) to be kept at Inspection Agency for reference.

Style No.	Color	Size	Defect / Information	Quantity

* Add as many fields for defects as required.

☒ All the selected cartons were not sealed after inspection because the factory did not repack them immediately.

11. INSPECTION ENVIRONMENT

Lighting	☐ Day light	☐ Room lighting	☐ Sufficient	☒ Insufficient
Inspection place	☐ Warehouse	☐ Factory workshop	☒ Other: GODOWN	

INSPECTION REPORT

all about clothing

Inspection done on	☐ Table	☐ Other:	
Cleanliness	☐ Clean	☐ Dirty	☐ Other:
Weather condition	☐ Rainy	☐ Dry	☐ Other:
Observations			

12. ATTACHMENT

Related photo	Related photo
	
	
	

Add as many photos as required.

INSPECTION REPORT

all about clothing

Inspection done on	☐ Table	☐ Other:	
Cleanliness	☐ Clean	☐ Dirty	☐ Other:
Weather condition	☐ Rainy	☐ Dry	☐ Other:
Observations			

12. ATTACHMENT

Related photo	Related photo
	
	
	

Add as many photos as required.

INSPECTION REPORT

all about clothing

Inspection done on	☐ Table	☐ Other:	
Cleanliness	☐ Clean	☐ Dirty	☐ Other:
Weather condition	☐ Rainy	☐ Dry	☐ Other:
Observations			

12. ATTACHMENT

Related photo	Related photo
	
	
	


Add as many photos as required.

INSPECTION REPORT

all about clothing

Inspection done on	☐ Table	☐ Other:	
Cleanliness	☐ Clean	☐ Dirty	☐ Other:
Weather condition	☐ Rainy	☐ Dry	☐ Other:
Observations			

12. ATTACHMENT

Related photo	Related photo
	
	
	

Add as many photos as required.

INSPECTION REPORT

all about clothing

Inspection done on	☐ Table	☐ Other:	
Cleanliness	☐ Clean	☐ Dirty	☐ Other:
Weather condition	☐ Rainy	☐ Dry	☐ Other:
Observations			

12. ATTACHMENT

Related photo	Related photo
	
	
	

Add as many photos as required.

INSPECTION REPORT

Inspection done on	☐ Table	☐ Other:	
Cleanliness	☐ Clean	☐ Dirty	☐ Other:
Weather condition	☐ Rainy	☐ Dry	☐ Other:
Observations			

12. ATTACHMENT

Related photo	Related photo
	
	
	

Add as many photos as required.

INSPECTION REPORT

Inspection done on	☐ Table	☐ Other:	
Cleanliness	☐ Clean	☐ Dirty	☐ Other:
Weather condition	☐ Rainy	☐ Dry	☐ Other:
Observations			

12. ATTACHMENT

Related photo	Related photo
	
	
	

Add as many photos as required.

INSPECTION REPORT

all about clothing

Inspection done on	☐ Table	☐ Other:	
Cleanliness	☐ Clean	☐ Dirty	☐ Other:
Weather condition	☐ Rainy	☐ Dry	☐ Other:
Observations			

12. ATTACHMENT

Related photo	Related photo
---------------	---------------

SELECTED CARTONS FOR INSPECTION GROSS AND NET WEIGHT			
CARTON NO.	NET WEIGHT	GROSS WEIGHT	EMPTY BOX WEIGHT GIVEN BY FACTORY
303	11.800	13.400	1.600
6	9.850	11.450	1.600
40	9.700	11.300	1.600
70	9.900	11.500	1.600
130	11.500	13.100	1.600
100	9.700	11.300	1.600
160	11.450	13.050	1.600
190	12.050	13.650	1.600
230	11.800	13.400	1.600
340	12.600	14.200	1.600
363	16.650	18.450	1.800
400	16.350	18.150	1.800
410	16.500	18.300	1.800
421	13.600	15.400	1.800
435	14.300	16.100	1.800
455	15.400	17.200	1.800
470	18.000	19.800	1.800
490	14.950	16.750	1.800

INSPECTION REPORT

all about clothing

Inspection done on	☐ Table	☐ Other:	
Cleanliness	☐ Clean	☐ Dirty	☐ Other:
Weather condition	☐ Rainy	☐ Dry	☐ Other:
Observations			

PACKING LIST

PLEASE ADD NET WEIGHT AND GROSS WEIGHT AND TOTAL PIECES PER COLOR/SIZE

Marks & Nos	Quality Size	Colors	Packing	Cartons Packing	Total Carton	Net Weight Kgs	Gross Weight Kgs	Cbm
MPL CTN-NOS 107	12X22	Black	500 Pcs Each Ctn	01 - 24 Carton	24	237.6	276.00	2.463
	12X22	Blue	500 Pcs Each Ctn	25 - 58 Carton	34	336.6	391.00	3.490
	12X22	Green	500 Pcs Each Ctn	59 - 89 Carton	31	306.9	356.50	3.180
	12X22	Orange	500 Pcs Each Ctn	90 - 126 Carton	37	366.30	425.50	3.798
	12X24	Orange	500 Pcs Each Ctn	127 - 154 Carton	28	329.00	373.80	2.874
	12X24	Black	500 Pcs Each Ctn	155 - 184 Carton	30	352.50	400.50	3.079
	12X24	Blue	500 Pcs Each Ctn	185 - 223 Carton	39	458.25	520.65	4.003
	12X24	Green	500 Pcs Each Ctn	224 - 250 Carton	27	317.25	360.45	2.771
	14X24	Green	500 Pcs Each Ctn	251 - 276 Carton	26	317.2	358.80	2.669
	14X24	Black	500 Pcs Each Ctn	277 - 302 Carton	26	317.2	358.80	2.669
	14X24	Green	500 Pcs Each Ctn	303 - 331 Carton	29	353.8	400.20	2.972
	14X24	Orange	500 Pcs Each Ctn	332 - 357 Carton	26	317.2	358.80	2.669
	14X24	Blue	500 Pcs Each Ctn	358 - 388 Carton	31	483.60	554.90	4.607
	17.5X5X15 Laminated	Pink	300 Pcs Each Ctn	389 - 419 Carton	31	483.60	554.90	4.607
	17.5X5X15 Laminated	Yellow	300 Pcs Each Ctn	420 - 429 Carton	10	133.00	156.00	1.469
	18X5X14	Blue	200 Pcs Each Ctn	430 - 447 Carton	18	254.70	298.00	2.887
	18X5X14 Plain	Black	300 Pcs Each Ctn	448 - 464 Carton	17	260.95	300.05	2.507
	18X5X14 Plain	Grey	300 Pcs Each Ctn	465 - 485 Carton	21	350.70	399.00	3.134
	18X5X14 Plain	Bleached	300 Pcs Each Ctn	486 - 504 Carton	19	273.60	317.30	2.836
	18X5X14 Plain	Brown	300 Pcs Each Ctn	505 - 505 Carton	1	15.30	17.60	0.149
	Laminated / Plain Bags	Dyed	300 Pcs in Ctn	506 - 506 Carton	1	15.60	17.90	0.149
	12X22 / 12X24 / 14X24	Dyed	600 Pcs in Ctn		506	6,280.85	7,194.75	53.58