

DAELIM INDUSTRIAL CO., LTD.

5B Floor, HL Tower, 82 Alley, Duy Tan Street, Dich Vong Ward, Cau Giay District,

Hanoi, Vietnam.

Tel: +84-24-3795-7135

Fax: +84-24-3795-7136

Website: www.daelim.co.kr

Date:

January 05, 2022

Ref. No.:

DLM-MLT-00001-22-E

To:

Mr. David CHEVALLIER - Acting Project Director

Systra Hanoi Metro Project Office

Address: 12th floor, HOA BINH International Towers, 106 Hoang Quoc Viet,

Cau Giav Dist., Hanoi City, Viet Nam

Tel: 84-24-37 91 85 40

Fax: 84-24-37 91 85 44

Cc:

Mr. Nguyen Cao Minh - General Director

Hanoi Metropolitan Railway Management Board (MRB)

Address: Building CC-2, Dong Tau Urban Area, Hoang Mai Dist., Hanoi

Tel: 84-24-39 43 51 27

Fax: 84-24-39 43 51 26

Subject:

CP01 - Conduct technical investigation and preparation of the Pier P103 and

relevant structures after truck accident

(Replying to PIC's letter No. PIC-MLT-06028-21-E&V dated 31/12/2022)

Dear Sirs,

Referring to abovementioned subject, CP01 has contact and invited 3rd Party (UCT Co., LTD) for site checking at Pier P103's accident area.

UCT is company which has experience to do several testings/verifications in CP01's work such as: Load test for U-girder, Structure verification of pedestrian bridge, Structure verification of cantilver formwork platform. CP01 believes that UCT has fully ability to carry out this investigation and assessment work.

Therefore, CP01 would like to submit herewith the preliminary investigation plan relevant structures after truck accident at Pier P103 for your review.

After getting your confirmation, CP01 and our 03rd party shall start the work as soon as practicable.

Your promptly response would be highly appreciated.

TEE CHUNG HEE PROJECT MANAGER

THÂU CHÍNH
GÓI THÂU SỐ 1
TUYẾN - ĐOẠN THẬU CAO
ĐỊ ẨN THYỆN ĐƠI THÌ YIỆM

- 1. Investigation Plan
- 2. UCT company profile



DAELIM INDUSTRIAL CO., LTD.

Tầng 5B, Tòa nhà HL, NGỗ 82, Duy Tân, P. Dịch Vọng, Q. Cầu Giấy, Hà Nội, Vietnam. Điện thoại: +84-24-3795-7135 Fax: +84-24-3795-7136 Website: www.daelim.co.k

Ngày:

05/01/2022

CV sô.:

DLM-MLT-00001-22-V

Kính Gửi:

Ông David CHEVALLIER - Quyền Giám đốc Dự án

Văn phòng Dư án Metro Hà Nội của Systra

Địa chỉ: Tầng 12, Tòa nhà Hòa Bình International, Số 106 Hoàng Quốc Việt,

Quận Cầu Giấy, Hà Nội, Việt Nam

Diên thoai: 84-24-37 91 85 40

Fax: 84-24-37 91 85 44

Đồng k/g:

Ông Nguyễn Cao Minh - Trưởng ban

Ban Quản Lý Đường Sắt ĐÔ thị Hà Nội (MRB)

Đại chỉ: Tòa nhà CC-2, Khu Đô Thị Đồng Tàu, Hoàng Mai, Hà Nội

Điện thoại: 84-24-39 43 51 27

Fax: 84-24-39 43 51 26

Về việc:

CP01 – Thực hiện điều tra kỹ thuật và sửa chữa của Trụ 103 và các kết cấu liên

quan sau vụ tai nạn với xe tải

(Trả lời thư PIC số PIC-MLT-06028-21-E&V ngày 31/12/2022)

Thưa Ông,

Đề cập đến chủ thể nói trên, CP01 đã liên hệ và mời Bên thứ 3 (UCT Co., LTD) để kiểm tra hiện trường tại khu vực tại nạn của Pier P103.

UCT là công ty có kinh nghiệm thực hiện một số thử nghiệm / kiểm định trong công việc của CP01 như: Kiểm tra tải trọng cho dầm U, Kiểm tra kết cấu của cầu đi bộ, Kiểm tra kế cấu cho xe đúc hẫng. CP01 tin rằng UCT hoàn toàn có đủ khả năng để thực hiện công việc điều tra, đánh giá này.

Do đó, CP01 xin gửi kèm theo đây kế hoạch điều tra sơ bộ các kết cấu liên quan sau vụ tai nạn xe tải tại tru P103 để Ông xem xét.

Sau khi nhận được xác nhận của Ông, CP01 và bên thứ 03 của chúng tôi sẽ bắt đầu công việc ngay lập tức

Chúng tôi đánh giá cao phản hồi sớm từ phía Ông.



- 1. Kế hoạch khảo sát
- 2. Hồ sơ năng lực UCT