

## **Planetary Gearheads**

## 20 Nm

For combination with DC-Micromotors Brushless DC-Motors Motion Control Systems

## **Series 38A**

	38A
Housing material	steel
Geartrain material	steel
Recommended max. input speed for:	
– continuous operation	4 500 min <sup>-1</sup>
Backlash, at no-load	≤ 0,5 °
Bearings on output shaft	ball bearings
Shaft load, max.:	
- radial (14,5 mm from mounting face)	≤ 200 N
– axial	≤ 200 N
Shaft press fit force, max.	≤ 490 N
Shaft play	
- radial (14,5 mm from mounting face)	≤ 0,02 mm
– axial	≤ 0,3 mm
Operating temperature range	- 25 + 90 °C

Technical data								
Number of gear stages		1	2	2	3	3	4	4
Continuous torque	Nm	6	20	18	20	18	20	18
Intermittent torque	Nm	9,6	32	29	32	29	32	29
Mass without motor, ca.	g	190	260	260	330	330	410	410
Efficiency, max.	%	96	94	94	90	90	80	80
Direction of rotation, drive to	output	=	=	=	=	=	=	=
Reduction ratio (exact)		4:1 5:1	12:1 16:1 20:1	25:1	36:1 45:1 60:1 80:1 100:1 120:1 160:1	200:1	240:1 360:1 480:1 800:1	1 600:1
L2 [mm] = length without mo		42,2	55,0	55,0	67,6	67,6	80,2	80,2
<b>L1</b> [mm] = length with motor		78,8	91,6	91,6	104,2	104,2	116,8	116,8
	3257GCR	93,8	106,6	106,6	119,2	119,2	131,8	131,8
	3272GCR	108,8	121,6	121,6	134,2	134,2	146,8	146,8
	3863HCR	113,6	126,4	126,4	139,0	139,0	151,6	151,6
	3890HCR	139,6	152,4	152,4	165,0	165,0	177,6	177,6
	3242GBX4	81,0	93,8	93,8	106,4	106,4	119,0	119,0
	3268GBX4	107,0	119,8	119,8	132,4	132,4	145,0	145,0
	3274GBP4	110,8	123,6	123,6	136,2	136,2	148,8	148,8
	3564KB	106,2	119,0	119,0	131,6	131,6	144,2	144,2
	4490HB/BS	139,6	152,4	152,4	165,0	165,0	177,6	177,6
	MCS 3242GBX4	117,2	130,0	130,0	142,6	142,6	155,2	155,2
	MCS 3268GBX4	143,2	156,0	156,0	168,6	168,6	181,2	181,2
	MCS 3274GBP4	152,2	165,0	165,0	177,6	177,6	190,2	190,2

<sup>&</sup>lt;sup>1)</sup> L2 - 5,4 mm, in combination with 3242G...CR, 3257G...CR, 3272G...CR, 3242G...BX4, 3268G...BX4 and 3274G...BP4. L2 + 7,4 mm, in combination with 3863A...CR, 3890A...CR, 4490H...B and 4490H...BS.

