

Button wiring harness





* solder black wire to battery red wire white wire to battery black wire

* solder short LED lead (cathode) to gnd long LED lead (anode) to t

(Take care to not solder LEDs in backwards)
(Use heat-shrink tubes on solder joints - put tubes on wire before soldering.)