## Prototype 1





Too complicated

## Prototype 2





Poor fit

## Prototype 3











Great fit & easy to assemble... Best so far