
Lab 3 - Introduction to Assembly Language

3.1 x86 Assembly Instruction Format:

The general x86 machine instruction format contains an instruction prefix byte, opcode, Mod R/M byte, scale index byte (SIB), address displacement, and immediate data. Every instruction has an opcode, but the remaining fields are optional. Few instructions contain all fields. On average, most instructions are 2 or 3 bytes. Here is a quick summary of the fields:

- The **instruction prefix** overrides default operand sizes.
- The **opcode** (operation code) identifies a specific variant of an instruction. The ADD instruction, for example, has nine different opcodes, depending on the parameter types used.
- The **Mod R/M** field identifies the addressing mode and operands. The notation "R/M" stands for *register* and *mode*.
- The scale index byte (SIB) is used to calculate offsets of array indexes.
- The **address displacement** field holds an operand's offset, or it can be added to base and index registers in addressing modes such as base-displacement or base-index-displacement.
- The **immediate data** field holds constant operands.



3.2 x86 Instructions Encoding

To **encode** an instruction means to convert an assembly language instruction and its operands into machine code. To **decode** an instruction means to convert a machine code instruction into assembly language.

The basic idea with machine code is to use binary bytes to represent a computation. Different machines use different bytes, but Intel x86 machines use "0xc3" to represent the "ret" instruction, and "0xb8" to represent the "load a 32-bit constant into EAX" instruction.

0: b8 05 00 00 00 mov eax,5h

5: c3 ret

0: and 5: are the address offsets of the instructions in bytes (hexadecimal). "mov" is an instruction, encoded with the operation code or "opcode" 0xb8. Since mov takes an argument, the next 4 bytes are the constant to move into EAX.

The opcode 0xb9 moves a constant into ECX. Oxba moves a constant into EDX.

0:	b8	05	00	00	00	mov	eax,5h
5:	b9	05	00	00	00	mov	ecx,5h
a:	ba	05	00	00	00	mov	edx,5h

x86 specifies register sizes using prefix bytes. For example, the same "0xb8" instruction that loads a 32-bit constant into EAX can be used with a "0x66" prefix to load a 16-bit constant, or a "0x48" REX prefix to load a 64-bit constant.

Here we're loading the same constant 0x12 into all the different sizes of EAX:

0:	48	b8	12	00	00	00	00	00	00	00	mov	rax,12h
a:		b8	12	00	00	00					mov	eax,12h
f:	66	b8	12	00							mov	ax,12h
13:		b0	12								mov	al,12h
15:		с3									ret	

Encoding your assembly or compiled code shows you both the instructions and the machine code that implements them. Not only are there hundreds of different x86 instructions, but there can also be dozens of different machine code encodings for a given instruction. Here are a few examples:

ASM	Machine Code	Description		
add	0x03	Add one 32-bit register to another.		
mov	0x8B	Move one 32-bit register to another.		
mov	0xB8	Move a 32-bit constant into register EAX.		
ret	0xc3	Returns from current function.		
xor	0x33	XOR one 32-bit register with another.		
xor	0x34 BYTE	XOR register AL with this 8-bit constant.		

3.3 Encoding Memory and Register Operands

That last byte of most x86 instructions is called "ModR/M" in the Intel documentation, and it specifies what the source and destination are. It's just a bit field giving a selector called "mod" (which indicates whether r/m is treated as a plain register or a memory address), one register called "reg/opcode" (which is usually the destination register and determines the column in the ModR/M table), and a final register called "r/m" (usually the source register, which selects the row of the ModR/M table). These are stored in a single byte with this format:

mod	reg/opcode	r/m
2 bits, selects memory or register access mode: 0: memory at register r/m	3 bits, usually a destination register number.	3 bits, usually a source register number.
	For some instructions, this is actually extra opcode bits.	Treated as a pointer for mod!=3, treated as an ordinary register for mod==3.
2: memory at register r/m + 32-bit offset 3: register r/m itself (not memory)		If r/m==4, indicates the real memory source is a <u>SIB byte</u> .

3.4 ModR/M Table

This is the "ModR/M" table for the meaning of ModR/M byte values:

This is the Word W. Table for the meaning of Word W byte Values.											
r32(/r)	EAX	ECX	EDX	EBX	ESP	EBP	ESI	EDI			
reg=			000	001	010	011	100	101	110	111	
effective address	mod	R/M		value of mod R/M byte (hex)							
[RAX]	00	000	00	08	10	18	20	28	30	38	
[RCX]		001	01	09	11	19	21	29	31	39	
[RDX]		010	02	OA	12	1A	22	2A	32	3A	
[RBX]		011	03	0B	13	1B	23	2B	33	3B	
[SIB]		100	04	OC.	14	1C	24	2C	34	3C	
[RIP + DWORD]		101	05	0D	15	1D	25	2D	35	3D	
[RSI]		110	06	0E	16	1E	26	2E	36	3E	
[RDI]		111	07	0F	17	1F	27	2F	37	3F	
[RAX + BYTE]	01	000	40	48	50	58	60	68	70	78	
[RCX + BYTE]		001	41	49	51	59	61	69	71	79	
[RDX + BYTE]		010	42	4A	52	5A	62	6A	72	7A	
[RBX + BYTE]		011	43	4B	53	5B	63	6B	73	7B	
[SIB + BYTE]		100	44	4C	54	5C	64	6C	74	7C	
[RBP + BYTÉ]		101	45	4D	55	5D	65	6D	75	7D	
[RSI + BYTE]		110	46	4E	56	5E	66	6E	76	7E	
[RDI + BYTE]		111	47	4F	57	5F	67	6F	77	7F	
[RAX + DWORD]	10	000	80	88	90	98	A0	A8	B0	B8	
[RCX + DWORD]		001	81	89	91	99	A1	A9	B1	B9	
[RDX + DWORD]		010	82	8A	92	9A	A2	AA	B2	BA	
[RBX + DWORD]		011	83	8B	93	9B	A3	AB	B3	BB	
[SIB + DWORD]		100	84	8C	94	9C	A4	AC	B4	BC	
[RBP + DWORD]		101	85	8D	95	9D	A5	AD	B5	BD	
[RSI + DWORD]		110	86	8E	96	9E	A6	AE	B6	BE	
[RDI + DWORD]		111	87	8F	97	9F	A7	AF	B7	BF	
EAX	11	000	C0	C8	D0	D8	E0	E8	F0	F8	
ECX		001	C1	C9	D1	D9	E1	E9	F1	F9	
EDX		010	C2	CA	D2	DA	E2	EA	F2	FA	
EBX		011	C3	CB	D3	DB	E3	EB	F3	FB	
ESP		100	C4	CC	D4	DC	E4	EC	F4	FC	
EBP		101	C5	CD	D5	DD	E5	ED	F5	FD	
ESI		110	C6	CE	D6	DE	E6	EE	F6	FE	
EDI		111	C7	CF	D7	DF	E7	EF	F7	FF	


Note: For complete reference visit this <u>Link</u>. And read topic name "x86 Instruction Encoding" from book's page number 539 to 547.

3.5 x86 Instructions Encoding in Visual Studio


3.5.1 Method 1

MASM stores the encoded assembly instructions in a file called *Listing File*. To generate the listing file containing byte codes of our assembly program, open the Visual Studio and open the Assembly Project we created earlier. Go to "Solution Explorer" and right click on the Project and click on "Properties". A dialog box will open. On the Left side of the box, go to the "Microsoft Macro Assembler" tab. Expand the "Microsoft Macro Assembler" tab and click on "Listing File" option.

- Set "Generate Preprocessed Source Listing" to Yes
- Set "List All Available Information" to Yes
- Set "Enable Assembly Generated Code Listing" to Yes
- Set "Assembled Code Listing File" to "\$(ProjectName).lst"




After performing the above step now MASM will generate the Listing File when you build the project. A file named "Project.lst" will be stored to the project directory named. You can open this file in any text editor to view the machine code of your assembly program.




3.5.2 Method 2


There is another simple way to view the *Listing File* of our code directly during the debugging process. Start your program in debugging mode using breakpoints then go to "Debug" menu. Click on "Windows" option and then select "Disassembly" option available at the end of the menu.



Visual Studio will start showing the *Disassembly* window containing the source code as well as the address of the Assembly instructions in code segment.



To view the actual encoded instruction in Machine Code (Bytes) click on the "Show code bytes" checkbox at the upper left corner of the Disassembly window.



3.6 Assembly Instructions Formats

Zero-Operand Format:

```
stc
                   ; set Carry flag
```

Single-Operand Format:

```
inc eax
                  ; add 1 to EAX register
                ; add 1 to memory
inc myByte
```

mul a ; multply variavle a with EAX and keep it in.

Two-Operand Format:

```
mov EAX,a
                        ; copy value of a into accumulator register "EAX".
                       ; add value of b into value of "EAX" and keep it in.
add EAX,b
add ebx,ecx ; register, register
sub myByte,25 ; memory, constant
add eax,36 * 25 ; register, constant-expression
```

Three-Operand Format:

```
imul eax, ebx, 5
                    ; multiply values of EBX and 5, and store the result in EAX.
```

Some mnemonics are as follows:

Mnemonics	Syntax	Working			
mov	mov op1,op2	Copy data from operand 2 to operand 1.			
add	add op1,op2	Add operand 2 into operand 1 and keep it stored in operand 1.			
sub	sub op1,op2	Subtract operand 1 from operand 2.			
mul	mul op1	For unsigned multiplication. It multiplies operand to EAX and store result in EAX and EDX			
jmp	jmp	Jump to a new location.			
call	call proc1	Call a procedure.			
imul	imul eax,ebx,5	For signed multiplication. EBX is multiplied by 5, and the product is stored in the EAX register.			

Note: When two 32-bit integers are multiplied, output is 64-bit integer. In 32-bit architecture, 64-bit registers don't exist. Hence to accommodate 64-bit integer, upper 32-bits are moved to EDX and lower 32-bits are moved to EAX register. An instruction contains four basic parts:

- Label (optional)
- Instruction mnemonic (required)
- Operand(s) (usually required)
- Comment (optional)

This is how the different parts are arranged:

```
[label:] mnemonic [operands] [;comment]
```

3.6.1 Label

A label is an identifier that acts as a place marker for instructions and data. A label placed just before an instruction point toward the instruction's address. Similarly, a label placed just before a variable point toward the variable's address. There are two types of labels:

- Data Label
- Code Label

A *data label* identifies the location of a variable, providing a convenient way to reference the variable in code. The following, for example, defines a variable named count:

```
count DWORD 100
```

The assembler assigns a numeric address to each label. It is possible to define multiple data items following a label. In the following example, array defines the location of the first number (1024). The other numbers following in memory immediately afterward:

```
Array DWORD 1024, 2048
DWORD 4096, 8192
```

A *code label* is used as targets of jumping and looping instructions. Code labels must end with a colon (:) character. For example, the following JMP (jump) instruction transfers control to the location marked by the label named target, creating a loop:

```
target:

mov ax,bx
...
jmp target
```

A code label can share the same line with an instruction, or it can be on a line by itself:

```
L1: mov ax,bx
L2:
```

Label names follow the same rules we described for identifiers in Section 3.2.9 below.

3.7 First Assembly Language Program

Let's look at a simple assembly language program that adds two numbers and saves the result in a register. We will call it the *AddTwo* program:

```
1: main PROC
2: mov eax,5 ;move 5 to the eax register
3: add eax,6 ;add 6 to the eax register
4:
5: INVOKE ExitProcess,0 ;end the program
6: main ENDP
```

On the left side there are line numbers. You never actually type line numbers when you create assembly programs. Here is the explanation of each line:

- Line 1 starts the main procedure, the entry point for the program.
- Line 2 places the integer 5 in the EAX register.
- Line 3 adds 6 to the value in EAX, giving it a new value of 11.

- **Line 5** calls a Windows service (also known as a function) named *ExitProcess* that halts the program and returns control to the operating system.
- Line 6 is the ending marker of the main procedure.

This program does not display anything on the screen, but we could run it with Visual Studio's Debugger that would let us step through the program one line at a time and we can look at the register values.

3.7.1 Comments

Comments can be specified in two ways:

- Single-line comments, beginning with a semicolon character (;). All characters following the semicolon on the same line are ignored by the assembler.
- Block comments, beginning with the COMMENT directive and a user-specified symbol. All subsequent lines of text are ignored by the assembler until the same user-specified symbol appears. Here is an example:

```
COMMENT!

This line is a comment.

This line is also a comment.!
```

We can also use any other symbol, as long as it does not appear within the comment lines:

```
COMMENT &
This line is a comment.
This line is also a comment.
&
```

3.7.2 Adding a Variable

Now modify the *AddTwo* program to save the result of our addition in a variable named sum. To do this, we will add a couple of markers, or declarations, that identify the code and data areas of the program:

```
1: .data
                         ;this is the data area
2: sum DWORD 0
                         ;create a variable named sum
3:
4: .code
                         ;this is the code area
5: main PROC
                        ;move 5 to the EAX register
6: mov eax,5
7:
     add eax,6
                         ;add 6 to the EAX register
                        ;moving the value of EAX to sum variable
8:
     mov sum,eax
9:
10:
      INVOKE ExitProcess, 0 ; end the program
11: main ENDP
```

The **sum** variable is declared on **Line 2**, where we give it a size of 32-bits, using the **DWORD** keyword. There are a number of these size keywords, which work like data types. But they are not as specific as types you might be familiar with, such as int, double, float, and so on. They only specify a size, but there's no checking into what actually gets put inside the variable. Remember, you are in total control.

The ".code" and ".data" directives, are called *segments*. So, you have the *code segment* and the *data segment*. There is also a third segment named *stack segment* declared using ".stack".

3.7.3 Integer Literals (Constants)

An *integer literal* (also known as an *integer constant*) is made up of an optional leading sign, one or more digits, and an optional radix character that indicates the number's base:

```
[{+ | - }] digits [ radix ]
```

We will use **Microsoft Syntax Notation** throughout the Manual whenever the syntax is written. Elements within square brackets [..] are optional and elements within braces {..} require a choice of one of the enclosed elements, separate by the | character. Elements in *italics* identify items that have known definitions or descriptions.

So, for example, 26 is a valid integer literal. It doesn't have a radix, so we assume it's in decimal format. If we wanted it to be 26 hexadecimals, we would have to write it as 26h. Similarly, the number 1101 would be considered a decimal value until we added a "b" at the end to make it 1101b (binary).

Here are the possible radix values:

- d decimal
- **h** hexadecimal
- **b** binary
- **q** or **o** octal
- r encoded real
- t decimal (alternate)
- **y** binary (alternate)

And here are some integer literals declared with various radixes. Each line contains a comment:

26 ; decimal
26d ; decimal
11010011b ; binary
42q ; octal
420 ; octal
1Ah ; hexadecimal
0A3h ; hexadecimal

Note: A hexadecimal literal beginning with a letter must have a leading zero to prevent the assembler from interpreting it as an identifier.

3.7.4 Constant Integer Expressions

A constant integer expression is a mathematical expression involving integer literals and arithmetic operators. Each expression must evaluate to an integer, which can be stored in 32-bits (0 through FFFFFFFFh). The arithmetic operators are listed in Table 3-1 according to their precedence order, from highest (1) to lowest (4). The important thing to realize about constant integer expressions is that they can only be evaluated at assembly time. From now on, we will just call them *integer expressions*.

Operator	Name	Precedence Level
()	Parentheses	1
+,-	Unary plus, minus	2
* , /	Multiply, divide	3
MOD	Modulus	3
+, -	Add, subtract	4

Operator precedence refers to the implied order of operations when an expression contains two or more operators. The order of operations is shown for the following expressions:

3.7.5 Real Number Literals

Real number literals (also known as floating-point literals) are represented as either decimal reals or encoded (hexadecimal) reals. A decimal real contains an optional sign followed by an integer, a decimal point, an optional integer that expresses a fraction, and an optional exponent:

```
[sign]integer.[integer][exponent]
```

These are the formats for the sign and exponent:

```
sign {+,-}
exponent E[{+,-}]integer
```

Following are examples of valid decimal reals:

```
2.
+3.0
-44.2E+05
26.E5
```

3.7.6 Character Literals

A *character literal* is a single character enclosed in single or double quotes. The assembler stores the value in memory as the character's binary ASCII code. Examples are 'A', "d", etc.

The character literals are stored internally as integers, using the ASCII encoding sequence. So, when you write the character constant "A," it's stored in memory as the number 65 (41h in Hexadecimal).

3.7.7 String Literals

A *string literal* is a sequence of characters (including spaces) enclosed in single or double quotes: 'ABC', 'X', "Good night, Gracie", '4096', etc.

Embedded quotes are permitted when used in the manner shown by the following examples:

"This isn't a test" or 'Say "Good night," Gracie'.

Just as character constants are stored as integers, we can say that string literals are stored in memory as sequences of integer byte values. So, for example, the string literal "ABCD" contains the four bytes 41h, 42h, 43h, and 44h.

3.7.8 Reserved Words

Reserved words have special meaning and can only be used in their correct context. Reserved words, by default, are not case-sensitive. For example, MOV is the same as mov and Mov. Some of the reserved words are as follows:

- Instruction mnemonics, such as MOV, ADD, and MUL
- Register names

- Directives, which tell the assembler how to assemble programs
- Attributes, which provide size and usage information for variables and operands. Examples are BYTE and WORD
- Operators, used in constant expressions
- Predefined symbols, such as @data, which return constant integer values at assembly time

3.7.9 Identifiers

An *identifier* is a programmer-chosen name. It might identify a variable, a constant, a procedure, or a code label. There are a few rules on how they can be formed:

- They may contain between 1 and 247 characters.
- They are not case sensitive.
- The first character must be a letter (A..Z, a..z), underscore (_), @, ?, or \$.
- An identifier cannot be the same as an assembler reserved word.

In assembly language try to name the identifier short. Examples of well-formed names are:

```
lineCount firstValue index line_count
myFile xCoord main x_Coord
```

The following names are legal, but not as desirable:

```
_lineCount $first @myFile
```

Generally, you should avoid the @ symbol and underscore as leading characters, since they are used both by the assembler and by high-level language compilers.

3.7.10 Directives

A *directive* is a command embedded in the source code that is recognized and acted upon by the assembler. Directives do not execute at runtime, but they let you define variables, macros, and procedures. They can assign names to memory segments and perform many other housekeeping tasks related to the assembler. Directives are not case sensitive. For example, .data, .DATA, and .Data are equivalent.

The following example helps to show the difference between directives and instructions. The **DWORD** directive tells the assembler to reserve space in the program for a doubleword variable. The **MOV** instruction, on the other hand, executes at runtime, copying the contents of myVar to the EAX register:

```
myVar DWORD 26
mov eax,myVar
```

3.7.11 Defining Segments

Segments are sections of a program that have different purposes. For example, one segment can be used to define variables, and is identified by the **.DATA** directive:

```
.data
```

The .CODE directive identifies the area of a program containing executable instructions:

```
.code
```

The .STACK directive identifies the area of a program holding the runtime stack, setting its size:


```
.stack 100h
```

3.8 Cannot open file 'Debug*.obj' Error Solution:


Many students face a specific error while building the assembly code in MASM. The error can be something like this:

```
cax, ebx, 4
      12
                   mov ebx,3
      13
                   add ebx,7
      14
                   sub eax, ebx
      15
                   imul eax,eax,21
      16
                  call writeint
      17
      18
Output
Show output from: Build
 Build started...
 1>---- Build started: Project: Project, Configuration: Debug Win32 ----
 1>temp yem(3): warning A4011: multiple .MODEL directives found : .MODEL ignored 1>LINK : fatal error LNK1104: cannot open file 'Debug\temp.obj'
 1>Done building project "Project.vcxproj" -- FAILED.
 ======= Build: 0 succeeded, 1 failed, 0 up-to-date, 0 skipped ==
```

Or it could be:



Or it could be like this:




3.8.1 Steps to solve this error in Visual Studio

In <u>Section 3.5.1</u>, we practiced generating the listing file by configuring the MASM. The listing file setting can also interfere with the build process, that is why we could get error messages something like "cannot open file "Debug\AddSum.obj". So, we have to disable the listing file.

To disable generating the listing file, open the Visual Studio and open the Assembly Project we created earlier. Go to "Solution Explorer" and right click on the Project and click on "Properties". A dialog box will open. On the Left side of the box, go to the "Microsoft Macro Assembler" tab. Expand the "Microsoft Macro Assembler" tab and click on "Listing File" option.

- Erase value in the "Generate Preprocessed Source Listing" cell.
- Erase value in the "List All Available Information" cell.
- Erase value in the "Enable Assembly Generated Code Listing" cell.
- Erase value in the "Assembled Code Listing File" cell.



Click Apply and OK.

Important Links:

- This online tool converts the x86 Assembly Instruction to Machine Code: Link
- This is the documentation of Microsoft Macro Assembler (MASM): <u>Link</u>