

Surveyor Assessment Report

Placeholder values only - synthetic Indian claim test document

Surveyor / Adjuster Assessment

Claim Number: MTR-2026-08-1107

Vehicle Registration: MH12AB4581

Inspection Date: 2026-08-10

Findings:

- Rear bumper damage and left tail lamp breakage observed
- No visible front-end impact consistent with divider collision
- Engine bay shows no collision-related damage
- Odometer reading and workshop intake suggest commercial taxi use

Estimated Admissible Loss:

INR 68,000

Remarks:

1. Damage pattern appears inconsistent with the insured's description.
2. Delay of over 30 days in claim intimation without satisfactory explanation.
3. Vehicle appears to have been used for hire/reward, contrary to private car declaration.
4. Driver licence copy provided to workshop expired on 2026-06-15.